


Use 3.3mm drill all through, tap for M4 half way and then drill the bottom 12mm out to 4mm



Date 2022/08/24

Author HobbyMachinist

Note

Based on design in http://www.homemetalshopclub.org/news/14/newsletter1401.pdf#page=4