



Two ideal transformer pairs



One common-flux winding



Complete external ports for either realization



Each inward current I_j uses $V_j - V_O$. The winding terminal P is separate from O .
 The held-ring control has $V_R - V_O = 0$ and nonzero I_R .