
Machine: coils, capacitor, switches and clamp
$S_R$
$S_1$
Metered preparation
Metered driver supplies
$i_1$
$L_1$
Clamp
$C$
$L_2$
$i_2$
Receiver
$v_R, i_R$
Coupling $M$, orientation, release time $t_s$