
Calculated work history
Reset
Energy (J)
0.4
0.2
0
0
1
2
3
Time (s)
Gross input D
Useful output W_R
Return + other heat
Mass order and gaps
Full-history COP
1
0.5
0
0.5
2
8
Receiver b (N s/m)
1 : 3 : 1/2, zero gap
1 : 3 : 1/2, finite gaps
1 : 1 : 1, finite gaps