

Calculated work history
Energy (J)
15
10
5
0
0
0.5
1
1.5
Time (s)
Gross input D
Useful output W_R
Return + other heat
Release phase and clamp
Full-history COP
0.4
0.2
0
0.25
0.5
0.75
1
1.25
Release phase η
R = 1, 80 V
R = 10, 80 V
R = 50, 80 V
R = 1, 20 V