
Machine: coils, capacitor, switches and clamp
S_R
S_1
Metered source prepare/reset
Metered driver supplies
i_1
L_1
Clamp
C
L_2
i_2
Useful work W_R
v_R, i_R
Coupling M, orientation, release time t_s