
Integrated lifting/reset
and release inputs
Model: masses, lever, contacts and release
D_1
D_2
Delay Δt, state ϕ
contact stiffness k
Lift and motion
$f_R, \dot{y}_R$
Useful work W_R
$m_R, y_R, \dot{y}_R$
Support port
Integrate all input work through reset