

Aviation Maintenance Log (43)

Technicians may not bypass the pre-flight checklist for any reason.

The revised procedure supersedes all previous revisions.

Print your instructions from the portal before starting work.

File reference HO-2042.