

Bicycle Repair Workshop Notes (70)

Follow the torque instructions printed on the frame decal.

Bypass the derailleur adjustment if the cable is already seated.

The customer will collect the bicycle on Friday afternoon.

File reference HO-2069.