

Preventive Maintenance


Inline System KIT 70/20

Ostomy bags – K11/ K12/ K13

**Unit No.: 413-050 - Z277 / 413-051 - Z278 /
413-052 - C337**

**Z277 / Z278 /
C 337**

Preventive Maintenance



2013-10

KIEFEL GmbH

Index

Index

Index.....	1
Machine overview.....	5
1. L & M -module 1 – UWS.....	6
1.1 Emitter – Joisten & Kettenbaum.....	7
1.2 Web control – Fife.....	8
1.3 Foil connecting unit.....	10
1.4 Epicyclic gear set – Stöber.....	11
1.5 Actuator – Siemens.....	12
1.6 Pneum. Winding shaft – Fife.....	13
1.7 Gear motor – SEW.....	15
1.8 Guides cyclewise.....	18
1.9 Static unloader.....	19
2. L & M -module 2 – FPW / PRI / FOR.....	21
1.10 Guides cyclewise / Guides not cyclewise.....	23
1.11 Web control – Fife.....	25
1.12 Adjustment drive – Valeo.....	26
1.13 Hot stamp - Wilux Print.....	27
1.14 Camera – Cognex.....	28
1.15 Cylinder PN – Festo.....	29
1.16 Sealing bar / Sealing strip.....	30
1.17 Servomotor/actuator – Siemens.....	31
1.18 Epicyclic gear set – Stöber.....	32
1.19 Toothed belt drive – Roth.....	33
Checking the tension of the filter material.....	34
1.20 Bevel gear – Stöber.....	36
1.21 Toothed belt drive - Breco.....	38
1.22 Corona – accessoires – Markro.....	40
1.23 Thermotransfer printer – Imaje.....	41
Cleaning the print head.....	42
1.24 Vacuum pump - Busch.....	43
3. L & M -module 3 – FHP / BSW / FWC.....	44
1.25 Guides cyclewise / not cyclewise.....	45

1.26	Adjustment drive – Valeo	46
1.27	Pneumatic cylinder – Festo	47
1.28	Compressed air reservoir – Festo.....	48
1.29	Sealing strip – Fiberflon.....	49
1.30	Ball screw spindle - Bosch Rexroth.....	50
1.31	Bevel gear – Stöber.....	51
1.32	Servo motor/actuator – Siemens	53
1.33	Camera - Cognex	54
4.	L & M -module 4 – AF / VOP.....	55
1.34	Guides not cyclewise	56
1.35	Adjustment drive – Valeo	57
1.36	Pneumatic cylinder – Festo	58
1.37	Sealing strip - Teastech Lfd.....	60
1.38	Multiturn actuator – Schunk	61
1.39	Camera – Cognex.....	62
1.40	Cutting device.....	63
1.41	Gear motor – SEW	64
1.42	Toothed belt drive – Breco.....	67
1.43	Permanent slip coupling – Roba.....	68
1.44	Servomotor/actuator – Siemens	69
1.45	Bevel gear – Stöber.....	70
1.46	Linear drive – Fife	72
1.47	Web control – Fife	73
1.48	Sealing strip – Fibertron	74
5.	L & M -module 5 – PWC	75
1.49	Guides Cyclewise / Cyclewise	76
1.50	Adjustment drive.....	77
1.51	Cylinder PN - Festo	78
1.52	Knee lever system -	79
1.53	Cooling air blower - Papst	80
1.54	Ball screw spindle - Bosch Rexroth.....	81
1.55	Diaphragm-circle force transducer - Brandt	82
1.56	Bevel gear – Stöber	83
1.57	Servo motor actuator - Siemens.....	85
1.58	Sealing strip - Teastech LTD.....	86




1.59	–L & M -module 6 – ASB/ASC	87
1.60	Guides cyclewise / not cyclewise	88
1.61	Pneumatic cylinder - Festo	90
1.62	Camera - Cognex	92
1.63	Stepping motor / Planetary gear set – AHS	93
1.64	Labeling machine - SES	95
1.65	SL & M -module 7 – PPS / ULS	96
1.66	Guides cyclewise	97
1.67	Adjustment drive – Valeo	98
1.68	Pneumatic cylinder – Festo	99
1.69	Powerhouse - TOX Pressotechnik.....	100
1.70	Compressed air reservoir – Festo.....	101
1.71	Vacuum pump – Busch.....	102
1.72	Linear Drive – MAX.....	103
	Remove MAX linear unit.....	105
	MAX - Evaluating the toothed belt.....	106
1.73	Servomotor actuator – Siemens.....	110
1.74	Transport Belts - Robotunits	111
6.	L & M -module 8 – FFT / FFB / FFG.....	112
1.75	Chain system	114
1.76	Chain.....	115
1.77	Bevel gear – Stöber	116
1.78	Servo motor actuator - Siemens.....	118
1.79	Cylinder PN – Festo	119
1.80	Gear box – MAX.....	121
1.81	Linear drive – MAX	122
	Remove MAX linear unit.....	124
	Evaluating the toothed belt.....	125
1.82	Conveyor belt – Robotunits.....	129
1.83	Robot – Fanuc.....	130
1.84	Lateral channel blower - Busch	131
1.85	Vacuum pump – Busch.....	132
1.86	Compressed air reservoir – Festo.....	133
1.87	Camera – Festo.....	134
1.88	Lighting - Methaphase.....	135



7. -L & M module 9 – INS.....	136
1.89 Chain system	137
1.90 Chain.....	138
1.91 Linear guide unit - Rose & Krieger.....	139
1.92 Gear motor - SEW.....	140
1.93 Bevel gear motor - Stöber	143
1.94 Servo motor actuator - Siemens.....	145
1.95 Worm gear drive motor - SEW	146
1.96 PTO / sprockets	149

Machine overview



Machine overview - Z318

1. **MODULE 1** – Unwinding station - UWS
2. **MODULE 2** - Welding-punching station incl. Corona printer control
FPW / PRI / FOR /COR Filter welding station
3. **MODULE 3** – Welding station, incl. backing seal and punching
FHP / BSW / FWC Flange welding station
4. **MODULE 4** – Welding-punching station Binder Flap + Viewing option
AF / VOP Flap welding / Viewing option
5. **MODULE 5** – Periphery welding station
PWC Periphery welding station
6. **MODULE 6** – Labelling station Curved Closure incl. post-heating
ASC / ASB Labelling station
7. **MODULE 7** – Periphery punching station incl. unloading station
PPS / ULS Punching and unloading station
8. **MODULE 8** – Feeding station Barrier and Gasket
FFT / FFG / FFB Feeding station flange
9. **MODULE 9** – Chain conveyor
INS Chain conveyor