# MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064

## 1 Overview

The MCUXpresso Software Development Kit (SDK) is a collection of software enablement for Microcontrollers that includes peripheral drivers, high-level stacks including USB and lwIP, integration with WolfSSL and mbed TLS cryptography libraries, other middleware packages, such as multicore support and FatFs, and integrated RTOS support for FreeRTOS<sup>TM</sup> OS. In addition to the base enablement, the MCUXpresso SDK is augmented with demo applications and driver example projects, and API documentation to help the customers quickly leverage the support of the MCUXpresso SDK.

For the latest version of this and other MCUXpresso SDK documents, see the MCUXpresso SDK homepage MCUXpresso-SDK: Software Development Kit.

#### **NOTE**

See the attached Change Logs section at the end of this document to reference the device-specific driver logs, middleware logs, and RTOS log.

#### **Contents**

I	Overview	l
2	MCUXpresso SDK	1
3	Development tools	2
4	Supported development systems	2
5	Release contents	2
6	MCUXpresso SDK release package	3
7	MISRA compliance	e
8	Known issues	8

# 2 MCUXpresso SDK



#### **Development tools**

As part of the MCUXpresso software and tools, MCUXpressoSDK is the evolution of Kinetis SDK v2.3.0, which includes support for both LPC and i.MX System-on-Chips (SoC). The same drivers, APIs, and middleware are still available with support for Kinetis, LPC, and i.MX silicon. The MCUXpresso SDK adds support for the MCUXpresso IDE, an Eclipse-based toolchain that works with all MCUXpresso SDKs. Easily import your SDK into the new toolchain to have access to all of the available components, examples, and demos for your target silicon. In addition to the MCUXpresso IDE, support for the MCUXpresso Config Tools allows for easy cloning of existing SDK examples and demos, allowing users to easily leverage the existing software examples provided by the SDK for their own projects.

#### NOTE

In order to maintain compatibility with legacy FSL code, the filenames and source code in MCUXpresso SDK containing the legacy Freescale prefix 'FSL' has been left as is. The 'FSL' prefix has been redefined as the NXP Foundation Software Library.

# 3 Development tools

The MCUXpresso SDK was compiled and tested with these development tools:

- IAR Embedded Workbench for ARM version 8.30.2
- MDK-ARM Microcontroller Development Kit (Keil)<sup>®</sup> 5.25
- Makefiles support with GCC revision v6-2017-q2 from ARM Embedded
- MCUXpresso IDE v10.2.1 (in some cases, requires v10.3.0.eb3)

# 4 Supported development systems

This release supports boards and devices listed in this table. Boards and devices in bold font were tested in this release.

Table 1. Supported MCU devices and development boards

Development boards	MCU devices
EVK-MIMXRT1064	MIMXRT1064CVL5A, MIMXRT1064DVL6A

## 5 Release contents

This table provides an overview of the MCUXpresso SDK release package contents and locations.

Table 2. Release contents

Deliverable	Location
Boards	<install_dir>/boards</install_dir>
Demo applications	<install_dir>/boards/<board_name>/demo_apps</board_name></install_dir>
CMSIS driver examples	<pre><install_dir>/boards/<board_name>/cmsis_driver_examples</board_name></install_dir></pre>
Driver examples	<install_dir>/boards/<board_name>/driver_examples</board_name></install_dir>
RTOS examples	<install_dir>/boards/<board_name>/rtos_examples</board_name></install_dir>
emWin examples	<install_dir>/boards/<board_name>/emwin_examples</board_name></install_dir>

Table continues on the next page...

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

### Table 2. Release contents (continued)

USB demo applications	<install_dir>/boards/<board_name>/usb_examples</board_name></install_dir>
Documentation	<install_dir>/docs</install_dir>
Middleware	<install_dir>/middleware</install_dir>
USB Documentation	<install_dir>/docs/usb</install_dir>
IwIP Documentation	<install_dir>/docs/lwip</install_dir>
SDMMC card driver	<install_dir>/middleware/sdmmc</install_dir>
lwIP stack	<install_dir>/middleware/lwip</install_dir>
USB stack	<install_dir>/middleware/usb</install_dir>
Driver, SoC header files, extension header files and feature header files, utilities	<install_dir>/devices/<device_name></device_name></install_dir>
Cortex Microcontroller Software Interface Standard (CMSIS) ARM Cortex®-M header files, DSP library source	<install_dir>/CMSIS</install_dir>
Peripheral Drivers	<install_dir>/devices/<device_name>/drivers</device_name></install_dir>
Utilities such as debug console	<install_dir>/devices/<device_name>/utilities</device_name></install_dir>
RTOS Kernel Code	<install_dir>/rtos</install_dir>
Tools	<install_dir>/tools</install_dir>

# 6 MCUXpresso SDK release package

The MCUXpresso SDK release package contents are aligned with the silicon subfamily it supports. This includes the boards, CMSIS, devices, documentation, middleware, and RTOS support.

# 6.1 Device support

The device folder contains all available software enablement for the specific System-on-Chip (SoC) subfamily. This folder includes clock-specific implementation, device register header file, device register feature header file, CMSIS derived device SVD, and the system configuration source files. Included with the standard SoC support are folders containing peripheral drivers, toolchain support, and a simple debug console.

The device-specific header files provide a direct access to the MCU peripheral registers. The device header file provides an overall SoC memory mapped register definition. In addition to the overall device memory mapped header file, the MCUXpresso SDK also includes the feature header file for each peripheral instantiated on the SoC.

The toolchain folder contains the startup code and linker files for each supported toolchain. The startup code is a CMSIS-compliant startup that efficiently transfers the code execution to the main() function.

# 6.1.1 Board support

The boards folder provides the board-specific demo applications, driver examples, RTOS, and middleware examples.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

MCUXpresso SDK release package

## 6.1.2 Demo applications and other examples

The demo applications demonstrate the usage of the peripheral drivers to achieve a system level solution. Each demo application contains a readme file that describes the operation of the demo and required setup steps.

The driver examples demonstrate the capabilities of the peripheral drivers. Each example implements a common use case to help demonstrate the driver functionality.

The RTOS and middleware folders each contain examples demonstrating the use of the included source.

### 6.2 Middleware

### 6.2.1 USB stack

See the MCUXpresso SDK USB Stack User's Guide (document MCUXSDKUSBSUG) for more information.

#### NOTE

To enable USB High Speed function, add jumper on J14 and remove jumper on J53. To enable USB Full Speed function, add jumper on J53.

## 6.2.1.1 Peripheral devices tested with the USB Host stack

This table provides a list of USB devices tested with the USB Host stack.

Table 3. Peripheral devices

Device type	Device
USB HUB	BELKIN F5U233
	BELKIN F5U304
	BELKIN F5U307
	BELKIN F4U040
	UNITEK Y-2151
	Z-TEK ZK032A
	HYUNDAI HY-HB608
USB flash drive	ADATA C008 32 GB
	ADATA S102 8 G
	ADATA S102 16 G
	Verbatim STORE N GO USB Device 8 G
	Kingston DataTraveler DT101 G2
	SanDisk Cruzer Blade 8 GB
	Unisplendour 1 G
	Imation 2 GB
	V-mux 2 GB

Table continues on the next page...

Table 3. Peripheral devices (continued)

	Sanmina-SCI 128 M
	Corporate Express 1 G
	TOSHIBA THUHYBS-008G 8 G
	Transcend JF700 8 G
	Netac U903 16 G
	SSK SFD205 8 GB
	Rex 4 GB
	SAMSUNG USB3.0 16GB
USB card reader/adapter	SSK TF adapter
	Kawau Multi Card Reader
	Kawau TF adapter
	Kawau SDHC card
USB Mouse	DELL MS111-P
	DELL M066U0A
	DELL MUAVDEL8
	TARGUS AMU76AP
	DELL MD56U0
	DELL MS111-T
	RAPOO M110
USB Keyboard	DELL SK8135
	DELL SK8115

## 6.2.2 TCP/IP stack

The lwIP TCP/IP stack is pre-integrated with MCUXpresso SDK and runs on top of the MCUXpresso SDK Ethernet driver with Ethernet-capable devices/boards. For details, see the *lwIP TCPIP Stack and MCUXpresso SDK Integration User's Guide* (document MCUXSDKLWIPUG).

## 6.2.3 Security libraries

The MCUXpresso SDK is integrated with mbedTLS and wolfSSL libraries. The integration demonstrates hardware acceleration of various cryptography algorithms and random number generation. The packages are available through separate add-on packages at mcuxpresso.nxp.com, in the Optional Middleware section.

## 6.2.4 RTOS

The MCUXpresso SDK is integrated with FreeRTOS OS.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

#### 6.2.5 **CMSIS**

The MCUX presso SDK is shipped with the standard CMSIS development pack, including the prebuilt libraries.

# **MISRA** compliance

All MCUXpresso SDK drivers and USB stack comply to MISRA 2012 rules with the following exceptions.

Table 4. MISRA exceptions

Exception Rules	Description
Directive 4.4	Sections of code should not be commented out.
Directive 4.5	Identifiers in the same name space with overlapping visibility should be typographically unambiguous.
Directive 4.6	Typedef that indicate size and signedness should be used in place of the basic numerical type.
Directive 4.8	If a pointer to a structure or union is never dereferenced within a transaction unit then the implementation of the object should hidden.
Directive 4.9	A function should be used in preference to a function like macro where they are interchangeable.
Directive 4.10	Precautions shall be taken in order to prevent the contents of a header file being included more than once.
Directive 4.11	The validity of values passed to library functions shall be checked.
Rule 2.3	A project should not contain unused type declarations.
Rule 2.4	A project should not contain unused tag declarations.
Rule 2.5	A project should not contain unused macro declarations.
Rule 2.7	There should be no unused parameters in functions.
Rule 3.1	The character sequences /* and // shall not be used within a comment.
Rule 5.1	External identifiers shall distinct.
Rule 5.3	A identifier declared in an inner scope shall not hide an identifier declared in an outer scope.
Rule 5.7	A tag name shall be a unique identifier.
Rule 5.9	Identifiers that define objects or functions with external linkage shall be unique.
Rule 8.13	A pointer should point to a const-qualified type whenever possible.
Rule 8.3	All declarations of an object or function shall use the same names and type qualifiers.
Rule 8.6	An identifier with external linage shall have exactly one external definition.
Rule 8.7	Octal constants shall not be used.

Table continues on the next page...

# Table 4. MISRA exceptions (continued)

Г	T
Rule 8.9	A object should be defined at block scope if its identified only appears in a single function.
Rule 10.1	Operands shall not be of an inappropriate essential type.
Rule 10.3	The value of an expression shall not be assigned to an object with a narrower essential type of a different essential type category.
Rule 10.4	Both operands of an operator in which the usual arithmetic conversions are performed shall have the same essential type category.
Rule 10.5	The value of an expression should not be cast to an inappropriate essential type.
Rule 10.6	The value of a composite expression shall not be assigned to an object with wider essential type.
Rule 10.7	If a composite expression is used as one operand of an operator in which the usual arithmetic conversions are performed then the other operand shall not have wider essential type.
Rule 10.8	The value of a composite expression shall not be cast to a different essential type category or a wider essential type.
Rule 11.1	Conversions shall not be performed between a pointer to a function and any other type.
Rule 11.3	A case shall not be performed between a pointer to object type and a pointer to a different object type.
Rule 11.4	A conversion should not be performed between a pointer to object and an integer type.
Rule 11.5	A conversion should not be performed from pointer to void into pointer to object.
Rule 11.6	A cast shall not be performed between pointer to void and an arithmetic type.
Rule 12.1	The precedence of operators within expressions should be made explicit.
Rule 12.2	The right hand operator of a shift operator shall lie in the range zero to one less than the width in bits of the essential type of the left hand operand.
Rule 13.3	A full expression containing an increment(++) or decrement() operator should have no other potential side effects other than that caused by the increment or decrement operator.
Rule 13.5	The right hand operand of a logical && or II operator shall not contain persistent side effects.
Rule 14.2	A for loop shall be well formed.
Rule 14.4	The controlling expressions of an statement and the controlling expression of an iteration-statement shall have essentially Boolean type.
Rule 15.5	A function should have a single point of exit at the end.
Rule 16.1	All switch statements shall be well-formed.
Rule 17.1	The feature of <stdarg.h> shall not be used.</stdarg.h>

Table continues on the next page...

#### **Known issues**

## Table 4. MISRA exceptions (continued)

Rule 18.4	The +,-,+=and -=operators should not be applied to an expression of pointer type.
Rule 19.2	The union keyword should not be used.
Rule 20.1	#include directives should only be preceded by preprocessor directives or comments.
Rule 20.10	The #and ## preprocessor operators should not be used.
Rule 21.1	#define and #undef shall not be used on a reserved identifier or reserved macro name.

# 8 Known issues

# 8.1 Maximum file path length in Windows® 7 Operating System

Windows 7 operating system imposes a 260 character maximum length for file paths. When installing the MCUXpresso SDK, place it in a directory close to the root to prevent file paths from exceeding the maximum character length specified by the Windows operating system. The recommended location is the C:\nxp folder.

## 8.2 USBFS controller issue

Because of the USBFS controller design issues, the USB host suspend/resume demos (usb\_suspend\_resume\_host\_hid\_mouse) of the full speed controller do not support the low-speed device directly.

# MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064

**Change Logs** 

# **Contents**

<b>Driver</b>	Change Log	1
	CLOCK	1
	IOMUXC	1
	LPI2C	1
	LPSPI_CMSIS	1
	LPUART	2
	ADC	2
	ADC_ETC	2
	AIPSTZ	2
	AOI	3
	BEE	3
	CACHE	3
	CMP	3
	CSI	4
	DCDC	4
	DMAMUX	4
	<b>EDMA</b>	4
	ELCDIF	5
	<b>ENET</b>	6
	<b>EWM</b>	6
	FLEXCAN	6

# **Contents**

Title	Page Number
FLEXIO	7
FLEXIO_UART	7
FLEXIO_I2C	8
FLEXIO_SPI	9
FLEXIO_I2S	10
FLEXIO_MCU_LCD	11
FLEXIO_CAMERA	11
FLEXRAM	12
FLEXSPI	12
GPC	13
GPT	13
GPIO	13
KPP	13
LPI2C	13
LPSPI	14
LPUART	15
PIT	16
PMU	16
<b>PWM</b>	16
PXP	16
QTMR	17
RTWDOG	17
SAI	17
<b>SEMC</b>	18
<b>SPDIF</b>	18

# **Contents**

	Page
Title	Number
SRC	19
TEMPMON	19
TSC	19
USDHC	19
WDOG	20
XBARA	20
XBARB	21
Middleware Change Log	22
emWin library	22
FatFs for MCUXpresso SDK	22
lwIP for MCUXpresso SDK.	22
mbedTLS for MCUXpresso SDK	23
SDMMC	26
SDIO	28
SDSPI	28
USB stack for MCUXpresso SDK	28
QCA WiFi	32
wolfSSL	32
RTOS Change Log	34
FreeRTOS for MCUXpresso SDK	34

# 1 Driver Change Log

### **CLOCK**

The current CLOCK driver version is 2.1.5.

- 2.1.5
  - New feature:
    - \* Add support for ENET2.
- 2.1.4
  - Optimization:
    - \* Add PerClk in clock\_name\_t and CLOCK\_GetFreq.
    - \* Add APIs to get the frequency of AHB clock and SEMC, IPG clock and PER clock.
- 2.1.3
  - Use double instead of uint64\_t to achieve better performance with double precision FPU.
- 2.1.2
  - some minor fixes.
- 2.0.0
  - initial version.

### **IOMUXC**

The current IOMUXC driver version is 2.0.0.

- 2.0.0
  - initial version.

#### LPI2C

Current LPI2C CMSIS driver version is 2.0

- 2.0
  - Initial version.

## LPSPI CMSIS

Current lpspi\_cmsis driver version is 2.1

- 2.1
  - Bug Fix:
    - \* Fix the wrong clock polarity assignment in driver. For ARM\_SPI\_CPOL0\_CPHA0 and other frame format parameters, CPOL = 0 means kSPI\_ClockPolarityActiveHigh not kS-PI\_ClockPolarityActiveLow in driver.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- New feature:
  - \* Allow user to set up the default Transmit value by using ARM\_SPI\_SET\_DEFAULT\_-TX\_VALUE. Please note that set default value is not supported in slave interrupt mode, because the pin will remain tristated if TX buffer is NULL.
  - \* Enable slave select mode in the new driver, but this has no effect when user set any of them because the driver can only support the hardware control function.
  - \* Enable 3-Wire mode, users can use ARM\_SPI\_MODE\_MASTER\_SIMPLEX/ARM\_SPI\_MODE\_SLAVE\_SIMPLEX to enable this feature. For ARM\_SPI\_MODE\_MASTER\_SIMPLEX mode, select SOUT pin as the input/output pin, and for ARM\_SPI\_MODE\_SLAVE\_SIMPLEX, the SIN pin is selected as the input/output pin.
- 2.0
  - - Initial version.

#### **LPUART**

Current LPUART CMSIS driver version is 2.0

- 2.0
  - Initial version.

#### **ADC**

The current ADC driver version is 2.0.1.

- 2.0.1
  - Add control macro to enable/disable the CLOCK code in current driver.
- 2.0.0
  - Initial version.

## **ADC ETC**

The current ADC ETC driver version is 2.0.1.

- 2.0.1
  - Add control macro to enable/disable the CLOCK code in current driver.
- 2.0.0
  - Initial version.

#### **AIPSTZ**

The current AIPSTZ driver version is 2.0.0.

• 2.0.0

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- Initial version.

#### **AOI**

The current AOI driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **BEE**

The current BEE driver version is 2.0.1.

- 2.0.1
  - Bug fix:
    - \* Fixed bug in key user key loading sequence. BEE must be enabled during loading of user key.
    - \* Fixed typos in comments.
  - Feature:
    - \* Setting of AES nonce was moved from BEE\_SetRegionKey() into separate BEE\_Set-RegionNonce() function.
    - \* Changed handling of region settings. Both regions are configured simultaneously by BE-E\_SetConfig() function. Configuration of FAC start and end address using IOMUXC\_G-PRs was moved to application.
    - \* Added configuration setting for endian swap, access permission and region security level.
    - \* Default value for region address offset was changed to 0.
- 2.0.0
  - Initial version.

#### **CACHE**

The current CACHE driver version is 2.0.1.

- 2.0.1
  - Fixed cache size issue in L2CACHE\_GetDefaultConfig API.
- 2.0.0
  - Initial version.

## **CMP**

The current CMP driver version is 2.0.0.

• 2.0.0

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- Initial version.

#### **CSI**

The current CSI driver version is 2.0.1.

- 2.0.1
  - Switch DMA output buffer at the first data after each VSYNC, originally it happens when DMA transfer done.
- 2.0.0
  - Initial version.

#### **DCDC**

The current DCDC driver version is 2.0.0.

- 2.0.0
  - Initial version.

### **DMAMUX**

The current DMAMUX driver version is 2.0.2.

- 2.0.2
  - New feature:
    - \* Added an always-on enable feature to a DMA channel for ULP1 DMAMUX support.
- 2.0.1
  - Bug fix:
    - \* Fixed build warning while setting the DMA request source in DMAMUX\_SetSource-Change issue by changing the type of the parameter source from uint8\_t to uint32\_t.
- 2.0.0
  - Initial version.

### **EDMA**

The current eDMA driver version is 2.1.4.

- 2.1.4
  - Bug fix:
    - \* Clear enabled request, status during EDMA\_Init for the case that EDMA is halted before reinitialization.
- 2.1.3
  - Bug fix:

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* Add clear DONE bit in IRQ handler to avoid overwrite TCD issue.
- \* Optimize above solution for the case that transfer request occur in callback.
- 2.1.2
  - Improvements:
    - \* Added interface to get next TCD address.
    - \* Added interface to get the unused TCD number.
- 2.1.1
  - Improvements:
    - \* Added documentation for eDMA data flow when scatter/gather is implemented for the EDMA\_HandleIRQ API.
    - \* Updated and corrected some related comments in the EDMA\_HandleIRQ API and edma\_handle\_t struct.
- 2.1.0
  - Improvements:
    - \* Changed the EDMA\_GetRemainingBytes API into EDMA\_GetRemainingMajorLoop-Count due to eDMA IP limitation (see API comments/note for further details).
- 2.0.5
  - Improvements:
    - \* Added pubweak DriverIRQHandler for K32H844P (16 channels shared).
- 2.0.4
  - Improvements:
    - \* Added support for SoCs with multiple eDMA instances.
    - \* Added pubweak DriverIRQHandler for KL28T DMA1 and MCIMX7U5\_M4.
- 2.0.3
  - Bug fix:
    - \* Fixed the wrong pubweak IRQHandler name issue, which causes re-definition build errors when client sets his/her own IRQHandler, by changing the 32-channel IRQHandler name to DriverIRQHandler.
- 2.0.2
  - Bug fix:
    - \* Fixed incorrect minorLoopBytes type definition in \_edma\_transfer\_config struct, and defined minorLoopBytes as uint32\_t instead of uint16\_t.
- 2.0.1
  - Bug fix:
    - \* Fixed the eDMA callback issue (which did not check valid status) in EDMA\_HandleIRQ API.
- 2.0.0
  - Initial version.

#### **ELCDIF**

The current ELCDIF driver version is 2.0.0.

• 2.0.0

- Initial version.

#### **ENET**

The current ENET driver version is 2.2.3.

- 2.2.3
  - Improved data buffer cache maintenance in the ENET driver.
- 2.2.2
  - Added the APIs for extended multi-ring support.
  - Added the AVB configure API for extended AVB feature support.
- 2.2.1
  - Changed the input data pointer attribute to const in ENET\_SendFrame().
- 2.1.1
  - Added the extended MDIO IEEE802.3 Clause 45 MDIO format SMI command APIs.
  - Added the extended interrupt coalescing feature.
  - Combined all storage operations in the ENET\_Init to ENET\_SetHandler API.
- 2.0.1
  - Bug fix:
    - \* Used direct transmit busy check when doing data transmit.
  - Miscellaneous changes:
    - \* Updated IRQ handler work flow.
    - \* Changed the TX/RX interrupt macro from kENET\_RxByteInterrupt to kENET\_RxBuffer-Interrupt, from kENET\_TxByteInterrupt to kENET\_TxBufferInterrupt.
    - \* Deleted unnecessary parameters in ENET handler.
- 2.0.0
  - Initial version.

#### **EWM**

The current EWM driver version is 2.0.1.

- 2.0.1
  - Fixed EWM\_Deinit hardfault issue.
- 2.0.0
  - Initial version.

#### **FLEXCAN**

The current FLEXCAN driver version is 2.2.3.

- 2.2.3
  - Bug fix:
    - \* Fixed CANFD data phase's bit rate not set as expected.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.2.2
  - Improvements:
    - \* Added time stamp feature and enabled in interrupt\_transfer example.
- 2.2.1
  - Improvements:
    - \* Separated CANFD initialization API.
    - \* In the interrupt handling, fixed issue that user cannot use normal CAN API when FD is present.
- 2.2.0
  - Improvements:
    - \* Added FSL\_FEATURE\_FLEXCAN\_HAS\_SUPPORT\_ENGINE\_CLK\_SEL\_REMOV-E feature to support SoCs without CAN Engine Clock selection in FlexCAN module.
    - \* Added FlexCAN Serial Clock Operation to support i.MX SoCs.
- 2.1.0
  - Bug fixes:
    - \* Fixed wrong function name spelling: FLEXCAN\_XXX() -> FLEXCAN\_XXX();
    - \* Moved Freeze Enable/Disable setting from FLEXCAN\_Enter/ExitFreezeMode() to FLE-XCAN\_Init();
    - \* Fixed wrong helper macro values.
  - Other changes:
    - \* Hided FLEXCAN\_Reset() to user.
    - \* Used NDEBUG macro to wrap FLEXCAN\_IsMbOccupied() function instead of DEBUG macro.
- 2.0.0
  - Initial version.

#### **FLEXIO**

The current FLEXIO driver version is 2.0.2.

- 2.0.2:
  - Improvements:
    - \* Split FlexIO component which combines all flexio/flexio\_uart/flexio\_i2c/flexio\_i2s drivers into several components. FlexIO component, flexio\_uart component, flexio\_i2c master component, and flexio i2s component.
- 2.0.1
  - Bug fix:
    - \* Fix the Dozen mode configuration error in FLEXIO\_Init API. For enableInDoze = true, the configuration should be 0; for enableInDoze = false, the configuration should be 1.

## FLEXIO\_UART

The current FLEXIO\_UART driver version is 2.1.4.

- 2.1.4
  - Unify component full name to FLEXIO UART(DMA/EDMA) Driver
- 2.1.3
  - Bug fixes: The following modifications support FlexIO using multiple instances.
    - \* Removed FLEXIO\_Reset API in module Init APIs.
    - \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
    - \* Updated module Enable APIs to only support enable operation.
- 2.1.2
  - Bug fixes:
    - \* Fixed the transfer count calculation issue in FLEXIO\_UART\_TransferGetReceiveCount, FLEXIO\_UART\_TransferGetSendCount, FLEXIO\_UART\_TransferGetReceiveCountDMA, FLEXIO\_UART\_TransferGetSendCountDMA, FLEXIO\_UART\_TransferGetReceiveCountEDMA and FLEXIO\_UART\_TransferGetSendCountEDMA
    - \* Fixed the Dozen mode configuration error in FLEXIO\_UART\_Init API. For enableIn-Doze = true, the configuration should be 0; for enableInDoze = false, the configuration should be 1.
    - \* Reported error when set baudrate too low and FLEXIO cannot reach that baudrate.
    - \* Disabled FLEXIO\_UART receive interrupt instead of disable all NVIC when read data from ring buffer. Because ring buffer is used, receive nonblocking disables all NVIC interrupts to protect the ring buffer. This has negative effects on other IPS which are using interrupt.
- 2.1.1
  - Bug fixes:
    - \* Changed the API name FLEXIO\_UART\_StopRingBuffer to FLEXIO\_UART\_Transfer-StopRingBuffer to align with the definition in C file.
- 2.1.0
  - New features:
    - \* Added Transfer prefix in transactional APIs.
    - \* Added txSize/rxSize in handle structure to record the transfer size.
  - Bug fixes:
    - \* Added error handle to handle the data count is zero or data buffer is NULL situation.

## FLEXIO\_I2C

The current FLEXIO\_I2C driver version is 2.1.6.

- 2.1.6
  - Bug fix:
    - \* Fixed the issue that I2C Master transfer APIs(blocking/non-blocking) does not support the situation that master transfer with subaddress and transfer data size zero, which means no data follows by the subaddress.
- 2.1.5
  - Unify component full name to FLEXIO I2C Driver

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.1.4
  - Bug fixes: The following modifications support FlexIO using multiple instances.
    - \* Removed FLEXIO Reset API in module Init APIs.
    - \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
    - \* Updated module Enable APIs to only support enable operation.
- 2.1.3
  - Changed the prototype of FLEXIO\_I2C\_MasterInit to return kStatus\_Success if initialization successfully and return kStatus\_InvalidArgument if "(srcClock\_Hz / masterConfig->baud-Rate\_Bps) / 2 1" exceeds 0xFFU.
- 2.1.2
  - Fixed the FLEXIO I2C issue where the master cannot receive data from I2C slave in high baudrate.
  - Fixed the FLEXIO I2C issue where the master cannot receive NAK when master sends nonexistent addr.
  - Fixed the FLEXIO I2C issue where the master cannot get transfer count successfully.
  - Fixed the FLEXIO I2C issue where the master cannot receive data successfully when sending data first.
  - Fixed the Dozen mode configuration error in FLEXIO\_I2C\_MasterInit API. For enableInDoze = true, the configuration should be 0; for enableInDoze = false, the configuration should be 1.
  - Fixed the FLEXIO\_I2C\_MasterTransferBlocking API calls FLEXIO\_I2C\_MasterTransfer-CreateHandle issue. This leads the s\_flexioHandle/s\_flexioIsr/s\_flexioType variable written. Then, if calling FLEXIO\_I2C\_MasterTransferBlocking API multiple times, the s\_flexio-Handle/s\_flexioIsr/s\_flexioType variable cannot be written anymore due to it being out of range. This leads to the following: NonBlocking transfer APIs cannot work due to register IRQ failed.
- 2.1.1
  - Bug fixes:
    - \* Implemented the FLEXIO\_I2C\_MasterTransferBlocking API which defined in header file but has no implementation in the C file.
- 2.1.0
  - New features:
    - \* Added Transfer prefix in transactional APIs.
    - \* Added transferSize in handle structure to record the transfer size.

## FLEXIO\_SPI

The current FLEXIO SPI driver version is 2.1.3.

- 2.1.3
  - Unify component full name to FLEXIO SPI(DMA/EDMA) Driver
- 2.1.2
  - Bug fixes: The following modification support FlexIO using multiple instances.
    - \* Removed FLEXIO\_Reset API in module Init APIs.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
- \* Updated module Enable APIs to only support enable operation.
- 2.1.1
  - Bug fixes:
    - \* Fixed bug where FLEXIO SPI transfer data is in 16 bit per frame mode with eDMA.
    - \* Fixed bug where FLEXIO SPI transfer data is in 16 bit per frame and direction is Lsbfirst mode with eDMA and interrupt.
    - \* Fixed the Dozen mode configuration error in FLEXIO\_SPI\_MasterInit/FLEXIO\_SPI\_SlaveInit API. For enableInDoze = true, the configuration should be 0; for enableInDoze = false, the configuration should be 1.
  - Optimization:
    - \* Added #ifndef/#endif to allow user to change the default tx value at compile time.
- 2.1.0
  - New features:
    - \* Added Transfer prefix in transactional APIs.
    - \* Added transferSize in handle structure to record the transfer size.
  - Bug fixes:
    - \* Fixed the error register address return for 16-bit data write in FLEXIO\_SPI\_GetTxData-RegisterAddress.
    - \* Provided independent IRQHandler/transfer APIs for Master and slave to fix the baudrate limit issue.

## FLEXIO\_I2S

The current FLEXIO I2S driver version is 2.1.6.

- 2.1.6
  - Bug fix:
    - \* Add reset flexio before flexio i2s init to make sure flexio status is normal.
- 2.1.5
  - Bug fix:
    - \* Fix i2s driver use hard code for bitwidth setting.
- 2.1.4
  - Unify component full name to FLEXIO I2S(DMA/EDMA) Driver
- 2.1.3
  - Bug fixes: The following modifications support FlexIO using multiple instances.
    - \* Removed FLEXIO\_Reset API in module Init APIs.
    - \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
    - \* Updated module Enable APIs to only support enable operation.
- 2.1.2
  - New features:
    - \* Added configure items for all pin polarity and data valid polarity.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

11

- \* Added default configure for pin polarity and data valid polarity.
- 2.1.1
  - Bug fixes:
    - \* Fixed FlexIO I2S RX data read error and eDMA address error.
    - \* Fix FlexIO I2S slave timer compare setting error.
- 2.1.0
  - New features:
    - \* Added Transfer prefix in transactional APIs.
    - \* Added transferSize in handle structure to record the transfer size.

## FLEXIO\_MCU\_LCD

The current FLEXIO\_MCU\_LCD driver version is 2.0.2.

- 2.0.2
  - Unify component full name to FLEXIO\_MCU\_LCD(EDMA) Driver
- 2.0.1
  - Bug fixes: The following modification to support FlexIO using multiple instances.
    - \* Removed FLEXIO Reset API in module Init APIs.
    - \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
    - \* Updated module Enable APIs to only support enable operation.
- 2.0.0
  - Initial version.

## FLEXIO\_CAMERA

The current FLEXIO\_CAMERA driver version is 2.1.2.

- 2.1.2
  - Unify component full name to FLEXIO CAMERA(EDMA) Driver
- 2.1.1
  - Bug fixes: The following modifications support FlexIO using multiple instances.
    - \* Removed FLEXIO\_Reset API in module Init APIs.
    - \* Updated module Deinit APIs to reset the shifter/timer config instead of disable module and disable clock.
    - \* Updated module Enable APIs to only support enable operation.
- 2.1.0
  - New features:
    - \* Added Transfer prefix in transactional APIs.

#### **FLEXRAM**

The current FLEXRAM driver version is 2.0.2.

- 2.0.2
  - Updated driver due to Reference Manual update.
- 2.0.1
  - Fixed MISRA issue.
- 2.0.0
  - Initial version.

#### **FLEXSPI**

The current FLEXSPI driver version is 2.0.3.

- 2.0.3
  - Bug fixes:
    - \* Fixed AHB receive buffer size configuration issue, the FLEXSPI\_AHBRXBUFCR0\_B-UFSZ field should configure 64 bits size, and currently the the AHB receive buffer size is in byte which means 8-bit, so the correct configuration should be config->ahbConfig.buffer[i].bufferSize / 8.
- 2.0.2
  - New features:
    - \* Supports DQS write mask enable/disable feature during set FLEXSPI configuration.
    - \* Provides new API FLEXSPI TransferUpdateSizeEDMA for user to update eDMA transfer size(SSIZE/DSIZE) per DMA transfer.
  - Bug fixes:
    - \* Fixed FLEXSPI Init invalid operation to enable AHB bus Read Access to IP RX FIFO
    - \* Fixed FLEXSPI\_Init incorrect operation to configure IP TX FIFO watermark issue.
- 2.0.1
  - Bug fixes:
    - \* Fixed the flag clear issue and AHB read Command index configuration issue in FLEXSP-I\_SetFlashConfig.
    - \* Updated FLEXSPI UpdateLUT function to update LUT table from any index instead of previous command index.
    - \* Added bus idle wait in FLEXSPI\_SetFlashConfig and FLEXSPI\_UpdateLUT to ensure bus is idle before any change to FlexSPI controller.
    - \* Updated interrupt API FLEXSPI\_TransferNonBlocking and interrupt handle flow FLEX-SPI TransferHandleIRQ.
    - \* Updated eDMA API FLEXSPI\_TransferEDMA.
- 2.0.0
  - Initial version.

#### **GPC**

The current GPC driver version is 2.1.0.

- 2.1.0
  - Updated driver for IMX6RT.
- 2.0.0
  - Initial version.

#### **GPT**

The current GPT driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **GPIO**

The current GPIO driver version is 2.0.1.

- 2.0.1:
  - API interface changes:
    - \* Refined naming of API while keeping all original APIs, marking them as deprecated. Original API will be removed in next release. The main change is update API with prefix of \_PinXXX() and \_PortXXX. main change is update API with prefix of \_PinXXX() and \_PortXXX().
- 2.0.0
  - Initial version.

#### **KPP**

The current KPP driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### LPI2C

The current LPI2C driver version is 2.1.5.

- 2.1.5
  - Bug fix:
    - \* Extended the Driver IRQ handler to support LPI2C4 and change to use ARRAY\_SIZE(k-Lpi2cBases) instead of FEATURE COUNT to decide the array size for handle pointer array.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* 2.1.4
- Bug fix:
  - \* Fixed the LPI2C\_MasterTransferEDMA receive issue when LPI2C share same request source for TX/RX DMA request. In the previous vesion, the API uses scatter gather method, handle command transfer first, then handles the linked TCD which preset with the receive data transfer. The issue is that TX DMA request and RX DMA request are both enabled, when DMA finished the first command TCD transfer and handled the receive data TCD, the TX DMA request still happens due to TX FIFO empty. This results the RX DM-A transfer starting, without waiting on the expected RX DMA request. Fixed the issue by enabling IntMajor interrupt for the command TCD and checking if there is a linked TCD to disable the TX DMA request in LPI2C\_MasterEDMACallback API.
- 2.1.3
  - Improvement:
    - \* Added LPI2C\_WATI\_TIMEOUT macro to allow the user to specify the timeout times for waiting flags in functional API and blocking transfer API.
    - \* Added LPI2C\_MasterTransferBlocking API.
- 2.1.2
  - Bug fix:
    - \* In LPI2C\_SlaveTransferHandleIRQ, reset the slave status to idle when stop flag is detected.
- 2.1.1
  - Bug fix:
    - \* Disabled auto stop feature in eDMA driver. Previously, the autostop feature was enabled at transfer when transferring with stop flag. If the previous transfer was without stop flag, because the auto stop feature is enabled, then when starting a new transfer with stop flag, the stop flag sends before starting the new transfer, and the start flag cannot successfully send, so the transfer cannot start.
    - \* Changed default slave configuration with address stall false.
- 2.1.0
  - API name change:
    - \* LPI2C\_MasterTransferCreateHandle -> LPI2C\_MasterCreateHandle.
    - \* LPI2C\_MasterTransferGetCount -> LPI2C\_MasterGetTransferCount.
    - \* LPI2C MasterTransferAbort -> LPI2C MasterAbortTransfer.
    - $*\ LPI2C\_MasterTransferHandleIRQ -> LPI2C\_MasterHandleInterrupt.$
    - \* LPI2C\_SlaveTransferCreateHandle -> LPI2C\_SlaveCreateHandle.
    - $*\ LPI2C\_SlaveTransferGetCount -> LPI2C\_SlaveGetTransferCount.$
    - \* LPI2C SlaveTransferAbort -> LPI2C SlaveAbortTransfer.
    - \* LPI2C\_SlaveTransferHandleIRQ -> LPI2C\_SlaveHandleInterrupt.
- 2.0.0
  - Initial version.

## **LPSPI**

The current LPSPI driver version is 2.0.2.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.0.2
  - New feature:
    - \* Added a dummy data setup API to allow users to configure the dummy data to be transferred.
    - \* Enabled the 3-wire mode, SIN and SOUT pins can be configured as input/output pin.
- 2.0.1
  - Bug fix:
    - \* The clock source should divided by PRESCALE setting in LPSPI\_MasterSetDelayTimes function.
    - \* Fixed the bug that LPSPI\_MasterTransferBlocking function would hang in some corner cases.
  - Optimization:
    - \* Added #ifndef/#endif to allow user to change the default TX value at compile time.
- 2.0.0
  - Initial version.

#### **LPUART**

The current LPUART driver version is 2.2.5.

- 2.2.5
  - Do not set or clear the TIE/RIE bits when using LPUART\_EnableTxDMA() and LPUART\_EnableRxDMA().
- 2.2.4
  - Added hardware flow control function support.
  - Added idle line detected feature in LPUART\_TransferNonBlocking function. If an idle line was detected, a callback is triggered with status kStatus\_LPUART\_IdleLineDetected returned. This feature may be useful when the received Bytes is less than the expected receive data size. Before triggering the callback, data in the FIFO (if has FIFO) is read out, and all interrupts will not be disabled, except if the receive data size reaches 0.
  - Enabled the RX FIFO watermark function. With the idle line detected feature enabled, you can
    set the watermark value to whatever you want (should be less than the RX FIFO size). Data is
    received and a callback is triggered when data receive is end.
- 2.2.3
  - Changed parameter type in LPUART\_RTOS\_Init() struct rtos\_lpuart\_config -> lpuart\_rtos\_config\_t.
  - Bug fix:
    - \* Disabled LPUART receive interrupt instead of disabling all NVIC when read data from ring buffer. Because the ring buffer is used, receive nonblocking disables all NVIC interrupts to protect the ring buffer. This has a negative effect to other IPS which are using the interrupt.
- 2.2.2
  - Added software reset feature support.
  - Added software reset API to LPUART\_Init().

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.2.1
  - Added separate RX,TX IRQ number support.
- 2.2.0
  - Added 7 data bits and MSB support.
- 2.1.1
  - Removed unnecessary check of event flags and assert in LPUART\_RTOS\_Receive.
  - Always wait for RX event flag in LPUART\_RTOS\_Receive.
- 2.1.0
  - Update transactional APIs.

#### PIT

The current PIT driver version is 2.0.1.

- 2.0.1
  - Bug Fix:
    - \* Clear timer enable bit for all channels in function PIT\_Init() to make sure all channels stay in disable status before setting other configurations.
- 2.0.0
  - Initial version.

#### **PMU**

The current PMU driver version is 2.1.0.

- 2.1.0
  - Added feature macros for low power control APIs to support to conditional compile.
  - Renamed "PMU\_2P1EnablePullDown" to "PMU\_2P5EnablePullDown"
- 2.0.0
  - Initial version.

### **PWM**

The current PWM driver version is 2.0.0.

- 2.0.0
  - Initial version.

## **PXP**

The current PXP driver version is 2.0.0.

• 2.0.0

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- Initial version.

#### **QTMR**

The current QTMR driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **RTWDOG**

The current RTWDOG driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### SAI

The current SAI driver version is 2.1.5. -2.1.5

- Bug fix:
  - Correct SAI3 driver IRQ handler name.
  - Add I2S4/5/6 IRQ handler.
  - Add base in handler structure to support different instances share one IRQ number.
- New feature:
  - Update SAI driver for MCR bit MICS.
  - Add 192KHZ/384KHZ in the sample rate enumeration.

#### 2.1.4

- New feature:
  - Added API to enable/disable auto FIFO error recovery in platforms that support this feature.
  - Added API to set data packing feature in platform which support this feature.

#### 2.1.3

- New feature:
  - Added feature to make I2S frame sync length configurable according to bitWidth.

#### 2.1.2

- Bug fix:
  - Added 24-bit support for SAI eDMA transfer. All data shall be 32 bits for send/receive, as eDMA cannot directly handle 3 Byte transfer.

#### 2.1.1

- Optimization:
  - Reduced code size while not using transactional API.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

18

#### 2.1.0

- API name change:
  - SAI\_GetSendRemainingBytes -> SAI\_GetSentCount.
  - SAI GetReceiveRemainingBytes -> SAI GetReceivedCount.
  - All transcational API name add "Transfer" prefix.
  - All transactional API use base and handle as input parameter.
  - Unify the parameter names.
- Bug fix:
  - Fixed WLC bug while reading TCSR/RCSR registers.
  - Fixd MOE enable flow issue, move MOE enable after MICS settings in SAI\_TxInit/SAI\_Rx-Init.

#### 2.0.0

• Initial version.

#### **SEMC**

The current SEMC driver version is 2.0.4.

- 2.0.4
  - Fix the SEMC queueA and queueB weight configuration issue.
- 2.0.3
  - Add feature macro to control WDS&WDH bit setting for NOR synchronous transfer.
- 2.0.2
  - Changed SEMC NAND configuration structure and verify SEMC NAND related APIs.
  - Added extended SEMC clock enable
- 2.0.1
  - Fixed data size mask configure in SEMC\_ConfigureIPCommand API.
  - Updated the command mode in IP command type.
- 2.0.0
  - Initial version.

#### **SPDIF**

The current SPDIF driver version is 2.0.1.

- 2.0.1
  - Correct the feature macro name used to define s edmaPrivateHandle.
- 2.0.0
  - Initial version.

#### **SRC**

The current SRC driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **TEMPMON**

The current TEMPMON driver version is 2.0.0.

- 2.0.0
  - Initial version.

### **TSC**

The current TSC driver version is 2.0.1.

- 2.0.1
  - Add control macro to enable/disable the CLOCK code in current driver.
- 2.0.0
  - Initial version.
  - This module was first developed on I.MX 6ULL.

#### **USDHC**

The current USDHC driver version is 2.2.4.

- 2.2.4
  - Fix issue that real clock frequency is mismatch with target clock frequency, which is caused by incorrect prescaler calculation.
  - Add control macro to enable/disable the CLOCK code in current driver.
- 2.2.3
  - Fixed issue where AMDA did not disable with DMAEN clear.
  - Improved set clock function to check the output frequency range.
  - Dynamic set SDCLKFS during DDR enable or disable.
- 2.2.2
  - Improved read transfer cache maintain operation, combined clean and invalidated into one function.
- 2.2.1
  - Disabled the invalidate cache operation for tuning.
- 2.2.0
  - Improved USDHC to support mmc boot feature.
- 2.1.3
  - Fixed MISRA issue.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

20

- 2.1.2
  - Fixed Coverity issue.
  - Added base address and userData parameter for all callback functions.
- 2.1.1
  - Added cache maintain operation.
  - Added timeout status check for the DATA transfer which ignore error.
  - Added feature macro for SDR50/SDR104 mode.
  - Removed useless IRQ handler for different platform.
- 2.1.0
  - Integrated tuning into transfer function.
  - Added strobe DLL feature.
  - Added enableAutoCommand23 in data structure.
  - Removed enable card clock function because the controller will handle the clock on/off.
- 2.0.0
  - Initial version.

#### **WDOG**

The current WDOG driver version is 2.0.1.

- 2.0.1
  - Add control macro to enable/disable the CLOCK code in current driver.
- 2.0.0
  - Initial version.

#### **XBARA**

The current XBARA driver version is 2.0.3.

- 2.0.3
  - Bug fixes:
    - \* Corrected configuration for function XBAR\_SetOutputSignalConfig.
- 2.0.2
  - Other changes:
    - \* Changed array clock name.
- 2.0.1
  - Bug fixes:
    - \* Fixed w1c bits for XBARA\_SetOutputSignalConfig function.
- 2.0.0
  - Initial version.

## **XBARB**

The current XBARB driver version is 2.0.1.

- 2.0.1
  - Bug fixes:
    - \* Corrected XBARB\_SetSignalsConnection function.
  - Other changes:
    - \* Changed array clock name.
- 2.0.0
  - Initial version.

# 2 Middleware Change Log

## emWin library

The currently supported version is 5.38a.

## FatFs for MCUXpresso SDK

Current version is FatFs R0.13a rev0.

- R0.13a\_rev0
  - Upgraded to version 0.13a. Added patch ff\_13a\_p1.diff.
- R0.12c rev1
  - Add NAND disk support.
- R0.12c\_rev0
  - Upgraded to version 0.12c and applied patches ff\_12c\_p1.diff and ff\_12c\_p2.diff.
- R0.12b rev0
  - Upgraded to version 0.12b.
- R0.11a
  - Added glue functions for low-level drivers (SDHC, SDSPI, RAM, MMC). Modified diskio.c.
  - Added RTOS wrappers to make FatFs thread safe. Modified syscall.c.
  - Renamed ffconf.h to ffconf\_template.h. Each application should contain its own ffconf.h.
  - Included ffconf.h into diskio.c to enable the selection of physical disk from ffconf.h by macro definition.
  - Conditional compilation of physical disk interfaces in diskio.c.

## IwIP for MCUXpresso SDK.

The current version of lwIP is based on lwIP 2.0.3.

- 2.0.3\_rev1
  - New features:
    - \* Ported lwIP 2.0.3 (2017-09-15, SHA-1: 92f23d6ca0971a32f2085b9480e738d34174417b) to MCUXPRESSO SDK 2.0.0.
- 2.0.2 rev1
  - New features:
    - \* Ported lwIP 2.0.2 (2017-03-13, SHA-1: c0862d60746e2d1ceae69af4c6f24e469570ecef) to MCUXPRESSO SDK 2.0.0.
- 2.0.0\_rev3
  - New features:
    - \* Ported lwIP 2.0.0 (2016-11-10, SHA-1: 216bf89491815029aa15463a18744afa04df58fe) to MCUXPRESSO SDK 2.0.0.
- 2.0.0\_rev2

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- New features:
  - \* Ported lwIP 2.0.0 RC2 (2016-08-08, SHA-1: b1dfd00f9233d124514a36a8c8606990016f2ad4) to MCUXPRESSO SDK 2.0.0.
- 2.0.0\_rev1
  - New features:
    - \* Ported lwIP 2.0.0 RC0 (2016-05-26) to MCUXPRESSO SDK 2.0.0.
    - \* Changed lwIP bare-metal examples to use poll-driven approach instead of interrupt-driven one.
- 1.4.1 rev2
  - New features:
    - \* Enabled critical sections in lwIP.
  - Bug fixes:
    - \* Fixed default lwIP packet-buffer size to be able to accept a maximum size frame from the ENET driver.
    - \* Fixed possible drop of multi-frame packets during transmission.
- 1.4.1\_rev1
  - New features:
    - \* Ported lwIP 1.4.1 to MCUXPRESSO SDK 2.0.0.

## mbedTLS for MCUXpresso SDK

The current version of mbedTLS is based on mbedTLS 2.9.0 released 2018-May-01.

- 2.9.0 rev1
  - New features:
    - \* Added support for CASPER driver.
- 2.9.0
  - New features:
    - \* Ported mbedTLS 2.9.0 to MCUXPRESSO SDK.
- 2.6.0\_rev2
  - Bug fixes:
    - \* ssl\_cookie.c now uses SHA256 for COOKIE\_MD (instead of original SHA224). Some hw crypto acceleration (such as CAU3) don't support SHA224 but all support SHA256.
- 2.6.0\_rev1
  - Bug fixes:
    - \* ksdk\_mbedtls.c bignum functions now read sign of input mbedtls\_mpi at beginning of functions to properly support in place computations (when output bignum is the same as one of input bignums). Affected functions: mbedtls\_mpi\_mul\_mpi(), mbedtls\_mpi\_mod\_mpi(), ecp\_mul\_comb().
- 2.6.0
  - New features:
    - \* Ported mbedTLS 2.6.0 to MCUXPRESSO SDK.
    - \* Added MBEDTLS\_FREESCALE\_FREERTOS\_CALLOC\_ALT to allow alternate implementation of pvPortCalloc() when using .c.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.5.1 rev1
  - New features:
    - \* Added support for DCP driver.
- 2.5.1
  - New features:
    - \* Ported mbedTLS 2.5.1 to MCUXPRESSO SDK.
- 2.4.2\_rev2
  - New features:
    - \* Added Curve25519 support for CAU3.
    - \* Added MBEDTLS\_ECP\_MUL\_MXZ\_ALT configuration parameter enabling overloading of ecp\_mul\_mxz().
- 2.4.2 rev1
  - New features:
    - \* Added support for CAU3 driver.
    - \* Added new files:
    - \* .c contains regular software implementation of DES algorithm with added MBEDTL-S\_DES3\_SETKEY\_DEC\_ALT and MBEDTLS\_DES3\_SETKEY\_ENC\_ALT config parameters.
    - \* .h contains modified mbedtls\_des\_context and mbedtls\_des3\_context structures.
    - \* Added MBEDTLS\_DES3\_SETKEY\_DEC\_ALT configuration parameter enabling reloading of mbedtls\_des3\_set2key\_dec() and mbedtls\_des3\_set3key\_dec().
    - \* Added MBEDTLS\_DES3\_SETKEY\_ENC\_ALT configuration parameter enabling reloading of mbedtls\_des3\_set2key\_enc() and mbedtls\_des3\_set3key\_enc().
- 2.4.2
  - New features:
    - \* Ported mbedTLS 2.4.2 to MCUXPRESSO SDK 2.0.0.
    - \* Added CRYPTO\_InitHardware() function.
    - \* Added new file:
      - · .h contains declaration of CRYPTO\_InitHardware() function and should be included in applications.
- 2.3.0 rev1
  - New features:
    - \* Added support for CAAM driver.
    - \* In LTC-specific wrapper, allocate temporary integers from heap in one large block.
- 2.3.0
  - New features:
    - \* Ported mbedTLS 2.3.0 to MCUXPRESSO SDK 2.0.0.

#### 2.2.1

- New features:
  - Ported mbedTLS 2.2.1 to MCUXPRESSO SDK 2.0.0.
  - Added support of MMCAU cryptographic acceleration module. Accelerated MD5, SHA, AE-S, and DES.
  - Added support of LTC cryptographic acceleration module. Accelerated AES, DES, and PKH-A.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- Added new files:
- .c alternative implementation of cryptographic algorithm functions using LTC and MMCAU module drivers.
- .h configuration settings used by mbedTLS MCUXPRESSO SDK bare metal examples.
- Added mbedTLS MCUXPRESSO SDK bare-metal examples:
  - \* <board name> KSDK mbedTLS benchmark application.
  - \* <board name> KSDK mbedTLS self-test application.
- Added MBEDTLS\_GCM\_CRYPT\_ALT configuration parameter enabling reloading of mbedtls\_gcm\_crypt\_and\_tag().
- Added MBEDTLS\_ECP\_MUL\_COMB\_ALT to enable alternate implementation of ecp\_mul\_comb().
- Added MBEDTLS\_ECP\_ADD\_ALT configuration parameter enabling reloading of ecp\_add().
- Added MBEDTLS\_DES\_SETKEY\_DEC\_ALT configuration parameter enabling reloading of mbedtls\_des\_setkey\_dec(), mbedtls\_des3\_set2key\_dec() and mbedtls\_des3\_set3key\_dec().
- Added MBEDTLS\_DES\_SETKEY\_ENC\_ALT configuration parameter enabling reloading of mbedtls\_des\_setkey\_enc(), mbedtls\_des3\_set2key\_enc() and mbedtls\_des3\_set3key\_enc().
- Added MBEDTLS\_DES\_CRYPT\_CBC\_ALT configuration parameter enabling reloading of mbedtls\_des\_crypt\_cbc().
- Added MBEDTLS\_DES3\_CRYPT\_CBC\_ALT configuration parameter enabling reloading of mbedtls\_des3\_crypt\_cbc().
- Added MBEDTLS\_AES\_CRYPT\_CBC\_ALT configuration parameter enabling reloading of mbedtls\_aes\_crypt\_cbc().
- Added MBEDTLS\_AES\_CRYPT\_CTR\_ALT configuration parameter enabling reloading of mbedtls\_aes\_crypt\_ctr().
- Added MBEDTLS\_CCM\_CRYPT\_ALT configuration parameter enabling reloading of mbedtls\_ccm\_encrypt\_and\_tag() and mbedtls\_ccm\_auth\_decrypt().
- Added MBEDTLS\_MPI\_ADD\_ABS\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_add\_abs().
- Added MBEDTLS\_MPI\_SUB\_ABS\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_sub\_abs().
- Added MBEDTLS\_MPI\_EXP\_MOD\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_exp\_mod().
- Added MBEDTLS\_MPI\_MUL\_MPI\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_mul\_mpi().
- Added MBEDTLS\_MPI\_MOD\_MPI\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_mod\_mpi().
- Added MBEDTLS\_MPI\_GCD\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_gcd().
- Added MBEDTLS\_MPI\_INV\_MOD\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_inv\_mod().
- Added MBEDTLS\_MPI\_IS\_PRIME\_ALT configuration parameter enabling reloading of mbedtls\_mpi\_is\_prime().
- Added encrypt/decrypt mode to mbedtls\_des\_context and mbedtls\_des3\_context structure.
- Added carriage return "for mbedtls\_printf() in self test functions.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

#### **SDMMC**

The current driver version is 2.2.6.

- 2.2.6
  - Improvement:
    - \* Remove some soc specific header files from porting layer.
    - \* Save MMC OCR registers while sending CMD1 with argument 0.
- 2.2.5
  - New features:
    - \* Add SD\_ReadStatus api to get 512bit SD status.
    - \* Add error log support in SD card functions.
    - \* Add SDMMC\_ENABLE\_SOFTWARE\_TUNING to enable/disable software tuning and it is disabled by default.
    - \* Add error procedure in the transfer function to improve stability.
    - \* Remove deprecated gpio api in host layer.
- 2.2.4
  - Bug fix:
    - \* Fixed DDR mode data sequence miss issue, which is caused by NIBBLE\_POS.
  - New features:
    - \* Increased g\_sdmmc 512byte to improve the performance when application use a non-word align data buffer address.
    - \* Used OCR access mode bits to determine the MMC card high capacity flag.
    - \* Enabled auto cmd12 for SD read/write.
    - \* Disabled DDR mode frequency multiply by 2.
- 2.2.3
  - Bug fix:
    - \* Added response check for send operation condition command. If not checked, the card may occasionally init fail.
- 2.2.2
  - Moved set card detect priority operation before enable IRQ.
- 2.2.1
  - New features:
    - \* Improved MMC Boot feature.
    - \* Keep SD\_Init/SDIO\_Init function for forward compatibility.
- 2.2.0
  - New features:
    - \* Separated the SD/MMC/SDIO init API to xxx\_CardInit/xxx\_HostInit.
    - \* Allowed user register card detect callback, select card detect type, and determine the card detect timeout value.
    - \* Allowed user register the power on/off function, and determine the power on/off delay time.
    - \* SD\_Init/SDIO\_Init will be deprecated in the next version.
    - \* Added write complete wait operation for MMC\_Write to fix command timeout issue.
- 2.1.6
  - Enhanced SD IO default driver strength.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- 2.1.5
  - Fixed Coverity issues.
  - Fixed SD v1.x card write fail issue. It was caused by the block length set error.
- 2.1.4
  - Miscellaneous:
    - \* Added Host reset function for card re-initialization.
    - \* Added Host\_ErrorRecovery function for host error recovery procedure.
    - \* Added cache maintain operation
    - \* Added HOST CARD INSERT CD LEVEL to improve compatibility.
  - Bug fix:
    - \* Fixed card cannot detect dynamically.
- 2.1.3
  - Bug fix:
    - \* Non high-speed SD card init fail at switch to high speed.
  - Miscellaneous:
    - \* Optimized tuning/mmc switch voltage/mmc select power class/mmc select timing function.
    - \* Added strobe dll for mmc HS400 mode.
    - \* Added Delay for SDCard power up.
- 2.1.2
  - New features:
    - \* Added fsl\_host.h to provide prototype to adapt different controller IPs(SDHC/SDIF).
    - \* Added adaptor code in SDMMC/Port folder to adapt different host controller IPs with different. transfer modes(interrupt/polling/freertos). Application includes a different adaptor code to make application more simple.
    - \* Adaptor code provides HOST\_Init/HOST\_Deinit/CardInsertDetect. APIs to do host controller initialize and transfer function configuration. SDMMC card stack uses adaptor code inside stack to wait card insert and configure host when calling card init APIs (SD\_Init/MMC\_Init/SDIO\_Init).
    - \* This change requires the user to include host adaptor code into the application. If not changed, link errors saying it cannot find the definition of HOST\_Init/HOST\_Deinit/-CardInsertDetect appear.
  - New features: Improved SDMMC to support SD v3.0 and eMMC v5.0.
  - Bug fix:
    - \* Fixed incorrect comparison between count and length in MMC\_ReadBlocks/MMC\_-WriteBlocks.
- 2.1.1
  - Bug fix:
    - \* Fixed the block range boundary error when transferring data to MMC card.
    - \* Fixed the bit mask error in the SD card switch to high speed function.
  - Other changes:
    - \* Added error code to indicate that SDHC ADMA1 transfer type is not supported yet.
    - \* Optimized the SD card initialization function.
- 2.1.0
  - Bug fix:

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* Change the callback mechanism when sending a command.
- \* Fix the performance low issue when transferring data.
- Other changes:
  - \* Changed the name of some error codes returned by internal function.
  - \* Merged all host related attributes to one structure.
  - \* Optimize the function of setting maximum data bus width for MMC card.

#### **SDIO**

The current driver version is 2.2.6.

- 2.2.6
  - New features:
    - \* Add a unify transfer interface for SDIO.
  - Bug fix:
    - \* Wrong pointer address used by SDMMCHOST\_Init.
- 2.1.5
  - Bug fix:
    - \* Improved SDIO card init sequence and add retry option for SDIO\_SwitchToHighSpeed function.
- 2.1.4
  - Miscellaneous:
    - \* Added Go\_Idle function for SDIO card.
- 2.0.0
  - Initial version.

#### **SDSPI**

The current driver version is 2.1.3.

- 2.1.3
  - Improve SDSPI code size and performance.
- 2.0.0
  - Initial version.

## **USB stack for MCUXpresso SDK.**

The current version of USB stack is 2.0.1.

- 2.0.1
  - Bug fix:
    - \* fixed some USB issues.
    - \* Change the audio codec interfaces.
- 2.0.0

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- New features:
  - \* PTN5110N support.
- Bug fix:
  - \* Added some comments, fixed some minor USB issues.
- 1.9.0
  - New features:
    - \* Examples:
      - · usb\_pd\_alt\_mode\_dp\_host
- 1.8.2
  - Updated license.
- 1.8.1
  - Bug fix:
    - \* Verified some hardware issues, support aruba\_flashless.
- 1.8.0
  - New features:
    - \* Examples:
      - usb\_device\_composite\_cdc\_vcom\_cdc\_vcom
      - · usb\_device\_composite\_hid\_audio\_unified
      - · usb\_pd\_sink\_battery
      - · Changed usb\_pd\_battery to usb\_pd\_charger\_battery.

#### Bug fix:

• Code cleaned up, removed some irrelevant code.

## 1.7.0

- New features:
  - USB PD stack support.
- Examples
  - usb\_pd
  - usb\_pd\_battery
  - usb\_pd\_source\_charger

#### 1.6.3

• Bug fix: -IP3511\_HS driver control transfer sequence issue, enabled 3511 ip cv test.

#### 1.6.2

- New features:
  - Multi instance support.

#### 1.6.1

- New features:
- Changed the struct variable address method for device\_video\_virtual\_camera and host\_phdc\_manager.

#### 1.6.0

• New features:

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- Supported Device Charger Detect feature on usb\_device\_hid\_mouse.

#### 1.5.0

- New features:
  - Supported controllers
    - \* OHCI (Full Speed, Host mode)
    - \* IP3516 (High Speed, Host mode)
    - \* IP3511 (High Speed, Device mode)
  - Examples:
    - \* usb\_lpm\_device\_hid\_mouse
    - \* usb\_lpm\_device\_hid\_mouse\_lite
    - \* usb\_lpm\_host\_hid\_mouse

#### 1.4.0

- New features:
  - Examples:
    - \* usb\_device\_hid\_mouse/freertos\_static
    - \* usb\_suspend\_resume\_device\_hid\_mouse\_lite

#### 1.3.0

- New features:
  - Supported roles
    - \* OTG
  - Supported classes
    - \* CDC RNDIS
  - Examples
    - \* usb\_otg\_hid\_mouse
    - \* usb\_device\_cdc\_vnic
    - \* usb\_suspend\_resume\_device\_hid\_mouse
    - \* usb\_suspend\_resume\_host\_hid\_mouse

#### 1.2.0

- New features:
  - Supported controllers
    - \* LPC IP3511 (Full Speed, Device mode)

#### 1.1.0

- Bug fix:
  - Fixed some issues in USB certification.
  - Changed VID and Manufacturer string to NXP.
- New features:
  - Supported classes
    - \* Pinter
  - Examples:
    - \* usb\_device\_composite\_cdc\_msc\_sdcard
    - \* usb\_device\_printer\_virtual\_plain\_text

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

\* usb\_host\_printer\_plain\_text

#### 1.0.1

- Bug fix:
  - Improved the efficiency of device audio speaker by changing the transfer mode from interrupt to DMA, thus providing the ability to eliminate the periodic noise.

#### 1.0.0

- New features:
  - Supported roles
    - \* Device
    - \* Host
  - Supported controllers:
    - \* KHCI (Full Speed)
    - \* EHCI (High Speed)
  - Supported classes:
    - \* AUDIO
    - \* CCID
    - \* CDC
    - \* HID
    - \* MSC
    - \* PHDC
    - \* VIDEO
  - Examples:
    - \* usb\_device\_audio\_generator
    - \* usb\_device\_audio\_speaker
    - \* usb\_device\_ccid\_smart\_card
    - \* usb\_device\_cdc\_vcom
    - \* usb\_device\_cdc\_vnic
    - \* usb device composite cdc msc
    - \* usb\_device\_composite\_hid\_audio
    - \* usb\_device\_composite\_hid\_mouse\_hid\_keyboard
    - \* usb device hid generic
    - \* usb\_device\_hid\_mouse
    - \* usb\_device\_msc\_ramdisk
    - \* usb\_device\_msc\_sdcard
    - \* usb\_device\_phdc\_weighscale
    - \* usb\_device\_video\_flexio\_ov7670
    - \* usb\_device\_video\_virtual\_camera
    - \* usb\_host\_audio\_speaker
    - \* usb\_host\_cdc
    - \* usb\_host\_hid\_generic
    - \* usb\_host\_hid\_mouse
    - \* usb\_host\_hid\_mouse\_keyboard
    - \* usb\_host\_msd\_command

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* usb host msd fatfs
- \* usb\_host\_phdc\_manager
- \* usb\_keyboard2mouse
- \* usb\_pin\_detect\_hid\_mouse

#### **QCA WiFi**

The current version is 2.0.0.

- 2.0.0
  - Initial version.
    - \* Added QCA WiFi, ported from SDK 1.3, synchronized with latest MQX Qualcomm v3.-
  - Known issues:
    - \* Low power mode may not work, requires further investigation.
    - \* DHCP request requires some timeout to retrieve valid data.

### wolfSSL

The current version is 3.9.8\_rev3, based on Release 3.9.8 of wolfSSL.

- 3.9.8\_rev3
  - New features:
    - \* Added support for DCP driver.
- 3.9.8\_rev2
  - New features:
    - \* Added support for CAU3 driver.
- 3.9.8 rev1
  - New features:
    - \* Added support for CAAM driver.
    - \* Added FREESCALE ALT macros.
- 3.9.8
  - New features:
    - \* Added support for AES and SHA acceleration modules of LPC devices. Accelerates AES and SHA wolfSSL modules.
    - \* LTC acceleration for AES CBC now updates IV.
  - Bug fixes:
    - \* Fixed K8x/KL8x LTC RSA sign when FREESCALE\_LTC\_TFM\_RSA\_4096\_ENABLE macro is enabled.
- 3.9.0
  - New features:
    - \* Added more LTC public key acceleration (curve25519, ed25519 and RSA4096).
    - \* FREESCALE\_LTC\_TFM\_RSA\_4096\_ENABLE macro added to enable RSA4096 on K8x/KL8x LTC.

#### MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

- \* LTC MAX ECC BITS increased to 384 to enable ECC-384 curve acceleration on LTC.
- \* FREESCALE LTC SHA added for KL8x SHA-1 and SHA-256 hardware acceleration.
- Other changes:
  - \* wolfSSL/wolfcrypt/settings.h is changed to remove unused macros and add support for MCUXPRESSO SDK 2.0.
  - \* LTC public key acceleration is implemented in separate source file ksdk\_port.h and ksdk\_port.c

#### • 3.8.0

- New features:
  - \* Added support for LTC hardware acceleration module. Accelerates AES, 3DES, TFM module (modular integer arithmetic) and ECC wolfSSL modules.
  - \* Added support for random number generator modules TRNG and RNGA.
- Other changes:
  - \* The MMCAU acceleration now uses "fsl\_mmcau.h" instead of "cau\_api.h".
  - \* In DSA, wc\_dsaSign() changed to repeate wc\_RNG\_GenerateBlock() until k is less than q.
  - \* wolfSSL/wolfcrypt/settings.h is changed to remove unused macros and add support for MCUXPRESSO SDK 2.0.
  - \* In wolfcrypt/src/asn.c, ksdk\_time(time\_t) changed to extern, to be defined by application.

MCUXpresso SDK Release Notes Supporting EVK-MIMXRT1064, Rev. 0, 10/2018

34

# 3 RTOS Change Log

## FreeRTOS for MCUXpresso SDK.

The current version is FreeRTOS 9.0.0. Original package is available at freertos.org.

- 9.0.0 rev3
  - New features:
    - \* Tickless idle mode support for Cortex-A7. Add fsl\_tickless\_epit.c and fsl\_tickless\_generic.h in portable/IAR/ARM\_CA9 folder.
    - \* Enabled float context saving in IAR for Cortex-A7. Added configUSE\_TASK\_FPU\_SU-PPORT macros. Modified port.c and portmacro.h in portable/IAR/ARM\_CA9 folder.
  - Other changes:
    - \* Transformed ARM\_CM core specific tickless low power support into generic form under freertos/Source/portable/low\_power\_tickless/.
- 9.0.0\_rev2
  - New features:
    - \* Enabled MCUXpresso thread aware debugging. Add freertos\_tasks\_c\_additions.h and configINCLUDE\_FREERTOS\_TASK\_C\_ADDITIONS\_H and configFRTOS\_MEMORY SCHEME macros.
- 9.0.0 rev1
  - New features:
    - \* Enabled -flto optimization in GCC by adding attribute((used)) for vTaskSwitchContext.
    - \* Enabled KDS Task Aware Debugger. Apply FreeRTOS patch to enable configRECORD\_STACK\_HIGH\_ADDRESS macro. Modified files are task.c and FreeRTOS.h.
- 9.0.0 rev0
  - New features:
    - \* Example freertos\_sem\_static.
    - \* Static allocation support RTOS driver wrappers.
  - Other changes:
    - \* Tickless idle rework. Support for different timers is in separated files (fsl\_tickless\_systick.c, fsl\_tickless\_lptmr.c).
    - \* Removed configuration option configSYSTICK\_USE\_LOW\_POWER\_TIMER. Low power timer is now selected by linking of apropriate file fsl\_tickless\_lptmr.c.
    - \* Removed configOVERRIDE\_DEFAULT\_TICK\_CONFIGURATION in RVDS port. Use of **attribute**((weak)) is the preferred solution. Not same as weak!
- 8.2.3
  - New features:
    - \* Tickles idle mode support.
    - \* Added template application for Kinetis Expert (KEx) tool (template\_application).
  - Other changes:
    - \* Folder structure reduction. Keep only Kinetis related parts.

How to Reach Us:

Home Page:

nxp.com

Web Support:

nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP. the NXP logo. NXP SECURE CONNECTIONS FOR A SMARTER WORLD. COOLFLUX. EMBRACE, GREENCHIP, HITAG, I2C BUS, ICODE, JCOP, LIFE VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, AltiVec, C-5, CodeTEST, CodeWarrior, ColdFire, ColdFire+, C-Ware, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorlQ, QorlQ Qonverge, Ready Play, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, SMARTMOS, Tower, TurboLink, and UMEMS are trademarks of NXP B.V. All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamlQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© 2018 NXP B.V.

Document Number MCUXSDKMIMXRT1064RN Revision 0, 10/2018



