Work Instruction - Operations

HNADLING LOSS OF RADIO COMMUNICATIONS



Work description: This OCC Work Instruction details the handling of the loss of Radio Communications. **Scope:** This Work Instruction is written specifically for OCC operating staff of Honolulu Rail Transit. References: N/A **PPE and precautions Competencies or qualifications** Licenses or permits required Nil OCC Supervisor, Train Controller, Nil Controller, Information Controller, Engineering and Fault Customer Controller, Service Supervisor, Station Attendant, Train Attendant **Tools and equipment required** Nil

Impact to Train	•	None to AUTO trains		
Service	•	Train service will be affected if there are manually driven trains running within the		
		automatic territory.		

Loss of Radio Communications	
Train Controller / Yard Controller	 report the loss of radio communication to the Engineering and Fault Controller immediately inform the OCC Supervisor of the failure instruct Train Attendants who are operating trains manually to use the onboard ECP temporary to communicate with the OCC to confirm the movement authority when the train is at a standstill
	 instruct Train Attendants who are operating trains manually to resume using the portable handheld radio upon being notified by the Engineering and Fault Controller on the recovery of the EDACS radio system
Engineering and Fault Controller	 find out the extent of the failure inform the relevant Maintainer to immediately arrange first line maintenance team for maintenance intervention inform all relevant Maintainers to use A-TEL telephones to contact OCC until further notice
	• on notification from the first line maintenance team that the radio system failure have been rectified, inform the OCC Supervisor and the relevant Maintainers on the restoration of the radio system

		© P	
Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09553 - Handling Loss of Radio Communications	Effective Date:	
File Name	-e	Rev No.	Page 1 of 2

Work Instruction - Operations

HNADLING LOSS OF RADIO COMMUNICATIONS



OCC Supervisor

- find out the extent of the failure from the Engineering and Fault Controller especially the estimated recovery times
- inform the OCC Manager of the failures
- instruct Information Controller to inform all relevant internal and external parties to maintain the communication with OCC using A-TEL telephones as a temporary measure
- keep abreast of the fault rectifying progress
- on notification from the Engineering and Fault Controller that the radio system failures have been rectified:
 - instruct the Information Controller to inform all relevant internal and external parties that the radio system has been restored
 - inform the OCC Manager regarding restoration of radio system
 - log the event in the OCC Supervisor Daily Report

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09553 - Handling Loss of Radio Communications	Effective Date:	
File Name	-e	Rev No.	Page 2 of 2