Work Instruction - Operations

HITACHI

SCADA FAILURE WORK INSTRUCTION

Hitachi Rail Honolulu JV

Work description: This work instruction describes the handling of SCADA server failures.						
Scope: This work instruction is written specifically for the OCC operating staff of Honolulu Rail Transit.						
References: HNL-09325 OCC Evacuation Work Instruction						
PPE and precautions	Competencies or qualifications	Licenses or permits required				
Nil	OCC Supervisor, Train Controller, Yard Controller, Information Controller, Engineering & Fault Controller, Station Operator	Nil				
Tools and equipment required						
Nil						

1. Failure of a single SCADA server in the OCC					
Information	You must:				
Controller	1) Inform the Engineering & Fault Controller of the failure				
	2) Inform the OCC Supervisor of the failure				
Engineering & Fault	ineering & Fault You must:				
Controller	1) On receiving a failure report, record/register the fault to the MMIS				
	2) Inform the maintainer to arrange immediate maintenance intervention				
	3) Keep an eye on the SCADA server repair progress				
	4) Inform the OCC Supervisor and the Information Controller about the latest ATS repair progress				
OCC Supervisor	You must:				
	1) Follow the fault rectifying progress closely				

Failure of a pair of redundant SCADA servers in the OCC Engineering & Fault You must: Controller On receiving a failure report, record/register the fault to the MMIS 2) Inform the maintainer to arrange immediate maintenance intervention Inform the OCC Supervisor of the failure 3) On instructions from the OCC Supervisor to evacuate the OCC, follow the HNL-09325 OCC Evacuation Work Instruction for departing from / returning to the OCC OCC Supervisor You must: 1) Find out the extent of failures and the estimated recovery time from the Engineering and Fault Controller Dispatch the Yard Controller to the YCB immediately 2) Instruct the OCC operating staff to evacuate the OCC, follow the HNL-09325 OCC Evacuation Work Instruction for departing from / returning to the OCC Train Controller, You must: Information On instructions from the OCC Supervisor to evacuate the OCC, follow the HNL-09325 OCC Evacuation Work Controller Instruction for departing from / returning to the OCC

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL09423 SCADA Failure Work Instruction.01	Effective Date:	
File Name	HNL-09423.01.00-0-SCADA Failure Work Instruction	Rev No. 01	Page 1 of 2

Work Instruction - Operations

HITACHI

SCADA FAILURE WORK INSTRUCTION

Hitachi Rail Honolulu JV

Yard Controller

You must:

- 1) Stop all train movements in the yard immediately
- 2) Log off from Workstations on your desk
- 3) Bring your handheld radio, important phone numbers and controller logbooks with you
- 4) Leave OCC and proceed to the YCB
- 5) On arrival at YCB, log on to the LATS console and SCADA local panel to resume duties
- 6) On instructions from the OCC Supervisor to return to the OCC, follow the HNL-09325 OCC Evacuation Work Instruction for returning to the OCC
- 7) Stop all train movements in the Yard immediately
- 8) Relinquish controls in the Yard and return to the OCC to resume duties
- 9) Log the event in the Yard Controller Log