Work Instruction - Operations

CCTV FAILURE WORK INSTRUCTION



@Hitachi Rail Honolulu JV

Work description: This OCC Work Instruction	details the handling of CCTV System Failures.	
Scope: This Work Instruction is written specific	cally for OCC operating staff of Honolulu Rail Tra	nsit.
References: HNL-09510 Minimum Operating O	Conditions Work Instruction, HNL-09527 Fault Re	porting Process Work Instruction
PPE and precautions	Competencies or qualifications	Licenses or permits required
Nil	OCC Supervisor, Train Controller, Yard Controller, Information Controller, Engineering & Fault Controller, Security Controller, Train & Stations Supervisor, Station Operator	Nil
Tools and equipment required		
Nil		

When OCC cannot monitor CCTV of station platforms Information Check if the image can be viewed using another CCTV camera Controller If not, check with Train & Stations Supervisors/Station Operators on the extent of the failure – is it just OCC or a system-wide problem? Report the fault to the Engineering & Fault Controller immediately On instruction from OCC Supervisor, inform Train & Stations Supervisors to take over CCTV monitoring of station platforms and update OCC if required Inform Train & Stations Supervisors to arrange sufficient Station Operators to man the key locations in stations On instruction from OCC Supervisor, take back CCTV monitoring of station platforms OCC Supervisor Find out the extent of the failure from the Engineering & fault Controller especially the estimated recovery Inform the OCC Manager Instruct Information Controller to inform Train & Stations Supervisors to take over the CCTV monitoring of station platforms and update OCC regularly if required Keep abreast of the fault rectifying progress On notification from the Engineering & Fault Controller that the CCTV has been restored: Instruct the Information Controller to take back CCTV monitoring of station platforms from Train & Stations Inform the OCC Manager of the restoration of the CCTV system Log the event in the OCC Supervisor Daily Report Engineering & Fault Inform the relevant Maintainer to arrange first line maintenance staff for immediate maintenance intervention Controller Monitor the fault rectifying progress and keep the OCC Supervisor and Information Controller informed

When OCC cannot monitor CCTV of a train's interior

Information Controller

- Check if the image can be viewed using another CCTV camera
 - o If not, check to see if CCTV works on another train
- Report the fault to the Engineering & Fault Controller immediately
- On instruction from OCC Supervisor, check updates regularly from the Train Operators who have been assigned
 On board when OCC could not view trains' interiors
- On instruction from OCC Supervisor, replace the faulty train
- On instruction from OCC Supervisor, take back CCTV monitoring of train's interiors

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09434 CCTV Failure Work Instruction.01	Effective Date:	
File Name	HNL-09434.01.00-0-CCTV Failure Work Instruction	Rev No. 01	Page 1 of 2

Work Instruction - Operations

CCTV FAILURE WORK INSTRUCTION



(6)	Hitachi	Hail	Honolu	lu J

OCC Supervisor

- Find out the extent of the failure from the Engineering & fault Controller especially the estimated recovery times
 - o Inform the OCC Manager
- Instruct Information Controller to inform Train & Stations Supervisors to arrange Train Operators to board the faulty trains
- Decide the best strategy to continue the degraded service or replace the faulty train in accordance with HNL-09510 Minimum Operating Conditions Work Instruction
- Keep abreast of the fault rectifying progress
- On notification from the Engineering & Fault Controller that the CCTV has been restored:
 - Instruct the Information Controller to take back the CCTV monitoring of train interior and inform Train &
 Stations Supervisors of the restoration of the CCTV system
 - Inform the OCC Manager of the resumption of the CCTV system
 - Log the event in the OCC Supervisor Daily Report

Train Operator

- On instruction from OCC, board the assigned trains
- Monitor the train's interior and update the OCC until the train is withdrawn from Commercial Service or the CCTV system is resumed

Engineering & Fault Controller

- Inform the relevant Maintainer to arrange first line maintenance staff for immediate maintenance intervention
- Monitor the fault rectifying progress and keep the OCC Supervisor and Information Controller informed

When OCC cannot monitor CCTV of station or yard premises

Security Controller

- Check if the image can be viewed using another CCTV camera
- Report the fault to the Engineering & Fault Controller immediately
- Arrange sufficient security staff to patrol the restricted areas and areas not covered by the CCTV
- On notification from the OCC Supervisor that the CCTV has been restored, scale back the security staff patrolling, and take back CCTV monitoring of premises

OCC Supervisor

- Find out the extent of the failure from the Engineering & fault Controller especially the estimated recovery times
 - Inform the Security Manager
- Keep abreast of the fault rectifying progress
- On notification from the Engineering & Fault Controller that the CCTV has been restored:
 - Instruct the Security Controller to scale back the security staff patrolling and take back CCTV monitoring of premises
 - o Inform the Security Manager of the resumption of the CCTV system
 - Log the event in the OCC Supervisor Daily Report

Engineering & Fault Controller

- Inform the relevant maintainer to arrange first line maintenance staff for immediate maintenance intervention
- Monitor the fault rectifying progress and keep the OCC Supervisor and Security Controller informed

Document Code	HNL-09434 CCTV Failure Work Instruction.01	Effective Date:	
File Name	HNL-09434.01.00-0-CCTV Failure Work Instruction	Rev No. 01	Page 2 of 2