CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

•	uction describes the arrangements required for implementi itten specifically for the OCC operating staff of Honolulu Rai	
References: Nil		
PPE and precautions	Competencies or qualifications	Licenses or permits required
Nil	OCC Supervisor, Train Controller,	Nil
	Information Controller, Engineering & Fault	
	Controller, Station Operator	
Tools and equipment required		
Nil		



Warning

Be aware of which station platforms that will no longer be served by trains (which may be served by replacement bus services) if you decided to implementation any one of the Contingency Plans.

Contingency Plans

Severe equipment faults or incidents may lead to a line blockage which is a blocked line made inoperable by a disabled train, a total failure of a point, a broken rail, electrical faults, or a BLS activation, etc. A blocked line may lead to longer delays seriously disrupting the overall train service.

To maintain limited train service as much as practicable on the unaffected sections, the OCC Supervisor, with the help from the Train Controller, after assessing the situation may deploy one or more Contingency Plans as appropriate under the operational circumstances.

ATS System contains a list of pre-defined signaling routes which can be used to support the Contingency Plans in revenue service. The altered Destination IDs set by the Train Controller are then used by the Vehicle Regulation for train routing.



Note

In case of the Contingency Plan implementation the system shall be set in Headway Regulation. Schedule Regulation under Contingency Plans will be used only during overhaul period that a portion on the line will be unavailable for a longer period (1 week or more) for heavy maintenance activity!



Note

For all single-line blockages, the OCC Supervisor may REPLACE the extended train shuttling with replacement bus service for bridging those stations that have been blocked; thus, the handlings can be simplified. This will work only if the replacement bus service is available.

Legend	
	Line blockage
1	Train Operation Direction
†	Bi-directional Train Operation (Reversing)
\longrightarrow	2nd Loop: Train Operation Direction
†	2nd Loop: Bi-directional Train Operation (Reversing)
\leftarrow	(Optional) Bus Replacement Service

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 1 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION


HITACHI

@Hitachi Rail Honolulu JV

Plan No. 0	Normal Operations Pinched Loop - Intermediate O&M Period 1
Terminus:	East Kapolei DOWN platform (default)<->Aloha Station UP platform (default)



NORMAL OPERATIONS




Additional Staff Requirements	
Station Operator(s)	not required


Staff Action	Staff Action	
Engineering & Fault Controller	Carry out duties as usual	
Maintainer	Carry out duties as usual	
Train Controller	Carry out duties as usual	
OCC Supervisor	Carry out duties as usual	
Information Controller	Carry out duties as usual	
Station Operator(s) at East Kapolei	Carry out duties as usual	

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 2 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI





Additional Staff Requiremen	nts
Station Operator(s)	not required


Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage at East Kapolei DOWN platform
Maintainer	Send maintenance unit to the scene to address the blockage
	De-energize and isolate the blocked area from the running line
Train Controller	No intervention required because the switch to alternative platform is automatic
OCC Supervisor	Monitor the fault rectifying process closely
Information Controller	Inform Station Operators at East Kapolei Station about the use of the UP platform instead
Station Operator(s) at East Kapolei	Inform passengers to use the UP platform

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 2	This plan handles a double-line blockage covering East Kapolei Station
Terminus:	West Oahu Station DOWN platform<->Aloha Station UP platform (default)



Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at West Oahu Station to assist passengers transferring among buses/trains

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage beyond West Oahu Station
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for West Oahu Station Arrange the bus bridge service with service provider
Information Controller	 Inform UP track stations that the new terminus is West Oahu Station Inform East Kapolei Station and West Oahu the bus access points
Station Operator(s) at West Oahu Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at East Kapolei Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 4 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 3	This plan handles a single-line blockage from East Kapolei Station to West Oahu Station UP track	
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)	



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at both East Kapolei Station DOWN platform and West Oahu Station DOWN	
	platform to assist passengers going eastbound / westbound	

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line	
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	Request additional workforce for East Kapolei Station and West Oahu Station	
Information Controller	Inform Station Operators at East Kapolei Station about the use of the DOWN platform instead	
Station Operator(s) at East Kapolei Station and West Oahu Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 5 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 4	This plan handles a single-line blockage at East Kapolei Station DOWN track and at West Oahu Station UP track	
Terminus:	East Kapolei UP platform<->Aloha Station UP platform (default)	



Additional Staff Requirements		
Station Operator(s)		
	platform to assist passengers going eastbound / westbound	

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage at the UP track of West Oahu Station and the DOWN track of East Kapolei Station	
Maintainer	Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line	
Train Controller	Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at Hoopili Station UP platform and East Kapolei Station UP platform before releasing them across Remove excessive trains if required	
OCC Supervisor	Request additional workforce for East Kapolei Station and West Oahu Station	
Information Controller	 Inform Station Operators at East Kapolei Station about the use of the UP platform only Inform Station Operators at West Oahu Station about the use of the DOWN platform only 	
Station Operator(s) at East Kapolei Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at West Oahu Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 6 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 5	This plan handles a single-line blockage from East Kapolei Station to West Oahu Station	
Terminus:	East Kapolei UP platform<->Aloha Station UP platform (default)	



Additional Staff Requirements		
Station Operator(s)		

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required
OCC Supervisor	Request additional workforce for East Kapolei Station and West Oahu Station
Information Controller	 Inform Station Operators at East Kapolei Station about the use of the UP platform only Inform Station Operators at West Oahu Station about the use of the UP platform only
Station Operator(s) at East Kapolei Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at West Oahu Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 7 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 6	This plan handles a single-line blockage from Hoopili Station to West Loch Station
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)



Additional Staff Requirements		
Station Operator(s)	ation Operator(s) 1 to 2 additional staff required at both Hoopili Station DOWN platform and West Loch Station DOWN platform	
	to assist passengers going eastbound / westbound	

Staff Action	Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage		
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 		
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at West Oahu Station DOWN platform and at Waipahu Transit Center Station UP platform before releasing them across Remove excessive trains if required 		
OCC Supervisor	Request additional workforce for Hoopili Station and West Loch Station		
Information Controller	 Inform Station Operators at Hoopili Station about the use of the DOWN platform only Inform Station Operators at West Loch Station about the use of the DOWN platform only 		
Station Operator(s) at Hoopili Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 		
Station Operator(s) at West Loch Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 		


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 8 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 7	This plan handles a single-line blockage from Hoopili Station to West Loch Station
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at both Hoopili Station UP platform and West Loch Station UP platform to	
	assist passengers going eastbound / westbound	

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at Waipahu Transit Center Station UP platform and Pearlridge Station DOWN platform before releasing them across Remove excessive trains if required
OCC Supervisor	Request additional workforce for Hoopili Station and West Loch Station
Information Controller	 Inform Station Operators at Hoopili Station about the use of the UP platform only Inform Station Operators at West Loch Station about the use of the UP platform only
Station Operator(s) at Hoopili Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at West Loch Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 9 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 8	This plan handles a single lines blockage at Leeward CC Station UP track
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at Leeward CC Station DOWN platform to assist passengers going eastbound / westbound	

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at Waipahu Transit Center Station DOWN platform and Pearl Highlands Station UP platform before releasing them across Remove excessive trains if required 	
OCC Supervisor	Request additional workforce for Leeward CC Station	
Information Controller	Inform Station Operators at Leeward CC Station about the use of the DOWN platform only	
Station Operator(s) at Leeward CC Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 10 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 9	This plan handles a single-line blockage at Waipahu Transit Center Station and a single-line blockage at Leeward CC Station UP platform	
Terminus:	East Kapolei Station DOWN platform (default)<->Waipahu Transit Center Station UP platform, and Leeward CC Station DOWN platform<->Aloha Station UP platform (default)	



Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at both Waipahu Transit Center Station UP platform and Leeward CC Station
	DOWN platform to assist passengers transferring among buses/trains

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	 Request additional workforce for Waipahu Transit Center Station and Leeward CC Station Arrange the bus bridge service with service provider 	
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station and Leeward CC Station the bus access points 	
Station Operator(s) at Waipahu Transit Center Station	 Inform passengers to use the UP platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01 Effective Date:	
File Name HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction Rev No. 01	Page 11 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 10	This plan handles a double-line blockage between Waipahu Transit Center Station and Leeward CC Station	
Terminus:	East Kapolei Station DOWN platform (default)<->Waipahu Transit Center Station DOWN platform, and Leeward CC	
	Station DOWN platform<->Aloha Station UP platform (default)	



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at both Waipahu Transit Center Station DOWN platform and Leeward CC	
	Station DOWN platform to assist passengers transferring among buses/trains	

Staff Action	Staff Action Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	 Request additional workforce for Waipahu Transit Center Station and Leeward CC Station Arrange the bus bridge service with service provider 	
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station and Leeward CC Station the bus access points 	
Station Operator(s) at Waipahu Transit Center Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	

End of No. 10


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 12 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 11	This plan handles a single-line blockage at Waipahu Transit Center Station
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)



Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at Waipahu Transit Center Station UP platform to assist passengers going
	eastbound / westbound

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at West Loch DOWN platform and hold trains at Pearl Highlands UP platform before releasing them Remove excessive trains if required
OCC Supervisor	Request additional workforce for Waipahu Transit Center Station
Information Controller	Inform Station Operators at Waipahu Transit Center Station about the use of the UP platform only
Station Operator(s) at Waipahu Transit Center Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 13 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 12	This plan handles a double-line blockage at Leeward CC Station and a sing-line blockage from Pearl Highlands Station to Aloha Stadium Station	
Terminus:	East Kapolei Station DOWN platform (default)<->Waipahu Transit Center Station UP platform, and Pearl Highlands Station UP platform<->Aloha Stadium Station UP platform (default)	



Additional Staff Requirements	
Station Operator(s) 1 to 2 additional staff required at Waipahu Transit Center Station UP platform and Pearl Highlands Stati	
	platform to assist passengers transferring among buses/trains

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for Waipahu Transit Center Station and Pearl Highlands Station Arrange the bus bridge service with service provider
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station, Leeward CC Station and Pearl Highlands Station the bus access points
Station Operator(s) at (Waipahu Transit Center Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Inform passengers to use the UP platform Coordinate replacement bus services (Pearl Highlands) Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Leeward CC Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 14 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 15 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 13	This plan handles a single-line blockage from Pearl Highlands Station to Pearlridge Station and a single-line blockage at Aloha Stadium Station
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station DOWN platform



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at both Pearl Highlands Station UP platform and Pearlridge Station UP platfor	
	to assist passengers going eastbound / westbound	

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan Remove excessive trains if required
OCC Supervisor	Request additional workforce for Pearl Highlands Station and Pearlridge Station
Information Controller	Inform Station Operators at Pearl Highlands Station and Pearlridge Station about the use of the UP platform only
Station Operator(s) at Pearl Highlands Station and Pearlridge Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Aloha Stadium Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 16 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 14	This plan handles a single-line blockage from Pearl Highlands Station to Pearlridge Station	
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Station UP platform (default)	



Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at both Pearl Highlands Station DOWN platform and Pearlridge Station DOWN platform to assist passengers going eastbound / westbound

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set single line operation defined for this plan Set single line operation defined for this plan - hold trains at Leeward CC Station DOWN platform and Aloha Station UP platform before releasing them across Remove excessive trains if required
OCC Supervisor	Request additional workforce for Pearl Highlands Station and Pearlridge Station
Information Controller	Inform Station Operators at Pearl Highlands Station and Pearlridge Station about the use of the DOWN platform only
Station Operator(s) at Pearl Highlands Station and Pearlridge Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 17 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 15	This plan handles a single-line blockage at Aloha Stadium Station	
Terminus:	East Kapolei Station DOWN platform (default)<->Aloha Stadium Station DOWN platform (alternative platform)	



Additional Staff Requirements	
Station Operator(s)	none

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage de-energize and isolate the blocked area from the running line 	
Train Controller	No intervention as the default platform will change to use the alternative platform automatically when the default platform is blocked	
OCC Supervisor	No intervention	
Information Controller	• No intervention because the announcement on train arrival/departure will automatically adjust to use alternative platform at Aloha Stadium Station	
Station Operator(s) at Aloha Stadium Station	Inform passengers to use the DOWN platform	


End of No. 15

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 16	This plan handles a double-line blockage from East Kapolei Station to Hoopili Station	
Terminus:	West Loch Station DOWN platform<->Aloha Stadium Station UP platform (default)	




Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at West Loch Station DOWN platform to assist passengers transferring among buses/trains


Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	 Request additional workforce for West Loch Station Arrange the bus bridge service with service provider 	
Information Controller	 Inform UP track stations that the new terminus is West Loch Station Inform East Kapolei Station, West Oahu Station, Hoopili Station and West Loch Station the bus access points 	
Station Operator(s) at West Loch Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at East Kapolei Station, West Oahu Station and Hoopili Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 19 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI





Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at both West Loch Station DOWN platform and Hoopili Station DOWN platform
	to assist passengers going eastbound / westbound or transferring among buses/trains

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	 Request additional workforce for Hoopoili Station and West Loch Station Arrange the bus bridge service with service provider 	
Information Controller	 Inform UP track stations that the new terminus is Hoopili Station Inform Hoopili Station, West Oahu Station, East Kapolei Station the bus access points 	
Station Operator(s) at Hoopili Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at West Loch Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 20 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 18	This plan handles a single-line blockage from East Kapolei Station to West Oahu Station UP track and a double-line blockage from beyond West Oahu Station to West Loch Station	
Terminus:	East Kapolei Station DOWN platform, West Oahu Station DOWN platform (default)<->West Oahu Station DOWN platform, and Waipahu Transit Center Station UP platform, Aloha Stadium Station UP platform (default)	




Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at West Oahu Station DOWN platform and Waipahu Transit Center Station UP	
	platform to assist passengers transferring among buses/trains	


Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for West Oahu Station and Waipahu Transit Center Station Arrange the bus bridge service with service provider
Information Controller	 Inform UP track stations that the new terminus is Waipahu Transit Center Station Inform West Oahu Station, Hoopili Station, West Loch Station and Waipahu Transit Center Station the bus access points
Station Operator(s) at West Oahu Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Waipahu Transit Center Station	 Inform passengers to use the UP platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Hoopili Station and West Loch Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 21 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI





Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at Hoopili Station UP platform, West Loch Station UP platform and Leeward CC Station DOWN platform to assist passengers going eastbound / westbound and passengers transferring among buses/trains	

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for Hoopili Station, West Loch Station and Leeward CC Station Arrange the bus bridge service with service provider
Information Controller	 Inform stations about the new terminuses Inform West Loch Station, Waipahu Transit Center Station and Leeward CC Station the bus access points
Station Operator(s) at Hoopili Station and West Loch Station	 Inform passengers to use the UP platform Coordinate replacement bus services if applicable Arrange Station Operators to assist passengers Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Arrange Station Operators to assist passengers Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Waipahu Transit Center Station	 Coordinate replacement bus services Arrange Station Operators to assist passengers Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 22 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI


@Hitachi Rail Honolulu JV

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 20	This plan handles a double-line blockage at Leeward CC Station and a single-line blockage from Pearl Highlands Station to Aloha Stadium Station
Terminus:	East Kapolei Station DOWN platform (default)<->Waipahu Transit Center Station DOWN platform, Pearl Highlands Station DOWN platform<->Aloha Stadium Station DOWN platform



Additional Staff Requirements Station Operator(s) 1 to 2 additional staff required at Waipahu Transit Center Station DOWN platform and Pearl Highlands Station DOWN platform to assist passengers transferring among buses/trains

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for Waipahu Transit Center Station and Pearl Highlands Station Arrange the bus bridge service with service provider
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station, Leeward CC Station and Pearl Highlands Station the bus access points
Station Operator(s) at (Waipahu Transit Center, Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Leeward CC Station and Pearl Highlands	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 24 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 21	This plan handles a double-line blockage from Pearl Highlands Station to Aloha Stadium Station	
Terminus:	East Kapolei Station DOWN platform (default), Leeward CC Station DOWN platform	



Additional Staff Requirements	
Station Operator(s) 1 to 2 additional staff required at Leeward CC Station DOWN platform to assist passengers transferring amount of the control of the cont	
	buses/trains

Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	 Request additional workforce for Leeward CC Station Arrange the bus bridge service with service provider 	
Information Controller	 Inform DOWN track stations that the new terminus is Leeward CC Station Inform Leeward Station, Pearl Highlands Station, Pearlridge Station and Aloha Stadium Station the bus access points 	
Station Operator(s) at Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at (Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 25 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 22	This plan handles a double-line blockage at Aloha Stadium Station and a single-line blockage from Pearl Highlands Station to Aloha Stadium Station
Terminus: East Kapolei Station DOWN platform (default), Pearlridge Station UP platform	



Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at Pearlridge Station UP platform to assist passengers going westbound or transferring buses to and from Aloha Station


Staff Action	Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage	
Maintainer	 Send maintenance unit to the scene to address the blockage de-energize and isolate the blocked area from the running line 	
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required 	
OCC Supervisor	Request additional workforce for Pearl Highlands Station and Pearlridge Station	
Information Controller	 Inform DOWN track stations that the new terminus is Pearlridge Station Inform Pearlridge Station and Aloha Stadium Station the bus access points 	
Station Operator(s) at Pearlridge Station	 Inform passengers to use the UP platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at Pearl Highlands Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control 	
Station Operator(s) at Aloha Stadium Station	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 	


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 26 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV





Additional Staff Requirements	
Station Operator(s) 1 to 2 additional staff required at West Oahu Station UP platform to assist passengers going eastbound / westbound	


Staff Action	Staff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage		
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 		
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan Remove excessive trains if required 		
OCC Supervisor	Request additional workforce for West Oahu Station		
Information Controller	Inform Station Operators at West Oahu Station about the use of the UP platform instead		
Station Operator(s) at West Oahu Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control 		


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 27 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV






Additional Staff Requirements	
Station Operator(s)	1 to 2 additional staff required at West Loch Station and Waipahu Transit Station to assist passengers using the replacement bus services


Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage between West Loch Station and Waipahu Transit Center Station
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan remove excessive trains if required
OCC Supervisor	Request additional workforce for West Loch Station and Waipahu Transit Station
Information Controller	Inform UP track stations about the new terminus and the bus access point
Station Operator(s) at West Loch Station and Waipahu Transit Station	 Coordinate replacement bus services Arrange Station Operators to assist passengers Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 28 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI





Additional Staff Requirements				
Station Operator(s) 1 to 2 additional staff required at Waipahu Transit Center Station DOWN platform, Leeward CC Station U				
	platform, Pearl Highlands Station DOWN platform, Pearlridge Station DOWN platform and Aloha Stadium			
	Station DOWN platform to assist passengers going easthound / westhound or transferring among buses/trains			

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for Waipahu Transit Center, Leeward CC Station, Pearl Highlands Station, Pearlridge Station and Aloha Stadium Station Arrange the bus bridge service with service provider
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station and Leeward CC Station the bus access points
Station Operator(s) at (Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Waipahu Transit Center Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Leeward CC Station	 Inform passengers to use the UP platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 29 of 35


CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION


HITACHI

@Hitachi Rail Honolulu JV

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI





Additional Staff Requirements		
Station Operator(s) 1 to 2 additional staff required at Waipahu Transit Center Station DOWN platform, Leeward CC Station platform, Pearl Highlands Station UP platform, Pearlridge Station UP platform and Aloha Stadium Station platform to assist passengers going eastbound / westbound or transferring among buses/trains		

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Remove excessive trains if required
OCC Supervisor	 Request additional workforce for Waipahu Transit Center, Leeward CC Station, Pearl Highlands Station, Pearlridge Station and Aloha Stadium Station Arrange the bus bridge service with service provider
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station and Leeward CC Station the bus access points
Station Operator(s) at (Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Waipahu Transit Center Station and Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 31 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 27	This plan handles a double lines blockage between Leeward CC Station and Pearl Highlands Station, and a single-line blockage from Pearl Highlands Station to Aloha Stadium Station
Terminus:	East Kapolei Station DOWN platform<->Leeward CC Station DOWN platform, Pearl Highlands Station DOWN platform<->Aloha Stadium Station DOWN platform



Additional Staff Requirements			
Station Operator(s) 1 to 2 additional staff required at Leeward CC Station DOWN platform, Pearl Highlands Station DOWN platform, Pearlridge Station DOWN platform and Aloha Stadium Station DOWN platform to assist passenge going eastbound / westbound or transferring among buses/trains			

Staff Action	taff Action		
Engineering & Fault Controller	Coordinate with maintainer to address the blockage		
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 		
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required 		
OCC Supervisor	 Request additional workforce for Leeward CC Station, Pearl Highlands Station, Pearlridge Station and Aloha Stadium Station Arrange the bus bridge service with service provider 		
Information Controller	 Inform all stations about the new terminuses Inform Pearl Highlands Station and Leeward CC Station the bus access points 		
Station Operator(s) at (Pearlridge, Aloha Stadium) Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 		
Station Operator(s) at Pearl Highlands Station and Leeward CC Station	 Inform passengers to use the DOWN platform Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 		

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 32 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 33 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 28	This plan handles 2 single-line blockages: at West Loch Station, and at West Oahu Station	
Terminus:	East Kapolei Station UP platform <->, Hoopili Station DOWN platform, and Hoopili Station UP platform<->Aloha	
	Stadium Station UP platform	



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at West Oahu Station UP platform and West Loch Station UP platform to assist	
	passengers going eastbound / westbound	

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required
OCC Supervisor	Request additional workforce for West Oahu Station and West Loch Station
Information Controller	Inform all stations about the new terminuses
Station Operator(s) at (East Kapolei, West Oahu, West Loch) Station	 Inform passengers to use the UP platform Assist passenger, monitor passenger flow, and prepare for crowd control
Station Operator(s) at Hoopili Station	 Inform passengers to use the UP platform for trains to Aloha Stadium Station Inform passengers to use the DOWN platform for trains to East Kapolei Station Assist passenger, monitor passenger flow, and prepare for crowd control


Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 34 of 35

CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) WORK INSTRUCTION

HITACHI

@Hitachi Rail Honolulu JV

Plan No. 29	This plan handles a single-line blockage from Waipahu Transit Center Station to Leeward CC Station	
Terminus: East Kapolei Station DOWN platform (default) and Aloha Stadium Station UP platform (default)		



Additional Staff Requirements		
Station Operator(s)	1 to 2 additional staff required at both Waipahu Transit Center Station DOWN platform and Leeward CC	
	Station DOWN platform to assist passengers going eastbound / westbound	

Staff Action	
Engineering & Fault Controller	Coordinate with maintainer to address the blockage
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line
Train Controller	 Set short turn back operation defined for this plan Set single line operation defined for this plan - hold trains at Pearl Highlands Station UP platform and at West Loch Station DOWN platform before releasing them across Remove excessive trains if required
OCC Supervisor	Request additional workforce for Waipahu Transit Center Station and Leeward CC Station
Information Controller	Inform Station Operators at Waipahu Transit Center Station and Leeward CC Station about the use of the DOWN platform only
Station Operator(s) at Waipahu Transit Center Station and Leeward CC Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan) Work Instruction.01	Effective Date:	
File Name	HNL-09421.01.00-0-Contingency Plan (Alternate Service Plan) Work Instruction	Rev No. 01	Page 35 of 35