Work Instruction - Operations

AFC FAILURES WORK INSTRUCTION



Work description: The purpose of this document is to describe actions necessary to manage Automatic Fare Collection (AFC) failures.

This document is applicable for the Operation and Maintenance Services on the Honolulu Rail Transit Project (HRTP).

Scope: Actions to be taken in case of an AFC Failure

References: HNL-09504 Crowd Management Work Instruction, HNL-09527 Fault Reporting Process Work Instruction

PPE and precautions	Competencies or qualifications	Licenses or permits required
Nil	Station Operator	Nil
Tools and equipment required		



"A" Board

Warning

Crowding may occur at the AFC Gates in the event of a failure. Stations Operators are to manage Crowds in line with HNL-09504 Crowd Management Work Instruction

AFC Failure The AFC system consists of ticket vending machines and gates at the entrance of paid areas of each station, allowing the customers provided with the ticket to access the HRTP system. AFC gates are an efficient and effective way of managing fare collection through the station environment. From time to time the AFC gates may fail to operate correctly and action needs to take immediately to ensure revenue protection along with smooth passenger operations and movement through the station. The AFC Gates are continuously monitored through the central SCADA and the Engineering & Fault Controller

AFC Failure Station Operator The Station Operator must: Monitor the AFC system to ensure it is working as designed Report any Failures to the Engineering and Faults Controller in the OCC Apply an "A" Board indicating that the Gate or Machine is not in service Monitor Crowds around the affected areas and implement crowd control if necessary, in line with HNL-09504 Crowd Management Work Instruction **Engineering & Fault** Once advised of the Faults or Failure, the Engineering and Faults Controller must: Controller Record the Failure and open an MMIS notification in line with HNL-09527 Fault Reporting Process Work Instruction Inform the OCC Supervisor Close the MMIS notification upon OCC authorization and receipt of the repair report OCC Supervisor The OCC Supervisor must: Inform the City about the fault and co-ordinate for the repair with the City designated point of contact Get the repair report from the City Designated point of contact Instruct the Engineering & Fault Controller to close the MMIS notification once the report is available Instruct Station Operator to remove the "A" board when the repair is complete



Note

If all gates have failed staff are to make arrangements for passengers to enter the station through open gate arrays

The City	The City or designated point of contact shall:	
	Coordinate with OCC for the repair	
	Make sure the repair is performed	
	Provide the repair report to the OCC Supervisor when the work is complete	

Additional controls	
Train Operators may be deployed on request to assist in the management of crowds	

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09407 AFC Failures Work Instruction.01	Effective Date:	
File Name	HNL-09407.01.00-0-AFC Failures Work Instruction	Rev No. 01	Page 1 of 1