Work Instruction - Operations

TWC FAILURE



Work description: This work instruction describes the handling of TWC failures.

Scope: This work instruction is written specifically for the OCC operating staff of Honolulu Rail Transit.

References: HNL-09510 Minimum Operating Condition Work Instruction

PPE and precautions

Competencies or qualifications

Nil

OCC Supervisor, Train Controller, Information Controller, Engineering and Fault Controller

Tools and equipment required

Nli

| TWC Failures | |
|-------------------------------------|---|
| Train Controller | You must: route the train manually to the next station if the train fails to receive DID/performance data |
| | follow & monitor this train for the next 2 stations to see if manual routing needs to be continued (if there is a total TWC antennas failures) |
| | monitor this platform to see if the if the TWC communication failure affects every train that berthed (if there is a TWC loop failure) |
| | inform the Engineering and Fault Controller of the failure and your findings (train/platform) |
| | inform the OCC Supervisor of the failure and your findings (train/platform) on instructions from the OCC Supervisor to remove the train from service, take the train off service following HNL-09510 Minimum Operating Condition Work Instruction arrange a safe path for the maintainer to access the track for inspection and back to the station if required |
| | log the event in the Train Controller Log |
| Engineering and Fault Controller | You must: • inform the maintainer to arrange maintenance intervention in accordance to the OCC Supervisor decision |

Approved By: Director, Operations and Maintenance Department Manager Manager, HSE (Operations and Maintenance) Signature: Date:

| Document Code | HNL-09428 - TWC Failure | Effective Date: | |
|---------------|-------------------------|-----------------|-------------|
| File Name | -e | Rev No. | Page 1 of 2 |

Work Instruction - Operations

TWC FAILURE



| OCC Supervisor | You must: |
|----------------|--|
| | assess the findings to see if it is a TWC antennas (onboard) problems or a TWC loop (wayside) problem |
| | • if it is a TWC antennas fault, take the train off service in accordance to the HNL-09510 Minimum Operating Condition Work Instruction |
| | if it is a TWC loop fault, see if the maintainer requires track access to examine the TWC loop, however, any repair will only be allowed during Non-Revenue Service Hours instruct the Information Controller to make regular public announcements on service delays to trains and stations |
| | log the event in the OCC Supervisor Daily Report |
| Information | You must, on instructions from the OCC Supervisor: |
| Controller | make public broadcast announcements on service delays to trains and stations |
| | make regular announcements to update trains and stations affected |
| | log the event in the Information Controller Log |

| Approved By: | ☐ Director, Operations and Maintenance | ☐ Department Manager | ☐ Manager, HSE (Operations and Maintenance) |
|--------------|--|----------------------|---|
| Signature: | | | |
| Date: | | | |

| Document Code | HNL-09428 - TWC Failure | Effective Date: | |
|---------------|-------------------------|-----------------|-------------|
| File Name | -e | Rev No. | Page 2 of 2 |