Work Instruction - Operations

BUS REPLACEMENT SERVICE





Warning

Loud Hailer, Crowd Control Barriers

Passengers may be agitated when advised that busses have replaced trains. Remember to employ conflict resolution skills and provide as much information as possible to passengers during this time.

Bus Replacemen t Service

Crowd control barriers will ensure that passengers are properly positioned to join the bus services.







Note

When bus replacement service is to be introduced, OCC will inform all stations about the arrangement.

Bus Replacement When train services for a section of the line are suspended, bus replacement service will be requested by OCC Supervisor

© P			
Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09568 - Bus Replacement Service	Effective Date:	
File Name	-e	Rev No.	Page 1 of 2

Work Instruction - Operations

BUS REPLACEMENT SERVICE



Station	Station Attendants will:	
Attendant	Facilitate passengers boarding the buses	
	Passengers must be informed about the expected time of arrival of the first bus, the	
	pick-up points and the stations that will be served by the buses	
	Staff must announce bus destinations when they arrive	
	• Temporary notices/signs must be displayed to guide passengers to the pick-up points	
	• The notices/signs must also indicate the names of stations which the buses will serve	
	Additional Staff such as Train Attendants will be deployed by the Station Attendant to	
	provide guidance to prevent passengers boarding the "wrong" bus	
	Station Attendants will continually monitor and supervise the boarding and crowd	
	management and call for and deploy more staff to assist if required	

Specia		
Arrangements		
for	Airport	
Passengers		

If replacement bus services are not adequate or timely enough for airport-bound passengers, Station Attendant must contact the OCC Supervisor. The OCC Supervisor will arrange taxis to proceed to the stations affected by the service disruption. Station Attendants will give priority to the affected passengers who need to rush to the airport for boarding and maximize occupancy of the taxi's seating capacity.

Additional controls

Staff should call for the assistance of City Security Personnel and or Police to assist in crowd management if required

⊌ F			
Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09568 - Bus Replacement Service	Effective Date:	
File Name	-e	Rev No.	Page 2 of 2