
Work Instruction - Operations CONTINGENCY PLAN (ALTERNATE SERVICE PLAN) BHITACHI BHITACHI BHITACHI

Plan No. 20	This plan handles a double-line blockage at Leeward CC Station and a single-line blockage from Pearl Highlands Station to Aloha Stadium Station
Terminus:	East Kapolei Station DOWN platform (default)<->Waipahu Transit Center Station DOWN platform, Pearl Highlands Station DOWN platform<->Aloha Stadium Station DOWN platform



Additional Staff Requirements				
Station Operator(s) 1 to 2 additional staff required at Waipahu Transit Center Station DOWN platform and Pe				
	Station DOWN platform to assist passengers transferring among buses/trains			

Staff Action			
Engineering & Fault Controller	Coordinate with maintainer to address the blockage		
Maintainer	 Send maintenance unit to the scene to address the blockage De-energize and isolate the blocked area from the running line 		
Train Controller	Set short turn back operation defined for this plan Set shuttle operation defined for this plan Remove excessive trains if required		
OCC Supervisor	 Request additional workforce for Waipahu Transit Center Station and Pearl Highlands Station Arrange the bus bridge service with service provider 		
Information Controller	 Inform all stations about the new terminuses Inform Waipahu Transit Center Station, Leeward CC Station and Pearl Highlands Station the bus access points 		
Station Operator(s) at (Waipahu Transit Center, Pearl Highlands, Pearlridge, Aloha Stadium) Station	 Inform passengers to use the DOWN platform Assist passenger, monitor passenger flow, and prepare for crowd control 		
Station Operator(s) at Leeward CC Station and Pearl Highlands	 Coordinate replacement bus services Assist passenger, monitor passenger flow, and prepare for crowd control 		

End of No. 20

Document Code	HNL-09421 Contingency Plan (Alternate Service Plan).01	Effective Date:	
File Name	HNL-09421.00.00-1-Contingency Plan (Alternate Service Plan)	Rev No. 01	Page 22 of 32