Work Instruction - Operations

ATS FAILURE WORK INSTRUCTION



Hitachi Rail Honolulu JV

Work description: This work instruction describes the handling of ATS server failures.						
Scope: This work instruction is written specifically for the OCC operating staff of Honolulu Rail Transit.						
References: Nil						
PPE and precautions	Competencies or qualifications	Licenses or permits required				
Nil	OCC Supervisor, Train Controller, Yard Controller, Information Controller, Engineering & Fault Controller, Station Operator, Traffic Controller, Yard Controller	Nil				
Tools and equipment required						
Nil						
_	_	_				

1. Failure of a single ATS server in the OCC					
Train Controller	You must:				
	1) Inform the Engineering & Fault Controller of the failure				
	2) Inform the OCC Supervisor of the failure				
Engineering & Fault Controller	You must:				
Controller	1) On receiving a failure report, record/register the fault to the MMIS				
	2) Inform the maintainer to arrange immediate maintenance intervention				
	3) Keep an eye on the ATS repair progress				
	4) Inform the OCC Supervisor, Train Controllers, and the Yard Controller about the latest ATS repair progress				
OCC Supervisor	You must:				
	Follow the fault rectifying progress closely				

2. Failure of a pair of redundant ATS servers in the OCC Train Controller You must: Inform the Engineering & Fault Controller of the failure 2) Inform the OCC Supervisor of the failure On instructions from the OCC Supervisor to evacuate the OCC. Follow the OCC Evacuation Work Instruction for departing from / returning to the OCC **Engineering & Fault** You must: Controller On receiving a failure report, record/register the fault to the MMIS 2) Inform the maintainer to arrange immediate maintenance intervention Inform the OCC Supervisor of the failure On instructions from the OCC Supervisor to evacuate the OCC, follow the OCC Evacuation Work Instruction for departing from / returning to the OCC OCC Supervisor You must: Find out the extent of failures and the estimated recovery time from the Engineering & Fault Controller Dispatch the Yard Controller to the Yard Control Bungalow (YCB) immediately Instruct the OCC operating staff to evacuate the OCC, follow the OCC Evacuation Work Instruction for departing from / returning to the OCC

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09410 ATS Failure Work Instruction.01	Effective Date:	
File Name	HNL-09410.01.00-0-ATS Failure Work Instruction	Rev No. 01	Page 1 of 2

Work Instruction - Operations

HITACHI

ATS FAILURE WORK INSTRUCTION

Hitachi Rail Honolulu JV

Information Controller

You must:

On instructions from the OCC Supervisor to evacuate the OCC, follow the OCC Evacuation Work Instruction for departing from / returning to the OCC

Yard Controller

You must

- 1) Stop all train movements in the yard immediately
- 2) Log off from Workstations on your desk
- 3) Bring your handheld radio, important phone numbers and controller logbooks with you
- 4) Leave OCC and proceed to the YCB
- On instructions from the OCC Supervisor to return to the OCC:
 Stop all train movements in the Yard immediately
 Relinquish controls in the Yard and return to the OCC to resume duties
- 6) Log the event in the Yard Controller Log