Work Instruction - Operations

CONTRACTOR AND VISITOR MANAGEMENT IN OCC WORK INSTRUCTION



Work description: This OCC Work Instruction is about the access to OCC premises for work activities including authorized visitor access					
Scope: This Work Instruction is written specifically for OCC operating staff.					
References: N/A					
PPE and precautions	Competencies or qualifications	Licenses or permits required			
Nil	OCC Supervisor	Nil			
Tools and equipment required					
Nil					



Warning

Contractors may do works that cause hazards and risks at the OCC. Make sure the contractors are putting proper control to minimize hazard and risks to customers and staff.

Contractor's Pass	A Contractor's pass is issued to all verified Contractors in the OCC and must be worn	Issue Date / Time Contractor's Name Contractor's Company	Tel. No. Tick the type of such to be carried out of the state of the
	at all times visible to others.	CONTRACTOR'S PASS	A Work to be carried out when the Mark and Safety All work to be carried out when the Hall and Safety and Work Act 1974 and Safety a
		Specific Details of Work to be carried out and any Hazards involved in doing so. Specific Permits-to-Work may be required.	THER & LUBEDOBADY On heating the First Airm leave the building by the nearest free exit and proceed to the Assembly Point. • ACCIDENT (HAURIES Beyond a Cacidente, injuries, near-misses &
		ADDITIONAL PERMIT MAY BE REQUIRED BEFORE WORK COMMENCES	Illnesses to your host • COSHH This site is subject to COSHH regulations. • PERSONAL PROTECTIVE EQUIPMENT ALWAYS wear the PPE grovided. Inform safety contact or employer if PPE is damaged or unsuitable.
		Authorised signatory for permission to start work Time	SMOKING SMOKING IS NOT ALLOWED IN ANY AREA. Please return your Authorisation to Work and your Contractor's Pass to point of issue on leaving and sign out. Thank you.

Contractor Sign In

On arrival at the OCC, contractors must report to the OCC Supervisor before doing any work.

The OCC Supervisor will require the Contractor to:

- Present proof of their identity
- Sign in the Contractors and Visitors Log
- Provide evidence of work order or permit allowing the work to be carried out

The OCC Supervisor must issue a Contractor's Pass to the person in charge and the other contractors on site.

All Contractors must sign in the Contractors and Visitors Log.



Note

Contractors have safety responsibilities to Honolulu Rail Transit and their staff. The OCC Supervisor must make sure that they have got prior approval for the work to be carried out in the OCC.

Contractor Sign Out

Once the works are completed, the Contractor must report to the OCC Supervisor.

The OCC Supervisor must:

- Make sure the OCC is fit for operation and free of any hazards and risks
- Make sure passes issued are returned

All Contractors must sign out the Contractors and Visitors Log



Note

If the Contractor has not completed the work and needs to come back later, the contractor must make sure the area is well partitioned and guarded so that it is safe to operate the OCC under these circumstances, before leaving the OCC.

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09542 Contractor and Visitor Management in OCC Work Instruction.01	Effective Date:	
File Name	HNL-09542.01.00-0-Contractor and Visitor Management in OCC Work Instruction	Rev No. 01	Page 1 of 2

Work Instruction - Operations

CONTRACTOR AND VISITOR MANAGEMENT IN OCC WORK INSTRUCTION



Visitors Sign In and Out

On arrival at the OCC, visitors must report to the OCC Supervisor.

The viewing room is the preferred way of visiting the OCC.

The OCC Supervisor will:

- Have visitors identifying themselves and ask for the nature of their visit
- Make sure that the visit is authorized by the Management
- Provide a Safety Induction Briefing
- Instruct the Visitor/s to sign the Contractors and Visitors Log
- Issue the Visitor/s with a Visitors pass
- Accompany the Visitor/s if required during the duration of their visit
- Sign visitors out in the Contractors and Visitors Log

OCC Visitors Pass must be worn at all times by all visitors.



All Visitors must sign out the Contractors and Visitors Log

Additional controls

For large numbers of visitors, additional staff may be required for managing the event.