## **Work Instruction - Operations**

## TWC FAILURE WORK INSTRUCTION



Hitachi Rail Honolulu JV

Work description: This work instruction describes the handling of TWC failures.						
Scope: This work instruction is written specifically for the OCC operating staff of Honolulu Rail Transit.						
References: HNL-09510 Minimum Operating Conditions Work Instruction						
PPE and precautions	Competencies or qualifications	Licenses or permits required				
Nil	OCC Supervisor, Train Controller, Information Controller, Engineering & Fault Controller	Nil				
Tools and equipment required						
Nil						

TWC Failures				
Train Controller	You must:			
	<ol> <li>Route the train manually to the next station if the train fails to receive DID/performance data</li> <li>Follow &amp; monitor this train for the next 2 stations to see if manual routing needs to be continued (if there is a total TWC antennas failures)</li> <li>Monitor this platform to see if the if the TWC communication failure affects every train that berthed (if there is a TWC loop failure)</li> <li>Inform the Engineering &amp; Fault Controller of the failure and your findings (train/platform)</li> <li>Inform the OCC Supervisor of the failure and your findings (train/platform)</li> <li>On instructions from the OCC Supervisor to remove the train from service, take the train off service following HNL-09510 Minimum Operating Conditions Work Instruction</li> <li>Arrange a safe path for the maintainer to access the track for inspection and back to the station if required</li> <li>Log the event in the Train Controller Log</li> </ol>			
Engineering & Fault Controller	You must:  1) Inform the maintainer to arrange maintenance intervention in accordance to the OCC Supervisor decision			
OCC Supervisor	You must:			
	<ol> <li>Assess the findings to see if it is a TWC antennas (onboard) problems or a TWC loop (wayside) problem</li> <li>If it is a TWC antennas fault, take the train off service in accordance to the HNL-09510 Minimum Operating Conditions Work Instruction</li> <li>If it is a TWC loop fault, see if the maintainer requires track access to examine the TWC loop, however, any repair will only be allowed during Non-Revenue Service Hours</li> <li>Instruct the Information Controller to make regular public announcements on service delays to trains and stations</li> <li>Log the event in the OCC Supervisor Daily Report</li> </ol>			
Information	You must, on instructions from the OCC Supervisor:			
Controller	<ol> <li>Make public broadcast announcements on service delays to trains and stations</li> <li>Make regular announcements to update trains and stations affected</li> <li>Log the event in the Information Controller Log</li> </ol>			

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	HNL-09428 TWC Failure Work Instruction.01	Effective Date:	
File Name	HNL-09428.01.00-0-TWC Failure Work Instruction	Rev No. 01	Page 1 of 1