Work Instruction - Operations

HANDLING TELECOMMUNICATION FAILURES WORK INSTRUCTION

HITACHI

Hitachi Rail Honolulu JV

Work description: This work instruction describes the handling of the Telecommunication failures.						
Scope: This work instruction is written specifically for the OCC operating staff of Honolulu Rail Transit.						
References: HNL-09552 Handling ICCS Workstation Failures Work Instruction, HNL-09434 Handling CCTV Failure Work Instruction, HNL-						
09553 Handling Loss of Radio Communications Work Instruction, HNL-09417 Handling PIS Failures Work Instruction, HNL-09325 OCC						
Evacuation Work Instruction						
PPE and precautions	Competencies or qualifications	Licenses or permits required				
Nil	OCC Supervisor, Train Controller, Yard	Nil				
	Controller, Information Controller,					
	Engineering & Fault Controller					
Tools and equipment required						
Nil						

1. Handling Teleco	mmunication Failures			
Information	You must:			
Controller	 Inform the Engineering & Fault Controller of the failure Inform the OCC Supervisor of the failure 			
Engineering & Fault	You must:			
Controller	Inform the maintainer to arrange immediate maintenance intervention			
	 See whether an Emergency Track Possession is required for the maintainer(s) to carry out emergency repair; coordinate with the Train Controller to set up an Emergency Track Possession 			
	3) Keep an eye on the telecommunication repair progress			
	4) Inform the OCC Supervisor about the latest telecommunication repair progress			
Yard Controller	You must:			
	1) Inform the Engineering & Fault Controller of the failure			
	2) Inform the OCC Supervisor of the failure			
Train Controller	You must:			
	1) Inform the Engineering & Fault Controller of the failure			
	2) Inform the OCC Supervisor of the failure			
OCC Supervisor	You must:			
	1) Inform the Engineering & Fault Controller of the failure			
	2) Follow the fault rectifying progress closely			
	Depending on the nature of the failure, you may refer to any one or a combination of:			
	HNL-09552 Handling ICCS Workstation Failures Work Instruction			
	HNL-09434 CCTV Failure Work Instruction			
	HNL-09553 Handling Loss of Radio Communications Work Instruction			
	HNL-09417 Handling PIS Failures Work Instruction			

Handling Telecommunication Failures involving the failure of all ICCS Servers HNL-09552 Handling ICCS Workstation Failures Work Instruction; or HNL-09325 OCC Evacuation Work Instruction

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
B-4			
Date:			

Document Code	HNL-09551 Handling Telecommunication Failures Work Instruction.01	Effective Date:	
File Name	HNL-09551.01.00-0-Handling Telecommunication Failures Work Instruction	Rev No. 01	Page 1 of 1