PSGS BROKEN GLASS



Work description: The purpose of this document is to describe the actions necessary in case of PSGS Broken Glass. This document is applicable for the Operation and Maintenance Services on the Honolulu Rail Transit Project (HRTP).

Scope: Response activities required in the event of Broken Glass on the Platform Screen Gates

References: HNL-09517 Station Closure, HNL- 09320 Unauthorized Persons Trackside

PPE and precautions	Competencies or qualifications	Licenses or permits required
Removal of Sharp Objects	Train Controller, Information Controller, Train Attendant, Station Attendant	

Tools and equipment required

Demarcation Tape, Barriers

PSGS Broken Glass

The OCC can get the notice of the PSGS broken glass through:

Radio communication of a Station Attendant or any other O&M Personnel on the line Communication through ECP of a passenger or any other O&M Personnel on the line Through CCTV

OCC Supervisor

The OCC Supervisor must:

Request the station closure in case of any hazard for the passenger service

Request to the Train Controller to set the platform out of service and skip the station if needed

Record any event on the OCC Log

Train Controller

The Train Controller must:

Implement the procedure HNL-09517 Station Closure, if requested by the OCC Supervisor Set the platform out of service and skip the station if requested by the OCC Supervisor Dispatch two Train Attendants or Station Attendants to the affected platform Inhibit the affected gate through the ATC system

Request the Train Attendants or Station Attendants to supervise the area and to delimit the area with appropriate equipment (e.g. with barriers)

Request the Train Attendants or Station Attendants to isolate the interested PSGS

If the Train Attendants or Station Attendants confirm that there is not any hazard for passenger service:

- Ensure that trains entering the platform arrive at a lower speed modifying the braking profile at platform
- Re-start passenger service

In case of any passenger accessing the line through the PSGS broken glass:

- Apply an emergency station stop via ATC system
- Be ready to power off the line
- Implement all the actions to deal with passenger on the line (see procedure HNL-09320 Unauthorized Persons Trackside)

Remove any limitation to the interested PSGS once the glass has been fixed

Document Code	HNL-09432 - PSGS Broken Glass	Revision
External Code		Ext. Revision
File Name	-00.00-0-	Page 1 of 2

PSGS BROKEN GLASS



Information
Controller

The Information Controller must:

Continuously monitor the area through CCTV

In case of any passenger accessing the line through the interested PSGS, immediately communicate it to the OCC Supervisor

Make announcement in the interested platform through PA/PID, requesting passengers to keep distance from the PSGS broken glass

Make announcement in the stopped trains through PA/PID, to inform passengers about the situation

Engineering & Faults Controller

The Engineering & Faults Controller must:

- In case of any passenger on the line, immediately power off the line
- Ask for the intervention of the Maintenance team
- Inform the OCC Operators once the maintenance on the affected PSGS has been completed

Document Code	HNL-09432 - PSGS Broken Glass	Revision
External Code		Ext. Revision
File Name	-00.00-0-	Page 2 of 2