Work Instruction - Operations

AFC FAILURES



Work description: The purpose of this document is to describe actions necessary to manage AFC failures. This document is applicable for the Operation and Maintenance Services on the Honolulu Rail Transit Project (HRTP).

Scope: Actions to be taken in case of an AFC Failure

References: HNL-09504 Crowd Management, HNL-09668 Fault Reporting and Response at Stations

PPE and precautions	Competencies or qualifications	Licenses or permits required		
Nil	Station Attendant	Nil		
Tools and equipment required	d			
"A" Board				



Warning

Crowding may occur at the AFC Gates in the event of a failure. Stations Attendants are to manage Crowds in line with HNL-09504 Crowd Management

AFC Failure	The Automatic Fare Collection system consists of ticket vending machines and gates at the	
	entrance of paid areas of each station, allowing the customers provided with the ticket to	
	access the HRTP system. AFC gates are an efficient and effective way of managing fare	
	collection through the station environment. From time to time the AFC gates may fail to	
	operate correctly and action needs to taken immediately to ensure revenue protection	
	along with smooth passenger operations and movement through the station. The AFC	
	Gates are continuously monitored through the central SCADA and the Engineering and	
	Faults Controller	

AFC Failure Station The Station Attendant must: Attendant Monitor the AFC system to ensure it is working as designed; Report any Failures to the Engineering and Faults Controller in the OCC; Apply an "A" Board indicating that the Gate or Machine is not in service; Monitor Crowds around the affected areas and implement crowd control if necessary, in line with HNL-09504 Crowd Management Engineering Once advised of the Faults or Failure, the Engineering and Faults Controller must: Fault Controller Record the Failure and open an MMIS notification in line with HNL-0927 Fault **Reporting Process** Inform the OCC Supervisor Close the MMIS notification upon OCC authorization and receipt of the repair report

Document Code	HNL-09407 - AFC Failures	Revision
External Code		Ext. Revision
File Name	-00.00-0-	Page 1 of 2

Work Instruction - Operations

AFC FAILURES



OCC Supervisor

The OCC Supervisor must:

- Inform the City about the fault and co-ordinate for the repair with the City designated point of contact;
- Get the repair report from the City Designated point of contact;
- Instruct the Engineering and Faults Controller to close the MMIS notification once the report is available.
- Instruct Station Attendant to remove the "A" board when the repair is complete.



Note

If all gates have failed staff are to make arrangements for passengers to enter the station through open gate arrays

The City	The City or designated point of contact shall:	
	Coordinate with OCC for the repair;	
	Make sure the repair is performed;	
	Provide the repair report to the OCC supervisor when the work is complete	

Additional controls

Train Attendants may be deployed on request to assist in the management of crowds

Document Code	HNL-09407 - AFC Failures	Revision
External Code		Ext. Revision
File Name	-00.00-0-	Page 2 of 2