Work Instruction - Operations

AFC FAILURES



Work description: The purpose of this document is to describe actions necessary to manage AFC failures.

This document is applicable for the Operation and Maintenance Services on the Honolulu Rail Transit Project (HRTP).

Scope: Actions to be taken in case of an AFC Failure

References: HNL-09504 Crowd Management, HNL-09668 Fault Reporting and Response at Stations, HNL-09527 Fault Reporting Process

<u> </u>				
PPE and precautions	Competencies or qualifications	Licenses or permits required		
Nil	Station Operator	Nil		
Tools and equipment required				
"A" Board				



Warning

Crowding may occur at the AFC Gates in the event of a failure. Stations Operators are to manage Crowds in line with HNL-09504 Crowd Management

AFC Failure

The Automatic Fare Collection system consists of ticket vending machines and gates at the entrance of paid areas of each station, allowing the customers provided with the ticket to access the HRTP system. AFC gates are an efficient and effective way of managing fare collection through the station environment. From time to time the AFC gates may fail to operate correctly and action needs to taken immediately to ensure revenue protection along with smooth passenger operations and movement through the station. The AFC Gates are continuously monitored through the central SCADA and the Engineering and Faults Controller

AFC Failure	
Station Operator	The Station Operator must:
	Monitor the AFC system to ensure it is working as designed;
	Report any Failures to the Engineering and Faults Controller in the OCC;
	Apply an "A" Board indicating that the Gate or Machine is not in service;
	 Monitor Crowds around the affected areas and implement crowd control if necessary, in line with HNL-09504 Crowd Management
Engineering & Fault Controller	Once advised of the Faults or Failure, the Engineering and Faults Controller must:
	 Record the Failure and open an MMIS notification in line with HNL-09527 Fault Reporting Process Inform the OCC Supervisor
	Close the MMIS notification upon OCC authorization and receipt of the repair report
OCC Supervisor	The OCC Supervisor must:
	Inform the City about the fault and co-ordinate for the repair with the City designated point of contact;
	Get the repair report from the City Designated point of contact;
	Instruct the Engineering and Faults Controller to close the MMIS notification once the report is available.
	Instruct Station Operator to remove the "A" board when the repair is complete.



Note

If all gates have failed staff are to make arrangements for passengers to enter the station through open gate arrays

The City	The City or designated point of contact shall:	
	Coordinate with OCC for the repair;	
	Make sure the repair is performed;	
	Provide the repair report to the OCC supervisor when the work is complete	

Additional controls
Train Operators may be deployed on request to assist in the management of crowds

Approved By:	☐ Director, Operations and Maintenance	☐ Department Manager	☐ Manager, HSE (Operations and Maintenance)
Signature:			
Date:			

Document Code	YYY.YYY. AFC Failures.00	Effective Date:	
File Name	HNL-09407.00.00-1-AFC Failures	Rev No. 00	Page 1 of 1