Field Notes (Intrastate)

- OVB CL 5[^] Overbend
- **SAG** CL 8[^] Sag
- **PIL** PI 10^40'42" Lt.
- **PIR** PI 24^15'22" Rt.
 - Note: These must be entered in this EXACT format, if you only have 10^24' listed on the alignment sheet, make sure to add the 00" at the end. Format = XX^00'00" Rt. or Lt.
- STQ Ahd.=XXX Bk. ***STATION EQUATION***
 - Note: The station equation field note should be entered on the ahead (existing) station series. Enter as noted above with 5 spaces BEFORE AND AFTER stars and only 3 stars.
- **COL** Leave Lake Co., Enter Polk Co.
- RL Leave R-15-E, Enter R-16-E
- TWP Leave T-8-S, Enter T-7-S
- SL Leave Sec. 32, Enter Sec. 33
- STL Leave Texas, Enter Louisiana

Construction Notes

- At TEE/TAPS: Begin Line 1015 Region Lateral or End of line depending on Flow @ 30+55 on Line 3016(MAINLINE).
- Begin WO- End WO: On Mainline for
 - Replacements
 - Begin Replacement (WBS or AFE) (Number)
 - End Replacement (WBS or AFE) (Number)
 - Recoats
 - Begin Recoat (WBS or AFE) (Number)
 - End Recoat (WBS or AFE) (Number)
 - o Re-routes
 - Begin Re-Route (WBS or AFE) (Number)
 - End Re-Route (WBS or AFE) (Number)
 - Sleeves
 - Begin Sleeve (WBS or AFE) (Number)
 - End Sleeve (WBS or AFE) (Number)