
(a)
1
0
Normalized depth (a_p/a_{max})
Initial surface
Roughing profile
(b)
1
0
Normalized depth (a_p/a_{max})
Segmented finishing levels
Machining front (Mode 2)
Target finishing depth
0
1
Normalized length (x/L)