
Sensor 0 response
Sensor displacement [µm]
Full model
Internal model
Cutter-point response
Cutter displacement [µm]
Full model
Internal model
Phase-cell force comparison in physical time
Axial force [N]
Exact reduced force map
Internal force approximation (cellwise ZOH)
Full plant phase average
Applied spindle-speed command
constant baseline
speed staircase
speed sinusoid
depth staircase
depth sinusoid
mixed excitation
$\omega_k$ (ZOH)
admissible bounds
$\omega$ [rad/s]
Applied axial-depth command
$a_p$ [mm]
$a_{p,k}$ (ZOH)
admissible bounds
Physical time [s]