

Interfacing. * (j3,j4) SX1276

Calibration.

* (j1) RTC * (j1) EEPROM

- Sensors.
 * (j6) Thermal (ambient/ground)
 * Humidity
- * (j5) Barometer
- * Rain * Dew
- * Wind
- * Light
- * Shock
- * Smoke * (j2 ADC) Solar Voltage

Diagnostic.

- * Buttons * LED
- * Buzzer
- * LCD
- * (piezo : tap I/O)