

Production Lines — Reference Map

Production Lines — Reference Map

- 1. Purpose
- 2. Lines at a glance
- 3. Canonical station ordering
- 4. Cross-line dependencies
- 5. Telemetry hierarchy
- 6. References

Production Lines — Reference Map

Audience: All personas. Used by the agent to orient any answer about “which line”, “which station”, or “which bottleneck”.
Applies to: All 5 production lines (30 stations total).

1. Purpose

This is the canonical map of the factory. Every other document — station SOPs, the maintenance overview, the OEE escalation matrix — refers back to this document for **line topology, part flow, canonical station ordering, and bottleneck identification**.

2. Lines at a glance

Line	Domain	Stations	Bottleneck	Target OEE
Line-A	Precision Machining	5	CMM-Inspection (60 s cycle)	78 %
Line-B	Sheet Metal Forming	4	Hydraulic-Press (1.5 % fault rate)	72 %
Line-C	Welding & Assembly	6	Welding-Robot + Leak-Test	75 %
Line-D	Surface Treatment	7	Curing-Oven (90 s cycle)	70 %
Line-E	Electronics Assembly	8	Wave-Solder (0.7 % fault rate)	73 %

3. Canonical station ordering

The simulator processes parts in strict left-to-right order on each line. Buffer capacity between adjacent stations is **5 parts**.

Line-A · Precision Machining

01 CNC-Lathe → 02 CNC-Mill → 03 Surface-Grinder → 04 Deburring-Station → 05 CMM-Inspection

- Part type produced: precision machined components.
- Bottleneck: **CMM-Inspection** at 60 s ideal cycle. Any outage here starves nothing downstream (final station) but **blocks** Deburring.
- See SOPs: Line-A_01_CNC-Lathe_SOP.pdf through Line-A_05_CMM-Inspection_Calibration.pdf.

Line-B · Sheet Metal Forming

01 Blanking-Press → 02 Hydraulic-Press → 03 Trimming-Station → 04 Quality-Inspection

- Part type produced: sheet metal panels.
- Bottleneck: **Hydraulic-Press** by fault-rate (1.5 % — the highest on this line). Watch closely per Line-B_02_Hydraulic-Press_Maintenance_SOP.pdf.
- See SOPs: Line-B_01_Blancking-Press_SOP.pdf through Line-B_04_Quality-Inspection_SOP.pdf.

Line-C · Welding & Assembly

01 Component-Loader → 02 Welding-Robot → 03 Weld-Inspection → 04 Fastening-Station → 05 Assembly-Robot → 06 Leak-Test

- Part type produced: welded sub-assemblies.
- Bottleneck: **Welding-Robot** for performance, **Leak-Test** for quality (3 % reject target).
- See SOPs: Line-C_01_Component-Loader_SOP.pdf through Line-C_06_Leak-Test_SOP.pdf.

Line-D · Surface Treatment

01 Surface-Prep → 02 Chemical-Wash → 03 Primer-Application → 04 Paint-Booth → 05 Curing-Oven → 06 Coating-Inspection → 07 Final-Packaging

- Part type produced: coated parts ready for ship.
- Bottleneck: **Curing-Oven** at 90 s ideal cycle. **Curing-Oven outage cascades within 1 cycle** — it starves Coating-Inspection and Packaging, and blocks Paint-Booth.
- Note: Curing-Oven stays > 60 °C for ~60 min after shutdown. See Line-D_05_Curing-Oven_SOP.pdf.

Line-E · Electronics Assembly

01 PCB-Loader → 02 SMT-Placement → 03 Reflow-Oven → 04 AOI-Inspection → 05 Through-Hole-Insert → 06 Wave-Solder → 07 Functional-Test → 08 Conformal-Coat

- Part type produced: electronics modules.
- Bottleneck: **Wave-Solder** by fault-rate (0.7 %). Solder pot stays molten ~3 hours after power-off. See Line-E_06_Wave-Solder_Troubleshooting.pdf.
- AOI-Inspection has a 4 % reject-rate target — the highest on this line.

4. Cross-line dependencies

The 5 lines run independently — there is no inter-line part flow in this factory. **A fault on Line-A does not affect Line-D.** However:

- **Maintenance technicians are shared** across all lines. A surge of

work orders on one line can delay response on another. See [Maintenance_Workflow_Overview.pdf](#) §4.

- **The Plant Manager dashboard** aggregates OEE across all 5 lines and is the place to detect cross-line patterns (e.g., shift-change quality dips).

5. Telemetry hierarchy

Telemetry events from the simulator carry these identifiers:

- `line_id` $\in$ { Line-A, Line-B, Line-C, Line-D, Line-E }
- `station_position` $\in$ { 01, 02, ... } — 1-indexed position on the line.
- `station_type` — e.g., CNC-Lathe. The same `station_type` can appear on different lines (e.g., Nozzle-Clog appears on Line-D Primer, Line-D Paint-Booth, Line-E SMT-Placement, and Line-E Conformal-Coat).

When the agent answers, **always disambiguate by `line_id` + `station_position`** so the user knows exactly which station is being discussed.

6. References

- All 30 per-station SOPs.
- [Maintenance_Workflow_Overview.pdf](#) — fault-type table by station.
- [OEE_Targets_and_Escalation.pdf](#) — KPI targets and escalation matrix.
- [Quality_Reject_Disposition_Policy.pdf](#) — reject-rate targets and pause thresholds by station.
- [Shift_Handover_Checklist.pdf](#) — bottleneck-station status review.