- -V1: 3.3v power supply
- -V2: 5v power supply
- -V3: 9v power supply
- -RPI: raspberry pi
- -P1: potentiometer
- -K1: push button
- -R1:  $R220\Omega$
- -R2:  $R10K\Omega$
- -R3: R10KΩ
- -S1: anemometer (windsensor)
- -S2: LDR photoresistor
- -S3: NTC thermoresistor
- -M1: unipolair stepper motor
- -IC1: PCF8574
- -IC2: MCP3008
- -IC3: ULN2003A
- -LCD: LCD display