

Analog Clock

Buttons, Pullups, and Debug




RTC

Buttons, Pullups, and Debug




Pullups




PP5V0 PP5V0 PP5V0 R11 R_0805_10K R12 R_0805_10K R_0805_10K RESET_L BUTTON_HOURS_L BUTTON_MINUTES_L SW1 SW2 Omron_B3F_SPST Omron_B3F_SPST Omron_B3F_SPST PP5V0 PP5V0 R13 R_0805_10K R15 R_0805_10K BUTTON_MATRIX_L BUTTON_MODE_L SW3 SW5 Omron_B3F_SPST Omron_B3F_SPST **Buttons**

Display and LED Matrix



Motor

Layout: Make sure to put mounting holes in correct position under 3 pin connectors.



Layout: Make sure to indicate connector polarity.

Layout: Make sure to indicate connector polarity.

Testpoints

