

#100#
100%

L11 = 450.0000

L12 = 13.0000

L19 = 22.0000

L14 = 10.0000

L13 = 14.0000

R1 = R 15.0000

L15 = 6.0000

L16 = 6.0000

L17 = 135.0000

L18 = 91.0000

L20 = 22.0000

L10 = 119.0000

