

Oxford OptistatDry BLV
D_max 20 mm, H_max 50 mm (sourced)
QD PPMS 14 T
D_max 23 mm, H_max 50 mm (sourced)
MI 6800C CFMS 9 T
D_max 30 mm, H_max 50 mm (sourced)
Montana CryoAdvance 50
D_max 53 mm, H_max 63 mm (sourced)
kiutra L-Type Rapid
D_max 55 mm, H_max 117 mm (sourced)
Bluefors LD400 (HDW)
size limits not documented
clearance (mm)
width/diameter D (mm)
height H (mm)
no clearance: limits undocumented
(markers placed at z = 0)
Lean: Requirements met
Lean: Need more information
Lean: Does not meet requirements
zero clearance (sourced limits)