Reyrolle Duobias M

It's transformer differential relay. The relay is mostly supported.

Not supported features:

- not linear high values bias characteristic
- the current implementation of the PF CT adapter block is more flexible of the real features available inside the device. For instance inside the relay the voltage level isn't available and only a numerical multiplier is present.
- Breaker failure feature