

ACTIVITY REPORT

Technical support by HRRP-Kathmandu



Name of Activity	Orientation Program		
Program Name:	Orientation program on Retrofitting to DLPIU Engineers		
Location	DCC hall, Babarmahal, Kathmandu		
Date	22 December 2019		
Organizer	DLPIU-Building, Kathmandu		
Targeted Groups	DLPIU engineers		
Number of participants	Male	Female	Total
	45	44	89
Resource Persons from HRRP	Sweata Sijapati, District Technical Coordinator		
Counterpart Coordinator	Er. Bidhya Manandhar	Contact No.	
	District Support Engineer		
Program Brief	A one-day orientation program on retrofitting to DLPIU engineers was conducted at DCC hall, Babarmahal, Kathmandu on 22 December 2019. The program was facilitated by the The major area of focus during the orientation was • Discussion on the retorting techniques and identifying its feasibility on the houses listed under retrofitting grant. • Discussion on the correction and exception measure and its effective implementation in field. • Discussion on the field issues and identifying a way forward. As per the retrofitting feasibility report collected by the retrofitting task force, the criteria for recommendation of the retrofitting was discussed in detail based on the photos collected from the field. Some of the major reason for technically unfeasibility for retrofitting identified in Kathmandu are as follows: • Damage Grade greater than 3 • Site cleared after dismantling old house • Hybrid structure (Majority are BMM + SMM) • BMM structure of more than 3 stories plus attic • Asymmetrical openings		
Lists of Session/support from HRRP	Special Observation by the HRRP Resource Person		

ACTIVITY REPORT

Technical support by HRRP-Kathmandu

Good Aspects of the Program & Area of Improvement

Good points: Engineers confusion regarding the feasibility criteria of retrofitting was cleared. As the discussion was based on typologies collected by the field engineer, the orientation was more impactful.

Points to be Improved: Due to time constrain the orientation couldn't equally focus on all the areas of retrofitting. Group work for detail discussion and understanding would have been beneficial.

PHOTOGRAPH



Group photo of the participants during the orientation program on retrofitting