

HRRP

Meeting Minutes

District HRRP Coordination Meeting - Ramechhap

Date: 15 12 2016

Time: 03:00 - 05:00 PM

Location: HRRP Office, Manthali, Ramechhap

Participants: NRA, HRRP, MEDAIR, CDS, HELVETAS/EFS, NRCS, Swisscontact/NAMDP

Agendas:

1. Welcome/Introduction
2. Overview of new 4W template
3. Cluster Approach in reconstruction from MEDAIR
4. Mason experience sharing from Bhatauli VDC
5. Donor visit update
6. Alternative resource
 - Soil and concrete block survey
 - Bamboo treatment video
7. Open discussion
 - PO's support in Inspection process
8. AOB
9. Next meeting

Key Discussion

Introduction:

The meeting took place at HRRP Office, Manthali, Ramechhap on Thursday, 15th December 2016. The formal meeting started with short introduction and was facilitated by HRRP District Coordinator with total 8 participants. The meeting was mainly focused on overview of new 4W template, mason experience sharing, cluster approach in reconstruction, alternative resources and donor visit updates.

Overview of new 4W template:

HRRP, Ramechhap IM introduced new 4W template to its PO's and provided an overview on its added components and other important changes. Similarly all partners were requested to provide detailed and ward level information of their activities.

Cluster Approach in reconstruction from MEDAIR:

A presentation on cluster approach in reconstruction was presented by MEDAIR in the HRRP platform. The presentation mainly focused on the advantages of cluster approach while rebuilding and it also provided important information on how MEDAIR is working in their project area using this approach.

Mason experience sharing from Bhatauli VDC:

Mason experience along with challenges faced by masons which were collected from former Bhatauli VDC, now Manthali municipality was shared with participants in the meeting. On the Job Training was conducted by HELVATAS and the trained masons are already working in the neighborhood using their skills. Shortage of timber, stones and water is creating difficulty to build earthquake resilient structure. The introduction of concrete banding is also creating challenges as they do not have appropriate tools and steel reinforcement skills which might lead to haphazard rebuilding.

Donor visit update:

There was a donor visit from SDC on 7th and 8th December 2016 which was briefly updated to the partners. Donor visit went very well and they were equally happy with the participation of all partners in HRRP.

Alternative resource:

Partners were provided with the information collected during the soil and block survey conducted by HRRP team in Ramechhap district. HRRP team conducted a survey which showed that there were not concrete block manufacturing industries in the surrounding and every household prepares concrete block by themselves when necessary. One household preparing soil block was found for their own rebuilding and the materials were sent for strength test and as per information provided if approved they will start commercial production.

A short video on bamboo treatment procedure and bamboo strength test was shown to the partners.

Open discussion:

An open discussion on PO's support on inspection process was discussed and PO's informed that they are ready to support the process if provided the guidelines. They will discuss and look at they own resource so that they can decide how to support the process.

Next Meeting:

Wednesday, 28th December 2016, HRRP Office, Manthali

Agenda: TBD

Meeting Participants List/Attendance Sheet

Name	Org	Phone	Email
Bikram Raj Gyawali	NRA	9843753118	bikramrajgyawali@gmail.com
Sanjay Deshar	HRRP	9841190081	dc.ramechhap@hrrpnepal.org
Sushil Kakshyapati	HRRP	9849747454	sushil@hrrpnepal.org
Santosh Magar	CDS	9849551874	cdsmagar@gmail.com
Jaya Ram Basnet	NRCS	9841653249	jaya.basnet@gmail.com
Tulasi Dahal	HELVETAS/EFS	9846022034	tulasi.dahal@helvetas.org
Devraj Gautam	MEDAIR	9851225844	shelterpm-npl@medair.org
Balaram Lama	CDS	9851060469	blrm.link@gmail.com
Shiba Achhami	Swisscontact/NAMDP	9849283546	shiba.achhami@swisscontact.org

The End