

This district profile outlines the current activities by partner organisations (POs) in post-earthquake recovery and reconstruction. It is based on 4W and secondary data collected from POs on their recent activities pertaining to housing sector. Further, it captures a wide range of planned, ongoing and completed activities within the HRRP framework. For additional information, please refer to the HRRP dashboard.

FACTS AND FIGURES

Population: 420,477¹

35 VDCs and 2 municipalities

Damage Status - Private Structures



Damage Grade (3-5)	37,318
Damage Grade (1-2)	53,675
Total	90,993²


Type of housing walls Makwanpur National

Mud-bonded bricks/stone	45%	41%
Cement-bonded bricks/stone	30%	29%
Other	25%	30%

% of households who own their housing unit 87% 85%
(Census 2011)¹

ENROLLMENT STATUS

KEY FIGURES




MUNICIPALITY/VDC

0 completed
36 ongoing
8 remaining

PARTNERS

HERD-I
MAITI-N
NRCS
TEARFUND


OPERATIONAL PRESENCE




ACTIVITIES

The maps depict the reached figures according to different thematic areas³. A proper analysis of such information allows the stakeholders to identify possible gaps, minimize cases of duplication, and serves as a vital tool for supporting decision-making processes.


Mason Training - Short training (masons)




BBS Messaging (households)




Demonstration Constructions (constructions)




Financial Assistance - Cash (households)



House Construction Materials (households)



Construction supervision-DLPIU (households)



NEWS & UPDATES

1. DAO, DDC, DLPIU and NRA have provided orientation on enrollment to the newly recruited staffs/volunteers prior to their deployment to respective VDCs.
2. Three people were buried to death in a landslide at Bhimphedi-5 triggered by incessant rainfall. The affected people were living in a quake damaged house after repair.
3. One death and six injuries were reported due to thunderstorm on 6 August, 2016. As per DDRC, 301 people have lost their lives in last 40 years due to the incidence which indicates that Makwanpur has always been a thunderstorm-prone area. Thus, installing lightning arrestors is recommended during reconstruction of houses in hilly areas.



© Santosh Upadhyay, HRRP

PARTNERS

Partner Organisation	Implementing Partner(s)
ICCO	CCDN
NRCS	
PLAN	CEEDF
SHANGRILA ORP	
TEARFUND	RADO
UNDP	

6 partners

This table indicates the partner organisations and their respective implementing partner(s)³

MASON TRAINING STATUS


SHORT TRAINING

DUDBC	299	126
CTEVT	20	
OTHER	336	

■ Reached ■ Remaining

These graphs show the number of planned and reached masons for different types of training (short and vocational) according to their respective curriculums (DUDBC, CTEVT, OTHER)³

LANDSLIDE SUSCEPTIBILITY



KEY CONTACTS

DAO OFFICE

Dr. Man Bahadur B.K
Chief District Officer
Telephone: 057-520495

DDC OFFICE

Mr. Laxman Bikram Thapa
Local Development Officer
Telephone: 057-520950

NRA District Office

Mr. Ramesh Kumar KC
Sub-Regional Head

DUDBC OFFICE

Mr. Sudeep Acharya
Division Head
Telephone: 057-520028