

This district profile outlines the current activities by partner organisations (POs) in post-earthquake recovery and reconstruction. It is based on 4W and secondary data collected from POs on their recent activities pertaining to housing sector. Further, it captures a wide range of planned, ongoing and completed activities within the HRRP framework. For additional information, please refer to the HRRP dashboard.


## FACTS AND FIGURES

### Population:

280,874<sup>1</sup>

### 48 VDCs and 2 municipalities

### Damage Status - Private Structures



|                    |                           |
|--------------------|---------------------------|
| Damage Grade (3-5) | 56,293                    |
| Damage Grade (1-2) | 4,346                     |
| <b>Total</b>       | <b>60,639<sup>2</sup></b> |

### Type of housing walls Dolakha National

|                            |     |     |
|----------------------------|-----|-----|
| Mud-bonded bricks/stone    | 92% | 41% |
| Cement-bonded bricks/stone | 5%  | 29% |
| Other                      | 3%  | 30% |

|                                            |     |     |
|--------------------------------------------|-----|-----|
| % of households who own their housing unit | 94% | 85% |
|--------------------------------------------|-----|-----|

(Census 2011)<sup>1</sup>

## NEWS & UPDATES

1. Field observation shows that the majority of the houses are reconstructed using stone and mud; stone with cement mortar are also being applied significantly.
2. The treatment and seasoning of timber was considered to be a major challenge in many areas. In some areas, only soft or medium wood is available and people wanted to know if any type of wood could be used for banding by using some form of local treatment or what other options might be available for constructing seismic bands.
3. Orientation of the Inspection SOP has been conducted for VDC Secretaries, DLPIU engineers and POs. Some participants felt that the Inspection SOP is not inclusive as poor / vulnerable households will not be able to comply with the minimum requirements. It was recommended that special support should be provided to vulnerable households during the inspection process.
4. There were concerns that accessing remote VDCs will be a challenge, and because VDC secretaries typically spend the majority of their time in the district headquarters.



## PARTNERS

| Partner Organisation | Implementing Partner(s) |
|----------------------|-------------------------|
| BC                   | PLAN                    |
| CA                   | CEEPAARD, HURADEC       |
| CARITAS-N            |                         |
| CW                   | RRN                     |
| HELVETAS             | AFD, CS, KITES          |
| IOM                  | CWIN-TUKI, IOM, REDR-I  |
| LWF                  | HURADEC                 |
| NRCS                 |                         |
| NSET                 |                         |
| PLAN                 |                         |
| SCI                  | RDTA                    |
| UNDP                 |                         |
| UNHABITAT            |                         |

13 partners

This table indicates the partner organisations and their respective implementing partner(s)

## SUMMARY AND HIGHLIGHTS<sup>3</sup>



### SHORT TRAINING

2,198

1,785

### VOCATIONAL TRAINING (Targets Achieved)

482

5,518

Reached Remaining



### 11 Demonstration Constructions in 11 VDCs



### 0 VDC with Household WASH Assistance



47,614 beneficiaries enrolled, 92%

47,079 beneficiaries received the 1st Tranche, 91%<sup>4</sup>



246 houses provided with Housing Grants by POs

## KEY CONTACTS

### DAO OFFICE

Mr. Yagyaraj Bohara  
Chief District Officer  
Telephone: 049-421133

### DDC OFFICE

Mr. Shankar Nepal  
Local Development Officer  
Telephone: 049-421142

### NRA District Office

Mr. Sagar Acharya  
District Focal Point

### DUDBC OFFICE

Mr. Ekraj Adhikari  
Division Head  
Telephone: 049-421777


- 0 VDC with all 6 TA Activities
- 1 VDC with no TA
- 1 VDC with no TA and more than 60% damage

The coverage of Technical Assistance (TA) is defined according to the presence (planned and on-going) of the following 6 activities and the VDCs highlighted suggest the summation of the activities presented:


- a. Community/household orientation with more than 1 session
- b. Continuous Door to door technical assistance (Mobile Technical Support)
- c. Short training for Masons (Target achieved)
- d. Vocation/on the job training for masons (Target achieved)
- e. Helpdesk/Technical Support Center
- f. Demonstration construction

### Disclaimer:

The highlighted VDCs indicate that at least one of the aforementioned activities is being conducted/planned by partner organizations, irrespective of the methodology or household level coverage of the activity. For activity c and d, it is highlighted when there are more than 70% of masons trained according to the targets defined by NRA and field surveys.



### Coverage of TA



Wards with no TA