

District Report

Sindhuli

12 – 25 May 2018

Activity Summary

Activity	Contact Person	Reference Document
Coordination with POs and various Government agencies regarding Reconstruction status	techcord.sindhuli@hrrpnepal.org	
Conducted District Technical Coordination Meeting on 17 th May 2018 chaired by Senior Divisional Engineer Shyam Sundar Mishra in DCO Meeting Hall Sindhuli	techcord.sindhuli@hrrpnepal.org	Meeting Minute

Upcoming Events & Meetings

	Date, Time, and Location	Contact Person
Planning to conduct Palika Level Meeting and Joint monitoring field visit in Golanjor Rural Municipality	On 29 th May 2018 to 3 rd June 2018, at Golanjor Rural Municipality.	techcord.sindhuli@hrrpnepal.org

News & Updates

- Participated One-day training on Light Timber/Steel Frame Structure organized by JICA in Sindhupalchowk
- Restructuring of NRA office in the district

Key Points Discussed in Technical Coordination Meeting

Date	Location	Participants
17 th May 2018	DCO Meeting Hall, Sindhuli	Representatives from Government office and POs present in Sindhuli district.
Objective(s)	❖ Joint Monitoring and field visit status with CLPIU, NRA/HRRP, MOUD ❖ Non-compliance issues seen during field visit ❖ Design and approval of Timber Frame Structure manual	
Summary	The District Technical Coordination Meeting was chaired by Senior Divisional Engineer NRA/DLPIU, Sindhuli Mr. Shyam Sundar Mishra and Chief Guest Mr. Shankar Raj Tiwari (Barma), DCO chief Sindhuli. Most of the technical teams from Government as well as POs working in the reconstruction sector in Sindhuli district were present in the program. Following points were discussed during the meeting.	

	➤ Discussion was focused on technical issues and problems seen during joint monitoring and field visit ➤ Absence and transfer of DLPIU Engineers effect in the reconstruction ➤ Design and approval of Timber Frame Structure manual and its necessity in the district for timber houses. ➤ There is need for orientation/training of Timber/Steel Frame Structure for DLPIU Engineers. So, all the concerned authorities from district to initiate in national level for the orientation/training as soon as possible.		
Challenges / Issues Discussed	Action Required	Responsible	Timeframe
❖ Non-compliance houses constructed recently after the Gorkha Earthquake, before the deployment of DLPIU Engineers	Solution regarding non-compliance houses that have DPC band and vertical band but not photos	NRA, MOUD/DLPIU , DSE	Before the deadline for 2 nd tranche announced by GON.
❖ Non-compliance houses that are constructed by the trained mason, training provided by NRCS	Beneficiary should prefer the correction exceptional manual to those houses which are non-compliance	NRA, NRCS, DLPIU	Before the deadline for 2 nd tranche announced by GON.
❖ Timber framed structure houses	Orientation/training on Timber/steel framed structure	NRA, MOUD/DLPIU	As soon as possible

Photos



Caption: HRRP DTC facilitating during District Technical Coordination Meeting. Presenting various technical issues seen during field visit.



Caption: Participants from different organization and government office during discussion on solution to technical issues and problems regarding reconstruction in Sindhuli district.



Caption: Mr. Basudev Humagain, section officer NRA Sindhuli presenting his remarkable points. He stated that most of the houses that were constructed recently after the Gorkha Earthquake 2015, are non-compliance and there is no solution unless beneficiary wants to correct them.