



NRA GEO-HAZARD ASSESSMENT PROGRAMME




1. PROJECT BACKGROUND & OBJECTIVES

2. PROJECT DATA COLLECTION & MANAGEMENT

OBJECTIVES

- Undertake geo-hazard assessments at 455 locations in 15 Districts
- **Districts:** Ramchhap, Solukhumbu, Dhading, Dolakha, Makwanpur, Kavrepalanchok, Rasuwa, Chitwan, Gorkha, Sindupalchowk, Okhaldunga, Lamjung, Tanahu, Kathmandu, Lalitpur
- **Methodology:** developed by the NRA Technical Committee, focuses mainly on landslides with questions on flooding.



OBJECTIVES

- Ultimate requirement is for the NRA to classify each location into one of three categories based on your recommendations:

Category I: Safer communities/villages where reconstruction can be started any time.

Category II: Communities/villages under the risk of manageable geo-hazards. Reconstruction can be started only after applying the suitable countermeasures.

Category III: Unsafe communities/villages due to the existing state of geo-hazards which are extremely difficult to control technically as well as financially. Reconstruction is not recommended.

- Identify potential relocation sites where required.
- Determine responsible agency for intervention (DSCWM/DWIDM)

PROCESS

METHODOLOGY – 5 STEPS

STEP 1 – TRAINING SESSIONS

STEP 2 – PREPARATION FOR FIELD WORK

STEP 3 – FIELD DATA COLLECTION

STEP 4 – FIELD DATA INTERPRETATION/FINAL REPORTING

STEP 5 – RECOMMENDATIONS TO NRA

PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 1: SETTLEMENT INFORMATION

B. Data Collection Sheet for Field Investigation

(Note: 1) As far as possible field photographs should be taken for each of the following items to illustrate the ground reality.

2) Walk over survey is to be conducted with GPS along the boundary of the landslide / settlements.

1. Settlement Information

District:.....VDC..... Ward No.....

Name of village.....

Date:

Number of households in the settlement:.....

Latitude.....Longitude.....Elevation.....

Name(s) and discipline of consultants:

1)




2)

3)

Position of the geo-hazards (tick the appropriate one): It is situated upslope / down slope/ within / side slope of the settlement.


(Place a representative photograph and the topographical map of the settlement here)

PRIMARY RESPONSIBILITY – SOIL & WATERSHED
MANAGEMENT EXPERT



PROCESS

PRIMARY RESPONSIBILITY – SOIL & WATERSHED
MANAGEMENT EXPERT



METHODOLOGY – FIELD DATA COLLECTION

FORM 2: PROBLEM STATEMENTS (1/3)

2. **Problem Statements** (based on the interaction with Key Informants)
(Please tick appropriate statements)

Name(s), position and telephone numbers of persons interviewed:



1)

2)

3)

4)




PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 3a: LANDSLIDE INFORMATION

PRIMARY RESPONSIBILITY – GEOLOGIST



Basic Information		Landslides classification (Tick in appropriate box)																													
Coordinate: At the bottom /toe of the landslide: Latitude: N Longitude: E At the crown of the landslide: Latitude: N Longitude: E Approximate dimension: Length:m Width:m Depth:m Slope aspect: Elevation: At the toe of landslide.....m. At the crown of landslide.m.		<table><thead><tr><th>Material</th><th>Tick</th></tr></thead><tbody><tr><td>Rock</td><td></td></tr><tr><td>Debris</td><td></td></tr><tr><td>Soil</td><td></td></tr></tbody></table>	Material	Tick	Rock		Debris		Soil		<table><thead><tr><th>Type</th><th>Tick</th></tr></thead><tbody><tr><td>Fall</td><td></td></tr><tr><td>Topple</td><td></td></tr><tr><td>Rotational</td><td></td></tr><tr><td>Translational</td><td></td></tr><tr><td>Lateral Spread</td><td></td></tr><tr><td>Debris Flow</td><td></td></tr><tr><td>Debris Avalanche</td><td></td></tr><tr><td>Earth Flow</td><td></td></tr><tr><td>Creep</td><td></td></tr></tbody></table>	Type	Tick	Fall		Topple		Rotational		Translational		Lateral Spread		Debris Flow		Debris Avalanche		Earth Flow		Creep	
Material	Tick																														
Rock																															
Debris																															
Soil																															
Type	Tick																														
Fall																															
Topple																															
Rotational																															
Translational																															
Lateral Spread																															
Debris Flow																															
Debris Avalanche																															
Earth Flow																															
Creep																															
		Please mention any other mechanism, if any, which is not covered by the above chart. (For example: Granular Flow commonly found in Siwalik region)..... Present state of slope movement (circle): Active/ Suspended/ Inactive/ Reactivated/ Dormant/ Stabilized/ Relict. Distribution of slope movement (circle): Retreating/ Advancing/ Widening/ Confined/ Enlarging/ Diminishing/ Moving. Rate of slope movement (circle): Extremely Slow/ Very Slow/ Slow/ Moderate/ Rapid/ Very Rapid/ Extremely Rapid.																													
History of landslide: When it was first initiated?(month/year) When it was last reactivated?(month/year) Recurrence interval:		Main causes (Tick in appropriate box): <table><tbody><tr><td>Geological</td><td>Terrace cultivation</td><td></td></tr><tr><td>Unfavorable rock discontinuity orientation</td><td>Low strength/high plasticity slope materials</td><td></td></tr><tr><td>Deforestation</td><td>Excessive irrigation/water impoundment</td><td></td></tr><tr><td>Machinery vibration</td><td></td><td></td></tr><tr><td>Drainage mismanagement</td><td>Riverbank/Toe cutting</td><td></td></tr><tr><td>Rural road construction</td><td>Road slope (Toe Cutting)</td><td></td></tr><tr><td>Increased load on slope</td><td>Any other:</td><td></td></tr></tbody></table>		Geological	Terrace cultivation		Unfavorable rock discontinuity orientation	Low strength/high plasticity slope materials		Deforestation	Excessive irrigation/water impoundment		Machinery vibration			Drainage mismanagement	Riverbank/Toe cutting		Rural road construction	Road slope (Toe Cutting)		Increased load on slope	Any other:								
Geological	Terrace cultivation																														
Unfavorable rock discontinuity orientation	Low strength/high plasticity slope materials																														
Deforestation	Excessive irrigation/water impoundment																														
Machinery vibration																															
Drainage mismanagement	Riverbank/Toe cutting																														
Rural road construction	Road slope (Toe Cutting)																														
Increased load on slope	Any other:																														
Triggers: Earthquake / Intense rainfall /Other																															

Type of landslide in term of mitigation (Tick in appropriate type):

Slides in earth/debris materials:

Shallow seated failure: Soil thickness less than 3m. A, B, and C soil horizons are disturbed. Treatable within reasonable timeframe and the scope of bio-engineering techniques and resources.

Deep seated failure: Soil thickness more than 3m. Treatment requires big structures (Concrete) and huge resources.

Slides in bed rock:

Shallow seated failure: Surface soil less than 1 m thick followed by bed rock. Surface soil and about 1 m thick rock layer (highly weathered rock) is sliding. Treatment requires bioengineering and simple civil engineering techniques such as retaining wall.


Deep seated failure: Rock failure (crack and slides in bed rocks). It requires expensive treatment such as rock bolting, rock anchoring, etc.).

PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 3b: LANDSLIDE IMPACTS

PRIMARY RESPONSIBILITY – SOIL & WATERSHED
MANAGEMENT EXPERT



Impacts of the landslide on					
Settlement					
No of house affected		No of people displaced		No. of people killed	
No of school affected		No of health post affected		No of community building affected	
Road					
Road Type (Tick in appropriate type)					
Dirt road ☐		Gravel road ☐		Asphalt road ☐	
Length of Road affected		Local road	m		
		Feeder road.....	m		
		National highway.....	m		
Irrigation					
Irrigation Type (Tick in appropriate type)				Command area in hectares	 ha.
Community ☐		Multi community ☐		Multi VDC ☐	
				Length in meters	m
Hydropower (Tick in appropriate type)					
Intake: ☐		Dam: ☐		Tunnel: ☐	
				Station: ☐	
				Settling basin: ☐	
Drinking water supply scheme					
Drinking water supply Type (Tick in appropriate type)				No. of User Households	
Community ☐		Multi community ☐		Multi VDC ☐	
				Length in meters	
Landslides Blocking Stream / River (Tick appropriate type)					
None (no signs of blockage of rivers)		Partially (partially blocked the river)		Complete (completely blocked the river, and still blocking)	
				Complete and broken through (blocked the river but later broken through)	


Agricultural land:.....	(hectors/ ropani/ bighas)
Pasture land.....	(hectors/ ropani/ bighas)
Forests (community forest / national forest):.....	(hectors/ ropani/ bighas)
National heritage and monuments:.....	(write names)
Any other (Please specify):.....	

PROCESS

PRIMARY RESPONSIBILITY – WATER INDUCED DISASTER MANAGEMENT EXPERT

METHODOLOGY – FIELD DATA COLLECTION

FORM 3c: LANDSLIDE GEOTECHNICAL CONSIDERATION



Geotechnical aspects of the landslide (Tick appropriate item or add your own words in the given spaces)	
Type of slide based on depth to slip surface	Shallow seated (1-3 m) Deep seated (>3 m)
Type of landslide (material & type)	
Size of the slide based on toe –width distance	Small (<50m), Medium (50-100m), Large (>100m)
Nature displaced material	Boulders:% by volume Gravels:% by volume Sands:% by volume Silts:% by volume Clay:% by volume Slope (range): Slope (representative):
Existing state of landslide (state and velocity)	
Nature of the slide in the crown part	No tension cracks Several Tension cracks parallel to the crown Many loose / detached rock blocks Possibility of plane/wedge/toppling failure Presence of seepage zone
Nature of the slide in the left flank	No tension cracks Several Tension cracks parallel to the crown Many loose / detached rock blocks Possibility of plane/wedge/toppling failure Presence of seepage zone

Nature of the slide in the right flank	No tension cracks Several Tension cracks parallel to the crown Many loose / detached rock blocks Possibility of plane/wedge/toppling failure Presence of seepage zone
Condition of drainage within the slide	
Condition of drainage in the toe part	
Condition of drainage in the crown part	
Toe cutting by a river	Yes/No Depth of the river / bank's height:m
Sketches of the landslide (plan view as well as cross-sectional view)	Prepare sketch of the landslide in the attached sheet Plan view: one sketch Cross sectional view: At least three sketches
Remarks, if any	

PROCESS


PRIMARY RESPONSIBILITY – GEOLOGIST

METHODOLOGY – FIELD DATA COLLECTION

FORM 4: Geological, Engineering Geological, Geotechnical Investigation Of Settlement

Part 1 – Geological Information

Geological Information	
(Information should be collected from stable ground situated nearby to the settlement / landslide)	
Tectonic Unit	Tera , Siwalik, Lesser Himalaya, Higher Himalaya, Tethys Himalaya
Stratigraphic Information (literature review)	Complex:
	Group:
	Formation:
	Member:
	Bed:
Lithology	
Rock types	
Attitude of bed	Strike: Dip amount: Dip direction:
Mineralogical composition	
Nature of lithological contacts	Sharp/ transitional Any other features:.....
Major geological structures	
Fault (active / passive)	Presence/absence of fault breccia / gouge/ slickenside / seepage
Attitude of the fault	Strike: Dip amount: Dip direction:
Fold axis	Presence / absence highly fractures rock / seepage
Attitude of the fold axis	Strike: Dip amount: Dip direction:




PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 5: RECOMMENDATIONS

JOINT TEAM EFFORT



C. Recommendations

Does landslide need to be monitored?	Yes: (Need) to demonstrate a simple method of slope monitoring to the local people) No: (Justify your answer)
If yes, how long does it to be monitored?	months (Justify your answer)
Is it necessary to fly drone for further data extraction?	Yes / No (Justify your answer)
Does the settlement need simple means of slope protection?	Yes / No If yes, tick the appropriate one - Surface water drainage - Groundwater drainage - Sealing of the cracks

	- Bioengineering works - Change in crops types - Slope trimming - Removal of soil - Removal of rock blocks - River training works - - -
Is it necessary to conduct detail geotechnical study?	Yes / No (Justify your answer) If yes: Soil parameters to be tested: Number of soil samples to be extracted: Approximate depths from where soil samples are to be extracted: Types of survey, if any, required:

PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 6: RELOCATION OPTIONS

PROVISION FOR INFORMATION ON 3 OPTIONS FOR RELOCATION

Option 2

Name of VDC:.....Name of village:.....

Tentative area (sq. m):.....Geographical coordinates: (Latitude/longitude).....

Representative angle of hill slope:.....Stratigraphic unit:

Land use:..... Nature of land ownership: Private/public.....

Nearby drainage condition:


State of geo-hazards: (Example: the site is safer from the landslide).....

Distance from the nearest drinking water source:km

Distance from nearest highway/district road/agricultural road:km

Availability of primary basic needs (school/health posts etc.):km

JOINT TEAM EFFORT



PROCESS

METHODOLOGY – FIELD DATA COLLECTION

FORM 7: FINAL IMPRESSIONS & KEY POINTS

E. Final impression of the field investigators:

Key points for decision making:

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
-
-

Signature and date:

Name of the field investigator:

Designation:

Affiliation:

Signature and date:

Name of the field investigator:

Designation:

Affiliation:


Signature and date:

Name of the field investigator:

Designation:

Affiliation:

JOINT TEAM EFFORT



METHODOLOGY – FIELD DATA COLLECTION

FORM 7: FINAL IMPRESSIONS & KEY POINTS



DRAFT FOR REVIEW AND COMMENT - Version 3.0_24August2016								
Multi-hazard Risk Evaluation Matrix*								
For the Qualitative Assessment of Geologic Hazards & Associated Risk								
			Risk Evaluation and Response					
			H	High	Risk is unacceptable - move to reduce/eliminate exposure to hazard			
			M	Medium	Risk may be tolerable; more detailed review required; reduce risk to as low as reasonably practicle			
			L	Low	Risk is tolerable; continue to monitor and reduce risk to as low as reasonably practice			
Partial Risk (annual probability)								
Indices		Probability Range						
Likelihood Descriptions	E	Almost certain	>0.9	M	M	H	H	H
Event typically occurs at least once per year	D	Very likely	0.1 to 0.9	M	M	H	H	H
Event typically occurs every few years	C	Likely	0.01 to 0.1	L	M	H	H	H
Event expected to occur every 10 to 100 years	B	Possible	0.001 to 0.01	L	L	M	H	H
Event expected to occur every 100 to 1,000 years	A	Unlikely	0.0001 to 0.001	L	L	L	M	H
			1	2	2	4	5	
		*Indices	Low Hazard	Moderate Hazard	Significant Hazard	High Hazard	Catastrophic Hazard	
Description of expected negative outcomes (consequences)	Landslide	Small landlides that communities can provide appropriate mitigation for; injuries not likely; recoverable in days to weeks	Threat of medium magnitude losses to structures, infrastructure and/or agricultural land; mitigations viable & with local capacity; serious injuries and personal hardship possible if unaddressed; full recovery not likely	Threat of high magnitude losses to structures, infrastructure and/or agricultural land; mitigations viable but may be beyond local capacity; serious injuries and fatalities likely if unaddressed; full recovery not likely; at least partial relocation to be considered	Threat of high magnitude losses to structures, infrastructure and/or agricultural land; mitigation viability questionable; serious injuries and fatalities highly likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Threat of high magnitude losses to structures, infrastructure and/or agricultural land; mitigation not viable; serious injuries and fatalities expected if unaddressed; not recoverable; relocation of settlement must be done		
	Liquefaction	Liquefaction hazard quantified and existing structures and infrastructure designed & constructed appropriately; very minor damage if any expected; recoverable in days to weeks	Structures & infrastructure expected to have moderate damage; serious injuries and personal hardship possible if unaddressed; recovery in weeks to months	Structures & infrastructure expected to have moderate to significant damage; serious injuries and fatalities likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Structures & infrastructure expected to have high damage; many fatalities highly likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Most if not all structures & infrastructure expected to have high damage; mass fatalities expected if unaddressed; relocation of settlement must be done		
	Flood	Potential for water damage to structures and infrastructure very limited; flood water velocities below 0.3 m/s (low); recoverable in days to weeks	Structures & infrastructure expected to have moderate damage; personal hardship; flood water 0.4 to 0.6 m/s (velocity moderate); Personal hardship; recoverable in weeks to months	Structures & infrastructure expected to have moderate damage; flood water velocity above 0.7 m/s (high); serious injuries & fatalities likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Structures & infrastructure expected to have high damage; many fatalities likely if unaddressed; flood water velocity high; full recovery not likely; relocation of all or part of settlement to be considered	Most if not all structures & infrastructure expected to have high damage; mass fatalities expected if unaddressed; relocation of settlement must be done		
	Flash Flood	Local topography limits flash flood hazard potential to low; location not at risk from glacial lake outburst flood (GLOF) or landslide-dammed river (LDR); flash flood water velocity low; recoverable in days to weeks	Local topography is conducive to flash flooding; location not at risk from GLOF or LDR; structures & infrastructure expected to have moderate damage; personal hardship; flash flood water velocity moderate; recoverable in weeks to months	Local topography is conducive to flash flooding and/or location at limited risk from GLOF or LDR; structures & infrastructure expected to have moderate damage; flash flood water velocity high; serious injuries & fatalities likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Local topography is conducive to flash flooding and/or location at risk from GLOF or LDR; structures & infrastructure expected to have high damage; flash flood water velocity high; serious injuries & fatalities likely if unaddressed; full recovery not likely; relocation of all or part of settlement to be considered	Location at extreme risk from GLOF or LDR; most if not all structures & infrastructure expected to have high damage; mass fatalities expected if unaddressed; relocation of settlement must be done		



*For use by professional staff at VDC & District level. *Indices for social, economic, and environmental dimensions of vulnerability not included - these are to be factored in at the NRA level.

PROCESS


METHODOLOGY – FIELD DATA COLLECTION



DATA RECORDED & REPORTED IN HARD COPY
FINAL REPORT PRESENTED TO NRA EXPERT PANEL

A sample of a hard copy field data recording sheet. At the top is the logo of the National Reconstruction Authority (NRA). Below the logo, the text reads: "NATIONAL RECONSTRUCTION AUTHORITY", "GEO-HAZARD ASSESSMENT PROGRAMME", and "FIELD DATA RECORDING SHEETS". There are four horizontal lines for text entry, labeled "Settlement Name", "Settlement Reference", "District", and "VDC".

DATA RECORDED, REPORTED AND SUBMITTED FROM FIELD
USING FIELDSIGHT TABLET/PHONE SYSTEM



DATA COLLECTION & MANAGEMENT



INNOVATION LAB – WORLD VISION & UNOPS

CONSTRUCT QUESTION FORMS USING KOBO TOOLBOX

The screenshot shows the FieldSight web application interface. The browser address bar displays "nra.fieldsight.org". The interface includes a search bar, a sidebar with navigation icons, and a main table listing projects. The sidebar has sections for "Projects" (with a "NEW" button), "Deployed (14)" (listing "Form 2--Problem Statements", "geological", "Form 4: Geological and Geomorphological...", and "Form 2 : Problem Statements"), "Draft (0)", and "Archived (0)". The main table has columns for "Name", "Owner", "Last Modified", and "Questions".

Name	Owner	Last Modified	Questions
☐ Form 2--Problem Statements	me	a month ago	49 ▶
☐ geological	me	a month ago	182 ▶
☐ Form 4: Geological and Geomorphological Investigation of Settleme...	me	a month ago	182 ▶
☐ Form 2 : Problem Statements	me	a month ago	49 ▶
☐ problem statement	me	a month ago	49 ▶
☐ Form 2: Problem Statements	me	a month ago	49 ▶
☐ Form 1: Settlement Information	me	a month ago	21 ▶
☐ Form 5: Recommendations	me	a month ago	25 ▶
☐ Form 6: Information on Options for Temporary / Permanent Relocati...	me	a month ago	49 ▶
☐ Form 7: Final Impression of Field Investigators	me	a month ago	47 ▶
☐ Form 8: Photographs	me	a month ago	7 ▶

DATA COLLECTION & MANAGEMENT

nra.fieldsight.org

Form 1: Settlement Information

SAVE

Layout


Search Library

METADATA: START TIME, END TIME


Settlement Information

abc	Settlement Reference Number	
abc	Settlement Name	
123	Ward Number	
abc	VDC	
abc	District	
123	Number of Households in the Settlement	

DATA COLLECTION & MANAGEMENT



DATA COLLECTION & MANAGEMENT



The screenshot shows a web browser window with the address bar displaying 'nrakc.fieldsight.org'. The page has a dark header with a 'Projects' menu icon on the left, 'Support' and 'KoBoToolbox' logos on the right, and a '+', 'copy', and 'share' icon on the far right. The main content area is a table listing various data collection forms, their status, and submission counts.

Projects	Active	Assign	Shared By	Date Created	Last Modified	Submissions
Form 5 - Recommendations Form 5 - Recommendations	✖	✉		Dec. 11, 2016	Jan. 02, 2017	1
Form 1: Settlement Information Form 1: Settlement Information	✔	✉		Dec. 20, 2016	Jan. 15, 2017	49
Form 4: Geological and Geomorphological Investigation of Settlement and Surroundings Form 4: Geological and Geomorphological Investigation of Settlement and Surroundings	✔	✉		Dec. 20, 2016	Jan. 15, 2017	40
Form 6 - Information on Options for Temporary / Permanent Relocation of Site Form 6 - Information on Options for Temporary / Permanent Relocation of Site	✖	✉		Dec. 11, 2016	Jan. 02, 2017	1
Form 8: Photographs Form 8: Photographs	✔	✉		Dec. 20, 2016	Jan. 15, 2017	44
Form 3 - Landslides Form 3 - Landslides	✖	✉		Dec. 11, 2016	Jan. 02, 2017	1
Form 3: Landslides Form 3: Landslides	✔	✉		Dec. 20, 2016	Jan. 15, 2017	40
Form 2 - Problem Statements Form 2 - Problem Statements	✖	✉		Dec. 11, 2016	Jan. 02, 2017	1
Form 7: Final Impression of Field Investigators Form 7: Final Impression of Field Investigators	✔	✉		Dec. 20, 2016	Jan. 15, 2017	31
Form 2: Problem Statements Form 2: Problem Statements	✔	✉		Dec. 20, 2016	Jan. 15, 2017	41
Form 1 - Settlement Information Form 1 - Settlement Information	✖	✉		Dec. 11, 2016	Jan. 02, 2017	1
Form 6: Information on Options for Temporary / Permanent Relocation of Site Form 6: Information on Options for Temporary / Permanent Relocation of Site	✔	✉		Dec. 20, 2016	Jan. 15, 2017	33
Form 4 - Geological and Geomorphological Investigation of Settlement and Surroundings Form 4 - Geological and Geomorphological Investigation of Settlement and Surroundings	✖	✉		Dec. 11, 2016	Jan. 02, 2017	2
Form 5: Recommendations Form 5: Recommendations	✔	✉		Dec. 20, 2016	Jan. 15, 2017	31

DATA COLLECTION & MANAGEMENT

The screenshot displays the nrakc.fieldsight.org web application. The browser's address bar shows the URL. The application's header includes a 'Projects' menu, a 'Support' link, and the 'KoBoToolbox' logo. A 'Project Settings' link is visible below the header. The main content area is titled 'Form 3: Landslides' and includes a breadcrumb trail. Below this, there are three main sections: 'Submissions (40)', 'Photos', and 'GPS Points'. Each section contains specific action buttons. The 'Submissions (40)' section has buttons for 'Assign This Form To ..', 'View data in table', and 'Download data'. The 'Photos' section has a 'View gallery' button. The 'GPS Points' section has buttons for 'View on map' and 'Download GPS points'. At the bottom, there is a 'Form' section with a text input field containing the ID 'ane7EbaVxmFt9npkutMQ8A' and buttons for 'Download' and 'Preview'.

nrakc.fieldsight.org

Projects Support KoBoToolbox

Project Settings

Form 3: Landslides

Form 3: Landslides

Submissions (40)

Assign This Form To .. View data in table Download data

Photos

View gallery

GPS Points

View on map Download GPS points

Form

ane7EbaVxmFt9npkutMQ8A Download Preview

DATA COLLECTION & MANAGEMENT

nrakc.fieldsight.org

Projects

Support KoBoToolbox

Return to Form 3: Landslides

Value and header format

Labels

Include groups in headers☐

Group separator

/

Update Table

View or Edit	View Media	Settlement Reference Number	Settlement Name	Settlement Location	_Settlement Location_latitude	_Settlement Location_longitude	_Settlement Location_altitude	_Settlement Location_precision	How many landslides are around the settlement?	Please Report Information for Up to 3 Landslides.	start	end
Open		524 2 05 29 5 008	Thulo haku						3		2016-12-26T13:47:...	2016-12-27T08:22:...
Open		524 2 05 29 5 008	Lumwa dada						1		2016-12-27T09:23:...	2016-12-28T19:13:...
Open		Dadagaun mailung	Mailung						1		2016-12-29T07:42:...	2016-12-29T08:03:...
Open		524205295009 Dh	Dhakaldanda	27.98996082 85.20...	27.98996082	85.20936367	1300.0	4.0	1		2016-12-27T13:28:...	2016-12-30T20:40:...
Open		524 2 05 29 5 008	Mailung						1		2017-01-01T15:35:...	2017-01-01T15:53:...
Open		524 2 05 29 5 008	Tiru						2		2017-01-01T19:17:...	2017-01-01T20:46:...
Open		524 2 05 29 5 008	Gogane						1		2017-01-02T06:05:...	2017-01-03T07:27:...
Open		524 2 05 29 5 012	Palep						2		2017-01-02T09:54:...	2017-01-04T09:43:...
Open		524 2 05 29 5 018	Ghormu						1		2017-01-04T07:11:...	2017-01-04T13:00:...
Open		524205295009 Ka	Kadamghaari	27.98326563 85.21...	27.98326563	85.21018086	1037.0	5.0	1		2016-12-30T10:01:...	2017-01-03T18:04:...
Open		524205295001 Ka	Karangey	27.9808009 85.236...	27.9808009	85.23639639	879.0	5.0	1		2017-01-02T09:49:...	2017-01-03T20:59:...
Open		524205295001 Ru	Rupsepani	27.98738859 85.22...	27.98738859	85.22665184	1179.0	5.0	1		2017-01-01T10:23:...	2017-01-03T20:28:...
Open		524205295009 Ta	Tallo Rupsepani	27.98482754 85.23...	27.98482754	85.23052695	1067.0	5.0	1		2017-01-01T13:03:...	2017-01-03T20:46:...
Open		525205295001Ek	Ekpakhrebas Bhanj...	28.00986 85.26442...	28.00986	85.26442316	1251.0	5.0	1		2017-01-04T10:58:...	2017-01-05T08:42:...
Open		524205295013Ch	Chilaunegaun	28.00019101 85.27...	28.00019101	85.27772234	1294.0	4.0	1		2017-01-05T08:07:...	2017-01-05T18:21:...
Open		524205295009 Gh, ...	Ghumti Citrapani, P...	27.99916866 85.21...	27.99916866	85.21923927	1543.0	5.0	1		2016-12-28T11:40:...	2017-01-08T09:22:...

DATA COLLECTION & MANAGEMENT

Projects View By Thade Archale the jaunSatdobato Kalikasthan Betrawati Trisuli Bazar Bidur Dangmai Ranipauwa Kakani Dharm	<table><tr><td>Consultant 3 Date Completed</td><td>2017-01-01</td></tr><tr><td>Key Points for Decision-Making</td><td>Category I Cracks are almost stable. Hillslope is naturally stable now but some bioengineering works can be applied.</td></tr><tr><td>Frequency</td><td>p_0_9_occurs_a</td></tr><tr><td>Hazard Level</td><td>low</td></tr><tr><td>Risk Evaluation</td><td>low__risk_is_</td></tr><tr><td>Field Sketch: Plan View</td><td> < </td></tr></table>	Consultant 3 Date Completed	2017-01-01	Key Points for Decision-Making	Category I Cracks are almost stable. Hillslope is naturally stable now but some bioengineering works can be applied.	Frequency	p_0_9_occurs_a	Hazard Level	low	Risk Evaluation	low__risk_is_	Field Sketch: Plan View	<
Consultant 3 Date Completed	2017-01-01												
Key Points for Decision-Making	Category I Cracks are almost stable. Hillslope is naturally stable now but some bioengineering works can be applied.												
Frequency	p_0_9_occurs_a												
Hazard Level	low												
Risk Evaluation	low__risk_is_												
Field Sketch: Plan View	<												

DATA COLLECTION & MANAGEMENT

KEY ADVANTAGES OF FIELDSIGHT TOOL

- PROGRESS MONITORING
- DETERMINE IF TEAMS ARE IN THE RIGHT LOCATION
- EARLY STAGE REVIEW OF DATA
- DATA STORAGE & BACKUP
- GOOD STARTING POINT FOR SETTING UP OF DATABASE

MAIN CHALLENGES

- NETWORK COVERAGE MEANT THAT DATA DID NOT COME THROUGH FOR ALL TEAMS
- PHOTOGRAPH ATTACHMENTS CAN MAKE FOR LARGE FILES (work on compressing files underway)
- GPS FUNCTION WAS OFTEN INEFFECTIVE