

District Report

Gorkha

4 – 17 January 2019

Summary of events during this period


Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
HRRP team visited Gorkha Municipality ward no. 9 and 10 and had discussion regarding reconstruction issues and update. The details are available in the field visit section.	28 th December 2018			dc.gorkha@hrrpnepal.org ; im.gorkha@hrrpnepal.org	
As part of the joint monitoring field visit with CLPIU M&E, HRRP technical coordinator, Er. Atit Shrestha visited Bhimsen Thapa rural municipality ward no. (previous Baguwa vdc and Masel vdc) with CLPIU M&E Mr. Khagendra Aawasthi along with Gorkha GMALI Chief, Er. Ram Sharan Acharya, district support engineer, Awashesh Thakuri. The monitoring team also included JICA EHRP team who are providing technical support in the area. For detail please see the field visit section.	8 th January 2019			techcord.gorkha@hrrpnepal.org	Field visit section
District Disaster Relief Committee – DDRC, Gorkha organized and celebrated Earthquake Safety Day in Gorkha on 16 January 2019. The program was coordinated by District Coordination Committee and supported by Transparency International. The earthquake safety day was celebrated with an interaction regarding importance of pre-plan on disaster mitigation measures, disaster risk reduction strategies and experiences so far. There were some presentations by DLPIUs (GMALI, Building and Education) as well. The program was attended by district stakeholders, media, development partners.	16 th January 2019			dc.gorkha@hrrpnepal.org	

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Monthly Coordination meeting	29 th January 2019, 10 am, Gorkha bazaar	HRRP/GMALI	dc.gorkha@hrrpnepal.org ; techcord.gorkha@hrrpnepal.org ; im.gorkha@hrrpnepal.org
Palika Level Coordination meeting	21 January 2019, Gandaki Rural Municipality	HRRP and ODRC	dc.gorkha@hrrpnepal.org , dc.gorkha@odrcollaborative.net
Palika Level Coordination meeting	28 January 2019, Shahid Lakhani Rural Municipality	HRRP & ODRC	dc.gorkha@hrrpnepal.org , dc.gorkha@odrcollaborative.net

News & Updates


- 84% houses will be constructed in Barpak Sulikot
- 18 earthquake affected beneficiaries received land ownership document (lal purja)




Tranche Status

Rural /Municipality	Aarughat	Ajirkot	Bhimsen	Chum Nubri	Dharche	Gandaki	Gorkha	Palungtar	Sahid Lakhani	Siranchok	Sulikot
Total HHs Surveyed	6919	4169	6616	2132	3905	5790	13413	11362	7494	6951	7160
Total HHs Eligible	6911	4123	6834	2275	4169	5603	10094	9700	7059	6819	7181
Total HHs Enrolled	6906	4123	6834	2275	4148	5484	10021	9690	7047	6819	7181
First Tranche	6613	3947	6599	1795	3160	4815	9122	8186	6079	5735	6817
Second Tranche	5865	3643	5865	1479	2345	3665	7680	6477	4985	5105	6342
Third Tranche	4664	3149	4612	1074	1976	2520	6771	4828	4186	4137	5645
Total HH Constructed	4664	3149	4612	1074	1976	2520	6771	4828	4186	4137	5645
Grievance Registered	16622 (Total in district)										
Grievance Addressed	967	452	941	279	1121	1390	2496	3770	2282	2023	901
RF HH Eligible	171	63	168	49	280	441	1079	1038	836	904	177
RF HH Enrolled	171	63	168	49	280	441	1079	1038	836	904	177
RF 1st Tranche	30	1	1		19	11	240	88	27	14	
RF 2nd Tranche							5			1	
Non-Compliance Registered	2413 (Total in district)										
Non-Compliance Addressed	58-Failed for tranche 2298- Recommended for 2 nd Tranche 2139- Recommended for 3 rd Tranche										


Graph of Tranche Status:



Graph for Retrofitting Status:



Graph for Grievance Status:



Field Visit /Joint Field Monitoring Visit Reports

Visit 1

Date	Location	Participants from HRRP and stakeholders
08/01/2019	Bhimsen Thapa Rural Municipality, Ward No. 1 & 5	- Mr. Ram Sharan Acharya (Chief GMALI) and GMALI team - Mr. Khagendra Aawasthi (M&E CLPIU Building) - Er. Awashesh Thakuri (DSE) - Mr. Babu Ram KC (DPM, JICA EHRP) and JICA EHRP team - Mr. Atit Shrestha (DTC, HRRP)
Objective(s)	Joint Monitoring field visit of housing reconstruction of Bhimsen Thapa Rural Municipality with M&E CLPIU Building and GMALI team	
Summary	As part of HRRP and CLPIU Building joint monitoring plan, HRRP District technical coordinator, Mr. Atit Shrestha, M&E Mr. Khagendra Aawasthi and DSE Mr. Aawashesh Thakuri along with EHRP JICA team (who are providing technical support in those areas) visited Bhimsen Thapa rural municipality ward no. 1 & 5, Baguwa and Masel. The joint monitoring team was also accompanied by GMALI Chief Er. Ram Sharan Acharya and GMALI team (upto Baguwa only). The main agenda of the monitoring field visit was to look into the housing reconstructed in the rural municipality and visit some non-complaint houses in the area. The team first visit the integrated settlement of Milan Basti Baguwa and looked in to the ongoing construction. The houses are being constructed with CSEB Blocks in the settlement. The team interacted with the chairperson of the users committee of the integrated settlement regarding how they are doing construction and support they are receiving. The team visited Masel after Milan Basti (GMALI team headed towards Takukot) to monitor some non-complaint houses in the area. The team visited two houses in the area. The first one was of Yogendra Bhatta (one story). His house is constructed of stone masonry mud mortar (see housing typology section) and doesn't contain any reinforcement or bands and the wall span in one direction is longer than standard. The house has been sent for structural analysis. Based on the report, the team will suggest the house owner for some correction measures. JICA EHRP team has committed to provide support of its technical team (engineers and masons) working in the area to oversee and supervise the correction works if the house owner is willing to do corrections. The house owner shared that he is not willing to construct another house and if this house can be corrected he can think of doing it but it all depends on the cost of correction works required. The team then visited house of Suraj Singh Wasti (one story plus attic). The house is constructed with RCC columns with 4 reinforcement bars and stone masonry mud mortar walls as infill walls. At the floor level also, the house owner has done beam casting (status of reinforcement bars unknown). The owner has added to additional rooms (extension on both sides) without any connection to the main structure. The house has also been forwarded for structural analysis and the team will suggest the house owner for some correction measures based on the analysis. JICA EHRP team has committed to provide support of its technical team (engineers and masons) working in the area to oversee and supervise the correction works if the house owner is willing to do corrections. The house owner shared that he is not willing to construct another house and if this house can be corrected he can think of doing it but it all depends on the cost of correction works required. After the interaction the team headed back to Gorkha bazaar.	

Challenges / Issues Identified	Action Required	Responsible	Time Frame
Correction of non-complaint houses	Need to do structural analysis and based on the report do correction if necessary	DLPIU Building and DSE	As soon as possible

Photos




Caption: Er. Ram Sharan Acharya, Chief, GMALI Gorkha, interacting with local people and mobile mason of EHRP JICA regarding CSEB construction.



Caption: Joint monitoring team taking background information about the house (owner Suraj Singh Wasti) to know about the details of key components of house.

Housing Typology Report



Caption: Shiva Lal Shrestha's brick masonry cement mortar house in Gandaki rural municipality ward no. 6, Bhumlichowk. The house owner has received all tranches.

Photo Courtesy: UNDP ODRC team




Caption: Chandra Man Shrestha's RCC house in Gandaki rural municipality ward no. 1, Makaisingh. Tranche status of the house unknown.

Photo Courtesy: UNDP ODRC Team



Caption: 2 story houses in integrated settlement of Milan Basti in Bhimsen Thapa rural municipality, ward no. 5, Baguwa. Name of the house owner and tranche status unknown. This house has been constructed with CSEB blocks with RCC band.

Photo Courtesy: Atit Shrestha, HRRP



Caption: Yogendra Bhatta's stone masonry mud mortar house in Bhimsen Thapa rural municipality ward no. 1, Masel. The house is constructed without any bands and vertical reinforcement. This house has been forwarded for structural analysis and the house owner has not received second and third tranche.

Photo Courtesy: Atit Shrestha, HRRP

Questions Collected

Question	Who Asked the Question?	Response Provided (By Whom)
There are beneficiaries willing to return the first tranche amount back to NRA. How can they get information regarding procedure about the returning of first tranche amount?	Beneficiaries	Beneficiaries can get the information from the GMALI office in the district or contact the NRA hotline number for the information regarding how to return the tranche money. (GMALI)
Technical support to beneficiaries regarding retrofitting is required for beneficiaries to carry out retrofitting in their house. How can we give technical support to beneficiaries?	Beneficiaries	DLPIU engineers based in ward offices of urban/rural municipalities have received training on seismic retrofitting from UNOPS and Build Change. They will provide technical support to beneficiaries regarding retrofitting. (GMALI)

Challenges and Way Forward

Challenge	Way Forward
How can beneficiaries register dissatisfaction regarding grievances result and reapplication for inclusion in reconstruction beneficiaries list?	They can submit their dissatisfaction in a written form to district GMALI/NRA. NRA/GMALI will give answer to them.
How can beneficiaries receive technical support regarding retrofitting?	The beneficiaries can consult with the engineer's based in the field for retrofitting measures to be implemented.

Case Study

Technical Support to beneficiaries

41 years old Parbati B.K. is residing at Palungtar urban municipality ward no 4, Thatichaur. She has two daughters and her husband is abroad. She did not have any information about building permit procedure and norms/procedure to be followed for housing reconstruction. She contacted the ward office and was told that she Government of India supported Nepal Housing Reconstruction Project will support her in housing reconstruction. She was also told about the building permit studio for design drawing preparation and for getting building permit from the urban municipality. After getting information about Nepal Housing Reconstruction Project and Building Permit Studio (BPS), then she linked with BPS for drawings and forwarded for getting building permit from the urban municipality. After that she was contacted and facilitated for reconstruction of her house through the technical team of Nepal Housing Reconstruction Project (especially trained mason Mr. Dhurba Acharya). Nepal Housing Reconstruction Projects Technical Persons facilitated her for Layout work of house.

During her house reconstruction process, the technical team regularly support for Technical Facilitation. After completion of DPC, trained mason Mr. Dhurba Acharya helped her with DPIU engineer for technical inspection and second tranche. The technical team continually visited her house during construction (especially Mr. Dhurba Acharya, trained mason visited her house 6 times). In present condition, her house has been completed to roof level. Third inspection has been completed and forwarded for third tranche.



Parbati B.K's house at Layout stage and Present stage