
			The state of the s	g to a total transfer and the second material and an analysis		, - , - , - , - , - , - , - , - , - , -		-							
1.		Engineering	Order : 5	Drawing Title ASSY, PW.	1000	Y ADDRESS INTERFACE			Xerox Corporation El Segundo, California						
	EO Typu		المام	uney	ADDRESS MOTERANCE			Drawing Number			Chg. Ltr				
1	Revision	[Innediate		•		•	• •	1	21634	. 7	· E				
	☐ Reserve ☐ Serial No./Date			Dist. Code	DCR N	No. DCR Date Model N						Sheat			
1.	☐ Variation	☐ Next Production	. •	ALT	. 50, 1	. 1	2. 22 - 7'	1				1 ,	•		
1	Affected by This Change					Disposition			ــــابــــــنــــ	1		1 / 0	01		
• 1.		Yos No	· Dwg. No.	Olher Dwgs.		Status .		Raturn To Stock Rawork		Scrap	Lowest Acc Rovision Le				
ï.	Spare Parts	0 0				On Order	I O STOCK		Uso	Journ					
1.	Tooling		•			In Process	-	7.	· ·	 	Mandatory		١.		
	Test Procedures					In Stock		1		 	Prior Rovisions		1		
:	Test Equipment			• • • • • • • • • • • • • • • • • • • •		In Next Assy	<i>,</i>	V	·····			-			
:	Programs		(************************************			In Field					Field Info.	only	******		
	Tech. Publication	ons 🗆 🗗 📗				Refurbishmen		. /			Lowest field usage level	4			
	Reason For Char	nge (If reason la Dosi	gn Error or Reliability, describe :	symptoms & conditions under	which ti	nèy occur.)				L-,	1				
	Design Error														
	Drawing Error														
			,	, , , , , , , , , , , , , , , , , , ,	· · · · · ·	1	04707	<u> </u>	, ,,,	<i>.</i>	. :				
	Producibility		•			•		•							
•	Maintainability														
		[☑ Reliability													
	Cost Reduction														
	Drawing Change Rowerk Instructions														
		DELETED NOT		1) 20	REMOVE JUMPER BETWEEN ASG PW 1 AND A42 PM 11 (ETCH SIDE										
		A 56 PIN I A	NO A42 PIN 11, (6	ETCH SIDE)"	a) Ai	ADD JUMPER FROM AZI PINII TO AST PIN 1.									
	ADDED NOTE 1-L = ADD WIRE FROM AZI PIN II TO ASG PIN I (WATCLE) 3) ADD JUMPER FROM ASG PIN 10 TO AZI PIN 12.														
	ADDED NOTE	I-L = ADD WIK	E FROM ALI PINTI T	B ASG PIN I (WATER	A) ADD JUMPER FROM ALL PINZ TO ALL PIN							•			
	. /	M = ADD WIRE A	FROM A59 PIN 10 TO A21	PIN 12 (STORE):	1/2 / 5 <i>TORE</i>] '								4 < 10		
	5) USE MICROCREUIT SOCKET STG-AGIID INSTEAD OF SIGN														
	I-N: ADD WIRE FROM ARI PIN 2 TO ARI PINIS (MYSYSCLK) 6) USE MICREGIRCUIT SOCKET SIX-AGIID INSTEAD OF 514-AC												6100		
MLITEM 4 MICROCIRCUIT 3601-1 NAS 3601									_			,			
													·,		
	M/C ITEM .47	P/N 516-AG	IIP WAS: 516-AGIC	\mathcal{D}	•		•	Fial			PREA	F 69	1 1		
	•		C D. WAS : 518-AG	10D		•			l from						
	MG 17EM 48		Test Pr	ocedure to Ver	Ify Change	- Kan 9 ti	UST H	1 2 2 2 2	西	197	1.				
Ì	ML ITEM 48 Ph 514-AGIID WAS: 51R-AGIOD. DELETED ML ITEMS 49 SOCKET, MICHOCIRCUIT 8 PIN GTY 1.												1.1		
	DELETED M	LITEMB 49	Socre, Micro												
	DELETED ME	ITEM 50 . Sock	ET, MICEOCIACUIT 22 F	OIN ATY 1.		•	•	4				•			
				· .	•		• •	-	-]		
Į															
	Draftsman	· Date Chec	Date .	Floio/Mig.		De	te Proj. Engr.		Da	te DCB	14	1.	Date		
	1. The Summer	2-22-77	J				13.20	1	2/27/	170	Stewa	et 2/2:	2/27		
•	1215-1(12/74)	a Same, wat is you and an owner desired the same and or same along the same and of the same an	,	V	, - 	***************************************	y argensus anj. Laura yasa pand s		*************		· · · · · · · · · · · · · · · · · · ·		** . ****		



1216 212 779

 $-E_2$