^ ,	a de la companya de l	Engineering Order						1		Xerox Corporation El Segundo, Californ. XERO				
S. S	EO 1		Effectivity	ASSY,)	<i>N</i> ,	MENLORY	DATA	INTEC	Drawing	Drawing Number			Chg. Ltr.	
	[9 Havision	[] Immediato	•			•				21631	a	0		
	Reserve	Scriat No./Date		Dist. Code	IDCR	75	805 5-1-							
•	☐ Variation	Next Production	1	ALT	. DCH	1-	CR Date と - スス - フ	Model-N	•	ext Assemb 2163	-	Sheet		
	Affected by Ti	1 71-1						×16.5		01				
•		Yes No	Other Dwgs.	Status Disposition of Existing Pa Return To Stock Rework				Use Scrap Revision			٠.			
	. Spare Parts	0 0	Dwg. No.	Other Dings.		On Order	To Stock	- Nework		ocrap	7107131011 2	1		
	Tooling		•		In Process					Mandatory	i .	•		
	* Test Procedures	ōō		-	****************	in Stock			•	<u> </u>	Prior Revisions	•		
	Test Equipment	<u> </u>		-	······································	In Next Assy.		· · · ·			Trevisions			
•	Programs			-		In Fjeld	<u></u>		,	 	Field info.	only•		
	Tech. Publication	ons 🗌 🗍		-		Refurbishment					Lowest fie	ld		
	Beacon For Char	no (II recent la fin	les France Bellebility describe	Summana & conditions unde				L		<u> </u>	usage leve		<u> </u>	
	Reason For Chango (If reason is Design Error or Reliability, describe symptoms & conditions under which they occur.) ***Design Error CHANGE REED TO INCREASE NOISE MARGIN.													
	Design Error		HANGE PERD TO	INCREASE NO	138 F	othedio.			•				•	
•	Drawing Error				:	•	•		:	• •		•		
	Producibility					٠,		•		· . :				
	☐ Maintainability	,	• •		•			•		'.				
	Reliability													
	Cost Reduction													
	130.LHER	•	4	······································	·									
	Drawing Change				Rowork	Instructions			•		•			
	ML ITEM	7 74	HOO WAS: 74	S132	132 REPLACE MICROCIECUIT 745132									
		·												
	NO ITEM	6 REMAR	KS COLUMN AZILL W	JAS = 434	WITH 74400. 10 PLACES.									
	MUITEM 6 REMARKS COLUMN ALL WAS: A34. MITH 14 HOD. (UPLACES) WITH 14 HOD. (UPLACES) WITH 14 HOD. (UPLACES) WITH 14 HOD. (UPLACES) WITH 14 HOD. (UPLACES)													
	14/ 17514	01. p/. 1	514 - AGIID WAS:	514-AG10D	Ü	ISE SOCI	cet Ph	J 514-	-AGII	DIN	ינואכני	01-		
	1000	20 170 .	516-AGIID WAS:	516- AGIOD	PN 514-AGIOD, TO 55 PL						LACES	•		
	MC LIGHT	. II. PAN			lise carre					100000000000000000000000000000000000000				
	5H 5 600	sic Diagram			30 SOCKET 0/2 510					-AGIOD, 30 PLACES.				
	/ Copposite	版 74400	CALLOUT, WAS, 745	102	7 <i>2</i>			J 516.	-AG10	D, 30	PLAC	·~> !!!!	-	
	•	REMOVED	SYMBOL TI FRO	M ALL		. •		•	1700	T EN TIP	BREE	ជា ស្រាស់ ស្រាស់ ស្រាស់ ស្	. 13	
	·	HYSTER		A GOUZS						70 38			<u>زلاخ</u>	
	•	: Test Procedure to Verify Change								17				
			١.		,		1	u 450 21 2	e en tent b		G			
•												H (3 1 -		
	•	•		•						1 1 1				
	•			·			M NY TOTA HEW YORK IN DI AND. NEW							
	Draftsman	Date Ch	eck Date	Fleid/Mig.	L	Dai	e Proj. Engi		Da	lo DCB	. /	Da	alo	
	2-1-		•				71-		2.60	/////	H	1. 2/201	122	
ار	/Whenser	2-72-77			<u> </u>		1//./	///	721	MUX.	newa	1 700/		
	-			·	A .									