### Laurel Message

From:

Taft.PA

Date: 24 March 1980 5:23 pm PST

(Monday)

Subject:

Bug in 3K CRAM

To:

Orr, Overton, Quarterman, Winfield, Mann, Burns

## **XEROX**

The new batch of 3K CRAM boards have an error on them. There is a jumper wire from A61-5 to A60-8 (p. 3 of fabrication instructions) that should not be there. It causes flakey Ethernet behavior on some machines. I found this error during the last round of debugging, but SPG failed to delete this jumper from the fabrication instructions, so it is likely that any boards you have received to date contain this error.

Ed

ce: Blanchard.WBST DMurray.WBST Taft

# REWORK INSTRUCTION FOR CONTROL MODULE WITH 3K CRAM. (REFER TO FIGURE1)

CUT ETCH TO FEED THROUGH P2-14 (ETCH SIDE) CUT ETCH TO FEED THROUGH P2-12 (ETCH SIDE) CUT ETCH BETWEEN U51-8 AND U51-7 (ETCH) CUT ETCH TO U70-10 (ETCH SIDE)

ADD JUMPER FROM U37-12 TO U37-7 (ETCH) ADD JUMPER FROM U51-7 TO U39-3 (ETCH) ADD JUMPER FROM U68-9 TO FEED THROUGH P2-14 (ETCH SIDE) ADD JUMPER FROM U68-12 TO FEED THROUGH P2-12 (ETCH SIDE) ADD JUMPER FROM U25-11 P3-7 (ETCH SIDE) TO FEED THROUGH ADD JUMPER FROM U25-3 TO FEED THROUGH P3-8 (ETCH SIDE) ADD JUMPER FROM U25-4 TO FEED THROUGH P3-9 (ETCH SIDE) ADD JUMPER FROM U25-6 TO FEED THROUGH P3-10 (ETCH SIDE)

REPLACE U51 WITH SW3K PROM (82S126)




FIGURE 1

#### ISIS<PAE>DRAWINGS>CONTROL-MOD.SIL

These drawings and specifications,and the data contained therein, are the exclusive property of Xerox Corporation and or Rank Xerox,Ltd.	Title	Xerox Corpora El Segundo, C			XEROX
issued in strict confidence and shall not, without the prior written permissIOn of Xerox Corpora- tion Rank Xerox,Ltd., be reproduced, copied or	File	Dwg. No.		-	Rov.
used for any purpose whatsoever, except the manufacture of articles for Xerox Corporation or Rank Xerox, Ltd.	CONTROL-MOD.SIL	Sheet	12	Of	4

		Revisions			
LAL	Rev	Description	Chk	Date	Approved
A	Α	ENGRG REL			
I	В	ENGRG REL		1/24/80	PAE
	С			3/1/80	WAKIDA

ISIS <pae>DRAWINGS&gt;2178120-C.</pae>	SIL	•	•				Dist Co	ode
These drawings and specifications and the data contained therein,		Notes Unless Specified Dra		n		Xerox Corporation  El Segundo, California		XEROX
are the exclusive property of Xerox Corporation and/or Rank		1. Tolerances		k		Li degando, Camornia	<del></del>	
Xerox,Ltd. issued in strict confidence and shall not, without the prior written permission of Xerox Corporation or Rank Xerox,Ltd. be reproduced,copied or used for any purpose whatsoever except e manufacture of articles for erox Corporation or Rank Xerox.		:xx +.03 Angular :xxx +.010 +1/20  2. Break All Sharp Edges .010 Approx  3. Mach. Surfaces  4.All Dim. in Inches				1		
				Material		ASSEMBLY, PRINTED 3K CRAM		) WIRING-
Model No. First Use	Finish	<u> </u>		Code Ident 18338	Size A	Dwg. No. 217812		Change Letter
Next Assy. First Use  File 3		3KCRAM01.SIL		Scale Do Not Scale I		Not Scale Drawing	Sheet	1 OF 16

٠,

,

#### NOTE: UNLESS OTHERWISE SPECIFIED.

- 1. FABRICATE PER XEROX SPEC 209454.
- 2. CUT ETCH PER INSTRUCTIONS.

A. CUT ALL ETCH LEADING TO	A52-11	ONE CUT	(ETCH SIDE)
	A49-11	TWO CUTS	(ETCH SIDE)
	A50-11	TWO CUTS	(ETCH SIDE)
	A62-11	TWO CUTS	(COMP & ETCH)
·	A63-11	TWO CUTS	(COMP & ETCH)
	A65-11	TWO CUTS	(COMP & ETCH)
	A75-11	TWO CUTS	(COMP & ETCH)
	A78-11	TWO CUTS	(ETCH SIDE)
	A88-11	TWO CUTS	(COMP. SIDE)
e e	A91-11	TWO CUTS	(ETCH SIDE)
	A61-15	ONE CUTS	(COMP. SIDE)
CUT ALL ETCH LEADING TO	A25-1	ONE CUT	(ETCH SIDE)

- B. CUT BOTH ETCH TO FEEDTHROW BETWEEN A68-18 AND A69-1 (ETCH,COMP
- C. CUT ETCH TO FEED THROUGH BETWEEN A52-10 AND A53-9 (COMP SIDE)
- D CUT ETCH TO EDGE CONNECTOR FINGER

  J2-13 (ETCH SIDE)
- E. CUT ETCH TO EDGE CONNECTOR FINGER J2-15 (ETCH SIDE) #
- E. COTETON TO EDGE CONNECTOR FINGER J2-15 (ETCH SIDE) #
- F. CUT ETCH TO EDGE CONNECTOR FINGER J2-29 (ETCH SIDE) #
  G. CUT ETCH TO EDGE CONNECTOR FINGER J2-30 (ETCH SIDE) #
- H. CUT ETCH TO A84-1 (COMP SIDE) #

#### 3. ADD JUMPER PER INSTRUCTION

A.	ADD JUMPER FROM	P2-12	TO	A70-9	(ETCH SIDE)	#
В.	ADD JUMPER FROM	P2-13	TO	A90-9	(ETCH SIDE)	#
C	ADD JUMPER FROM	P2-15	TO	A91-9	(ETCH SIDE)	#
D	ADD JUMPER FROM	P2-29	TO	A92-9	(ETCH SIDE)	#
F	ADD JUMPER FROM	P2.30	TO	A93.9	(FTCH SIDE)	#

I nese drawings and specifications, and the data contained therein, are the exclusive property of Xerox Corporation and or Rank Xerox, Ltd. issued in strict confidence and shall not, without the prior written permission of Xerox Corporation Rank Xerox, Ltd., be reproduced, copied or used for any purpose whatsoever, except the manufacture of articles for Xerox Corporation or Rank Xerox, Ltd.

ASSEMBLY, P.W.

3K CRAM

Xerox Corp El Segundo			XE	ROX
2178 <sup>-</sup>	12			FC
Sheet	2	Of	16	

#

#### 4. ADD JUMPER PER INSTRUCTION

- a. A49-11 TO A23-5
  - A62-11 TO A23-3
  - A75-11 TO A23-1
  - A88-11 TO A12-1
  - A50-11 TO A12-3
  - A52-11 TO A23-9
  - A63-11 TO A12-5
  - A65-11 TO A23-11
  - A78-11 TO A23-13
  - A91-11 TO A12-13
  - A21-15 TO A21-8
  - A24-13 TO A25-1
  - A87-15 TO A87-8
  - A66-11 TO A35-7
  - A57-1 TO P1-69
  - A57-2 TO A39-1
  - A57-3 TO A61-15
  - A61-5 TO A60-8
  - A45-4 TO A12-9
  - A12-8 TO FEED THROUGH BETWEEN A52-10 AND A53-9

I nese drawings and specifications, and the data contained therein, are the exclusive property of Xerox Corporation and or Rank Xerox, Ltd. issued in strict confidence and shall not, without the prior written permission of Xerox Corporation Rank Xerox, Ltd., be reproduced, copied or used for any purpose whalsoever, except the manufacture of articles for Xerox Corporation or Rank Xerox, Ltd.

THE

ASSEMBLY, P.W. 3K CRAM

Xerox Corp El Segundo		,	XE	ROX
2178 <sup>-</sup>	12	_		С
Sheet	3	Of	16	3

#### 5.0 DRILL HOLE:

issued in strict confidence and shall not, without

the prior written permissiOn of Xerox Corpora-

tion Rank Xerox, Ltd., be reproduced, copied or


used for any purpose whatsoever, except the manufacture of articles for Xerox Corporation

or Rank Xerox, Ltd.

a. DRILL HOLE PER FIGURE3.

6.0 MOUNT CABLE ASSEMBLY (2533)AND PLATE ASSEMBLY (218054-001) PER FIG. 1 AND FIG.2.

#### 7.0A ADD WIRE (OSERVE FIGURE 4)



**3K CRAM** 

3KCRAM04.SIL

Rev.

16

В

Dwg. No.

217812

4


**A88 THRU 95** 


Xerox Corporation 701 South Aviation Boulevard El Segundo, California 90245


Drawing No. Rev. ML MATERIAL LIST 217812 В Rev. Drawing Title These drawings and specifications, and the data contained therein, are the exclusive property of Xerox Corporation and or Rank Xerox,Ltd. ASSEMBLY, P.W. issued in strict confidence and shall not, without the prior written permissIOn of Xerox Corpora-Dwg. No. 3K CRAM tion Rank Xerox, Ltd., be reproduced, copied or used for any purpose whatsoever, except the manufacture of articles for Xerox Corporation or Rank Xerox, Ltd. Model No. Date Sheet 16 Of 3KCRAM05.SIL Item No. Drawing Title Drawing No. No. Req. Remarks 1 Board, P.W. 217813 1 Ref 2 Procedure, Test 216207 Ref 3 Spec, Assembly ML 4 5 Microcircuit 74H00 2 A2, 46 6 74S00 2 A13, 57 7 **74S04** 6 A1, 11, 12, 23, 45, 58 8 **74S08** 1 A40 9 **74S10** 1 10 74S03 4 A36, 42, 43, 44 11 74H20 1 A24 12 74H21 1 A27 13 **74S30** 2 A26, 28 74S32 1 14 A70 15 **74S38** 4 A3, 4, 5, 6 7438 4 A7, 8, 9, 10 16 74S138 1 17 A38 74S153 1 18 A59 19 74S157 8 A18,19,20,21,48,61,74,87 2 20 74166 A72, 85 5 21 **74S174** A22, 29, 34, 35, 39 7 22 74S175 A25,41,47,60,71,73,86 23 74S189 1 74298 4 24 A30, 31, 32, 33 F93422 FAIRCHILD 4 25 A14, 15, 16, 17 82S126 1 A37 26 27 Microcircuit 2147-3 INTEL 32 A49 THRU 56 A62 THRU 69 A75 THRU 82


Xerox Corporation
701 South Aviation Boulevard
El Segundo, California
90245


Drawing No. Rev. MLMATERIAL LIST 217812 В Rev. Drawing Title These drawings and specifications, and the data contained therein, are the exclusive property of Xerox Corporation and or Rank Xerox,Ltd. ASSEMBLY, P.W. -Dwg. issued in strict confidence and shall not, without No. the prior written permissIOn of Xerox Corpora-3K CRAM tion Rank Xerox, Ltd., be reproduced, copied or used for any purpose whatsoever, except the manufacture of articles for Xerox Corporation or Rank Xerox, Ltd Date Sheet Model No 16 3KCRAM06.SIL Of Drawing No Item No. Drawing Title No. Req Remarks 28 Socket, 14 pin Augat 514-AG11D 31 29 Socket, 16 pin Augat 516-AG11D 28 Socket, 18 pin Augat 518-AG11D 30 32 ML 31 Socket, 22 pin Augat 522-AG19D 4 32 33 Capacitor, 22uf 20% 15V 187720-005 2 C1,C2 34 Capacitor, .047uf AVX DG0150473M C4 THRU C50 47 35 Capacitor, 180pf 1 СЗ 36 Resistor, Film, 1K ohm 5% 1/4W 4 R2, R3, R7, R8 37 Resistor, Film, 2.7K ohm 5%, 1/4W 1 38 Resistor, Film, 330 ohm 5%, 1/4W 5 R4, R5, R6, R9 .R10 Resistor, SIP, 330 ohm (CTS 750-61-R330) 6 39 A96 TRU 101 Stiffener 40 216242 1 41 216250 2 extractor 42 rivet 156111-005 2 ASSY, CABLE 3KCRAM/CONT INTERFACE 218055 43 1 44 PLATE ASSEMBLY 218054-001 1 PLATE ASSEMBLY 1 218054-002 45 46 47 48 · 49 50




























XEROX	Project		File	Designer	Rev	Date	Page
ED	3K CRAM	S REGISTER CONTROL	3KCRAM15.SIL	ALBERT PAE	В	2/17/79	14
L			THE RESIDENCE OF THE PROPERTY OF	L	-	CONTRACTOR OF THE PROPERTY OF	nas communicario di mari cumpi. All





XEROX	Project		File	Designer	Rev	Date	Page
ED	3K CRAM	RESET MODE REGISTER	3KCRAM17.SIL	ALBERT PAE	В	2/17/79	16
					MONTH ALLEMAN	AND HE HEND WHEN THE RESERVE AND THE PARTY AND ALL ALL	