# **Project Demonstrations**

Below are the sample screenshots of the GUI software which I developed.


# (1D) TCAD Software Demo




1. Tab of epitaxial layers setting




2. Tab of Schrodinger solver setting



#### 3. Tab of laser cavity simulation




#### 4. Result visualizer for 1D simulations




# (2D) TCAD Software Demo


1. Tab of region setting (geometric definitions)




2. Setting dialogs




#### 3. Tab of material setting (material parameters)




### 4. Tab of mesh setting (automatically generating mesh)



### 5. Tab of Schrodinger solver




#### 6. Result visualizer




# (3D) TCAD Software Demo


1. Tab of (gmsh) region setting and demonstration



## 2. Tab of setting strain solver



### 3. Tab of setting FDTD simulation



## 4. Integrated result visualizer for 3D

