CHAPTER 35

OXYGEN

CHAPTER 35
OXYGEN

CH-SE-SU	Schem	Page	Sheet	Date
35-EFFECTIVE PAGES				
		1		Nov 14/2025
		2		BLANK
35-CONTENTS				
		1		May 15/2024
		2		BLANK
35-ALPHABETICAL INDEX				
		1		May 15/2024
		2		BLANK
35-11-11				
		1		May 15/2024
35-21-11				
		1		May 15/2024
35-21-21				
		1		May 15/2024
35-21-31				
		1		May 15/2024
35-21-41				
		1		May 15/2024

A = Added, R = Revised, D = Deleted, O = Overflow

ECCN 9E991 BOEING PROPRIETARY - See title page for details

CHAPTER 35
OXYGEN

Title	CH-SE-SU	Schem	Page	Sheet	Date	Effectivity
CREW OXYGEN SYSTEM						
CREW OXYGEN SYSTEM	35-11-11		1		May 15/2024	ALL
PASSENGER OXYGEN SYSTEM						
PASS OXYGEN CONTROL	35-21-11		1		May 15/2024	ALL
PASS OXYGEN - LEFT	35-21-21		1		May 15/2024	ALL
PASS OXYGEN - RIGHT	35-21-31		1		May 15/2024	ALL
OXYGEN DROP - PASS SERVICE UNIT	35-21-41		1		May 15/2024	ALL

ECCN 9E991 BOEING PROPRIETARY - See title page for details

CHAPTER 35
OXYGEN


CH-SE-SU	Title
35-11-11	CREW OXYGEN SYSTEM
35-21-41	OXYGEN DROP - PASS SERVICE UNIT
35-21-21	PASS OXYGEN - LEFT
35-21-31	PASS OXYGEN - RIGHT
35-21-11	PASS OXYGEN CONTROL

35-ALPHABETICAL INDEX

ECCN 9E991 BOEING PROPRIETARY - See title page for details

737-8 WIRING DIAGRAM MANUAL

-A
30



ECCN 9E991 BOEING PROPRIETARY - See title page for details


35-11-11

Page 1

May 15/2024

737-8 WIRING DIAGRAM MANUAL

-H
99



35-21-11


Page 1

May 15/2024

ECCN 9E991 BOEING PROPRIETARY - See title page for details

737-8 WIRING DIAGRAM MANUAL

-B
66



NOTES:

FOR WIRE BUNDLE W3150, WIRE NUMBERS ON COLOR CODED WIRES ARE FOR ENGINEERING REFERENCE ONLY. CODING IS OPTIONAL ON COLORED WIRES FOR THIS BUNDLE ONLY.

1 MATES WITH PASSENGER SERVICE UNIT AS REQUIRED. (SEE 35-21-41)

ECCN 9E991 BOEING PROPRIETARY - See title page for details

35-21-21


Page 1

May 15/2024

737-8 WIRING DIAGRAM MANUAL

-A

54



35-21-31


Page 1

May 15/2024


ECCN 9E991 BOEING PROPRIETARY - See title page for details

737-8 WIRING DIAGRAM MANUAL

8



M2812 (YBA) RIGHT PSU MODULE WITH SPEAKER (MULTIPLE LOCATIONS)



M2884 (YBD) LEFT PSU MODULE WITH SPEAKER (MULTIPLE LOCATIONS)

NOTES:

1 FUSE IS REPLACEABLE

ECCN 9E991 BOEING PROPRIETARY - See title page for details

35-21-41

Page 1

May 15/2024