FLEET TEAM DIGEST

737MAX-FTD-00-23001

Issue Title : Interchangeability - Removable Structural Components_737MAX

Airplane Model	ATA	Minor Model(s)
737MAX	0000-64	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
08/11/2023	12/19/2025	12/04/2024

Estimated Completion Date	Next Update Date
12/30/2027	12/31/2026

Revision Description

-Updated Milestones to record completion of Sixth RSC WTT

-Added 2025 Backlog and Priority Exercise spreadsheet as an Attachment

Description

Boeing is not able to provide installation approval for Removable Structural Components (RSCs) outside Type Design without the appropriate Engineering Drawings or Service Bulletins that capture the configuration.

A Removable Structural Component (RSC) is a structural component that is not permanently attached to the airplane. Since these parts can be rotated between airplanes, repairs and maintenance records must be tracked for each component to ensure utilization-based regulatory requirements are fulfilled at the correct times.

Rotable parts, including RSCs, are those that can be rotated to locations or airplanes outside of the original installation location. When a rotable part is installed in an airplane or at a location that is not within Boeings approved type design configuration, it is not traceable within Boeings documentation. The unique installation configuration may not be included in a Boeing issued airplane series bulletin to address a safety issue.

Type design is a fixed set of drawings and specifications that defines the configuration and design features of the airplane. Installing a rotable part that is not authorized in the Boeing type design is essentially a design change (also referred to as an alternation) that must be certificated. Boeing type design changes must be done in accordance with the FAA approved Organization Designation Authorization (ODA) procedures manual and documented in engineering data.

Status

Boeing has established a Customer Support Interchangeability Drawing (CSID) Team to expand Interchangeability relationships in the Boeing Design Data for existing RSCs.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

See attachment CSID_Backlog_&_Priority_4Q2025.xlsx for status and latest drawing releases.

Interim Action

Boeing is offering No Technical Objection (NTO) for Technical Concurrence for interchangeability outside of type design on a case-by-case basis per airplane to assist operators in obtaining approval from their regulatory agency. Multi-Model Service Letter 737-SL-00-022-H contains the definition of Boeing's NTO statement.

This FTD will be used for Boeing communications on Interchangeability Drawing Releases completed by the CSID Team.

Final Action

CSID Team will continue working the Backlog of Interchangeability Request to completion.

Milestones

17-Oct-2022: Initial team information was shared at the Structures Task Group (STG)

15-Mar-2023: Pathfinder drawing released

22-Mar-2023: Removeable Structural Component Working Together Team (RSC WTT) with Interchangeability Prioritization Exercise

29-Jun-2023: Second RSC WTT with Interchangeability Prioritization Exercise. Open invitation all Airlines.

17-Oct-2023: Third RSC WTT at the Structures Task Group (STG) General Session with Interchangeability Prioritization Exercise

13-Mar-2024: Fourth RSC WTT.

05-Nov-2024: Fifth RSC WTT at the Structures Task Group (STG) General Session

16-Oct-2025: Sixth RSC WTT at the Structures Task Group (STG) General Session.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-00-022-H		
Service Letter (SL)	737-SL-05-021		

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

Attachments:

a) CSID_Backlog_&_Priority_4Q2025.xlsx

b) SR Interchangeability Drawing Request Form

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991