FLEET TEAM DIGEST

737MAX-FTD-02-21001

Issue Title : EASA Required Navigation Performance – Authorization Required (RNP AR) Limitation for 737 MAX Airplanes

Airplane Model	ATA	Minor Model(s)
737MAX	0220-34	-8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/11/2021	09/04/2026	04/28/2026
Estimated Completion Date	**Next Update Date**	
10/30/2026	09/30/2026	

Revision Description

Updated the following section(s):

- Milestones.

Description

During 737 MAX-related engagements with regulators, the European Aviation Safety Agency (EASA) expressed concern with how compliance was previously approved for Acceptable Means of Compliance (AMC) 20-26. The specific concern stemmed from discussions regarding EASA pilot demonstrations for AMC 20-26. Consequently, as a requirement of the 737 MAX Return to Service, EASA has implemented a limitation in the 737 MAX Airplane Flight Manual (AFM) that inhibits Required Navigation Performance - Authorization Required (RNP AR) operations in the European Union (EU) airspace. This limitation applies to EASA-regulated airplanes, as well as all 737 MAX airplanes operating in EU airspace.

Non-EASA regulated 737 MAX airplanes operating outside of EU airspace are not impacted by this limitation, which inhibits RNP AR operations. This limitation is not included in the 737 MAX Federal Aviation Administration (FAA) AFM. Additionally, this limitation only applies to the EASA 737 MAX airplanes and not EASA 737NG airplanes.

Status

In the interim, EASA is only approving AFMs for the 737 MAX that have an RNP AR limitation to prohibit all RNP AR operations. The RNP AR operational limitation will be lifted once EASA approves the 737 MAX for RNP AR, which will allow local regulatory authorities to authorize RNP AR operations.

Interim Action

The EASA limitation, which is only applicable to EASA-regulated 737 MAX airplanes and 737 MAX airplanes operating within the EU airspace, impacts only RNP AR operations. RNP Approach (Non AR) and all other non approach RNP operations are not

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

impacted as noted in the applicable AFM. As such, Boeing recommends that impacted operators review their AFM to ensure flight crews are aware of the RNP AR limitation and appropriate action is taken to ensure compliance is maintained with this EASA-specific restriction.

Final Action

Once the EASA re-certification of RNP AR occurs, individual regulatory agencies will be able to authorize RNP AR operations. At that time, the limitation will also be removed from the AFM.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

737 MAX - EASA RNP AR Recertification Simulation Validation - Demonstration | Jul 2023 (Complete)

737 MAX - EASA RNP AR Recertification Simulation Validation - Demonstration 2 | May 2025 (Complete)

737 MAX - EASA RNP AR Limitation Lift - Certification | Q3-2026 (Target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Multi-Operator Message (MOM)	MOM-MOM-21-0015		

Related Categories

- Flight Operations : Flight Operations
- Regulatory : Issues mandated by airworthiness directive or other regulatory guidance material

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991